

Borough of North Arlington

Quality of Life Report

Date: Week of June 7th 2020

Completed 6/16/20 coupe, Aluotto

Location: Belleville Pike & Morgan Pl


- Curb
- Fence
- Roadway
- Tree
- Lamp
- Playground
- Sidewalk
- Streetlamp
- Park
- School
- Sign
- Other: _____

Replace sign Mon 8AM - 10AM

Needing Attention:

- Damage
- Painting
- Pothole
- Grass
- Missing
- Needs Trimming

Submitted by: James Baschiro



Borough of North Arlington

Quality of Life Report

Date: Week of June 1st 2020

Completed 6/16/20 coupe, Aluotto

Location: Little League field on River Road


- | | | |
|----------------------------------|-------------------------------------|---------------------------------------|
| <input type="checkbox"/> Curb | <input type="checkbox"/> Lamp | <input type="checkbox"/> Park |
| <input type="checkbox"/> Fence | <input type="checkbox"/> Playground | <input type="checkbox"/> School |
| <input type="checkbox"/> Roadway | <input type="checkbox"/> Sidewalk | <input type="checkbox"/> Sign |
| <input type="checkbox"/> Tree | <input type="checkbox"/> Streetlamp | <input type="checkbox"/> Other: _____ |

Replace sign "do not enter" faded

Needing Attention:

- | | | |
|-----------------------------------|----------------------------------|---|
| <input type="checkbox"/> Damage | <input type="checkbox"/> Pothole | <input type="checkbox"/> Missing |
| <input type="checkbox"/> Painting | <input type="checkbox"/> Grass | <input type="checkbox"/> Needs Trimming |

Submitted by: James Boecklin



Borough of North Arlington

Quality of Life Report

Date: Week of June 7th 2020

completed 6/16/20 coupe, Aluotto

Location: 95 Quincey Ave

Curb

Lamp

Park

Fence

Playground

School

Roadway

Sidewalk

Sign

Tree

Streetlamp

Other: _____

Replace Sign

Needing Attention:

Damage

Pothole

Missing

Painting

Grass

Needs Trimming

Submitted by: James Baschiro



Borough of North Arlington

Quality of Life Report

Date: Week of June 1st

completed 6/10/20 coupe, Gino

Location: 18 Pershing Pl.

Curb

Lamp

Park

Fence

Playground

School

Roadway

Sidewalk

Sign

Tree

Streetlamp

Other: _____

Sign on Pole & replace sign to Park 8-10 AM

Needing Attention:

Damage

Pothole


Missing

Painting

Grass

Needs Trimming

Submitted by: James Boecklin



Borough of North Arlington

Quality of Life Report

Date: Week of June 1st

completed 6/10/20 coupe, Gino

HIDDEN TER

Location: Herdell & Fairmont

Curb

Lamp

Park

Fence

Playground

School

Roadway

Sidewalk

Sign

Tree

Streetlamp

Other: _____

Replace sign 8 to 10 Tues on Fairmont

Needing Attention:

Damage

Pothole


Missing

Painting

Grass

Needs Trimming

Submitted by: James Boeckhino



Borough of North Arlington

Quality of Life Report

Date: Week of June 1st

completed 6/10/20 coupe, Gino

Location: Crystal St & High St


- | | | |
|----------------------------------|-------------------------------------|--|
| <input type="checkbox"/> Curb | <input type="checkbox"/> Lamp | <input type="checkbox"/> Park |
| <input type="checkbox"/> Fence | <input type="checkbox"/> Playground | <input type="checkbox"/> School |
| <input type="checkbox"/> Roadway | <input type="checkbox"/> Sidewalk | <input checked="" type="checkbox"/> Sign |
| <input type="checkbox"/> Tree | <input type="checkbox"/> Streetlamp | <input type="checkbox"/> Other: _____ |

Sign is best on High St

Needing Attention:

- | | | |
|-----------------------------------|----------------------------------|---|
| <input type="checkbox"/> Damage | <input type="checkbox"/> Pothole | <input type="checkbox"/> Missing |
| <input type="checkbox"/> Painting | <input type="checkbox"/> Grass | <input type="checkbox"/> Needs Trimming |

Submitted by: James Baschiro



Borough of North Arlington

Quality of Life Report

Date: Week of May 26th

Removed coupe, Alutto 6/4/20

Location: 36 Bergen Ave

Curb

Lamp

Park

Fence

Playground

School

Roadway

Sidewalk

Sign

Tree

Streetlamp

Other: _____

Sign on Pole

Needing Attention:

Damage

Pothole


Missing

Painting

Grass

Needs Trimming

Submitted by: James Baschimo



Borough of North Arlington

Quality of Life Report

Date: Week of 26th May

CANNOT Remove At this time coupe, Alutts
6/4/20

Location: 38 & 32 Union Place

Curb

Lamp

Park

Fence

Playground

School

Roadway

Sidewalk

Sign

Tree

Streetlamp

Other: _____

Sign on Poles remove

Needing Attention:

Damage

Pothole


Missing

Painting

Grass

Needs Trimming

Submitted by: James Boeckeno



Borough of North Arlington

Quality of Life Report

Date: Week of May 26th

REPLACED coupe, Alutto 614120

Location: 225 Galed St

Curb

Lamp

Park

Fence

Playground

School

Roadway

Sidewalk

Sign

Tree

Streetlamp

Other: _____

Replace sign faded

Needing Attention:

Damage

Pothole


Missing

Painting

Grass

Needs Trimming

Submitted by: James Baschino



Borough of North Arlington

Quality of Life Report

Date: Week of 5-17

REPLACED COUPE, HOYT 5128120

Location: Larigan Pl + Eagle

Curb

Lamp

Park

Fence

Playground

School

Roadway

Sidewalk

Sign

Tree

Streetlamp

Other: _____

Replace sign (one way) faded

Needing Attention:

Damage

Pothole


Missing

Painting

Grass

Needs Trimming

Submitted by: James Boecklin



Borough of North Arlington

Quality of Life Report

Date: Week of 5-17

AREA HAS concrete only (NO PLACE FOR PROPER INSTALL OF
stop sign
MKC


Location: Larayan & Teest

- | | | |
|----------------------------------|-------------------------------------|--|
| <input type="checkbox"/> Curb | <input type="checkbox"/> Lamp | <input type="checkbox"/> Park |
| <input type="checkbox"/> Fence | <input type="checkbox"/> Playground | <input type="checkbox"/> School |
| <input type="checkbox"/> Roadway | <input type="checkbox"/> Sidewalk | <input checked="" type="checkbox"/> Sign |
| <input type="checkbox"/> Tree | <input type="checkbox"/> Streetlamp | <input type="checkbox"/> Other: _____ |

Sign on pole Personal
Needing Attention:

- | | | |
|-----------------------------------|----------------------------------|---|
| <input type="checkbox"/> Damage | <input type="checkbox"/> Pothole | <input type="checkbox"/> Missing |
| <input type="checkbox"/> Painting | <input type="checkbox"/> Grass | <input type="checkbox"/> Needs Trimming |

Submitted by: James Baschino



Borough of North Arlington

Quality of Life Report

Week of

Date: 5-17-2020

REPLACED coupe, Hoyt 5/28/20

Location: 44 Trent St.

Curb

Lamp

Park

Fence

Playground

School

Roadway

Sidewalk

Sign

Tree

Streetlamp

Other: _____

replace sign (no parking this side)

Needing Attention:

Damage

Pothole


Missing

Painting

Grass

Needs Trimming

Submitted by: James Basolino



Borough of North Arlington

Quality of Life Report

Date: week of May 11th

REPLACED 5/20/20

Location: 13 Park Ave

Curb

Lamp

Park

Fence

Playground

School

Roadway

Sidewalk

Sign

Tree

Streetlamp

Other: _____

Replace Sign 10 to 12 noon Tues no Parking

Needing Attention:

Damage

Pothole


Missing

Painting

Grass

Needs Trimming

Submitted by: James Baschimo



Borough of North Arlington

Quality of Life Report

Date: Week of May 11th

completed 5/20/20

Location: 65 Park Ave

Curb

Lamp

Park

Fence

Playground

School

Roadway

Sidewalk

Sign

Tree

Streetlamp

Other: _____

Sign is Pale

Needing Attention:

Damage

Pothole


Missing

Painting

Grass

Needs Trimming

Submitted by: James Baschiro



Borough of North Arlington
Quality of Life Report

Date: 4-16-2020

Completed Black top crew 5/19/20

Location: 12 & 16 Bayle ave


- | | | |
|---|-------------------------------------|---------------------------------------|
| <input type="checkbox"/> Curb | <input type="checkbox"/> Lamp | <input type="checkbox"/> Park |
| <input type="checkbox"/> Fence | <input type="checkbox"/> Playground | <input type="checkbox"/> School |
| <input checked="" type="checkbox"/> Roadway | <input type="checkbox"/> Sidewalk | <input type="checkbox"/> Sign |
| <input type="checkbox"/> Tree | <input type="checkbox"/> Streetlamp | <input type="checkbox"/> Other: _____ |

Potholes by driveway

Needing Attention:

- | | | |
|-----------------------------------|----------------------------------|---|
| <input type="checkbox"/> Damage | <input type="checkbox"/> Pothole | <input type="checkbox"/> Missing |
| <input type="checkbox"/> Painting | <input type="checkbox"/> Grass | <input type="checkbox"/> Needs Trimming |

Submitted by: James Boecklin



Borough of North Arlington

Quality of Life Report

Date: 4-16-2020

Completed Black top crew 5/19/20

Location: 14 & 22 Sage Ave

Curb

Lamp

Park

Fence

Playground

School

Roadway

Sidewalk

Sign

Tree

Streetlamp

Other: _____

Potholes by Curb

Needing Attention:

Damage

Pothole


Missing

Painting

Grass

Needs Trimming

Submitted by: James Basolino



Borough of North Arlington
Quality of Life Report

Date: 1-28-2020

completed Black top crew 5119120

Location: 74 Herdel Ave


- | | | |
|---|-------------------------------------|---------------------------------------|
| <input type="checkbox"/> Curb | <input type="checkbox"/> Lamp | <input type="checkbox"/> Park |
| <input type="checkbox"/> Fence | <input type="checkbox"/> Playground | <input type="checkbox"/> School |
| <input checked="" type="checkbox"/> Roadway | <input type="checkbox"/> Sidewalk | <input type="checkbox"/> Sign |
| <input type="checkbox"/> Tree | <input type="checkbox"/> Streetlamp | <input type="checkbox"/> Other: _____ |

Pothole

Needing Attention:

- | | | |
|-----------------------------------|----------------------------------|---|
| <input type="checkbox"/> Damage | <input type="checkbox"/> Pothole | <input type="checkbox"/> Missing |
| <input type="checkbox"/> Painting | <input type="checkbox"/> Grass | <input type="checkbox"/> Needs Trimming |

Submitted by: James Bochenko



Borough of North Arlington
Quality of Life Report

Date: 1-2-2020

P.V. W. C. Notified trench

Location: 176 Canterbury Ave


- | | | |
|---|-------------------------------------|---------------------------------------|
| <input type="checkbox"/> Curb | <input type="checkbox"/> Lamp | <input type="checkbox"/> Park |
| <input type="checkbox"/> Fence | <input type="checkbox"/> Playground | <input type="checkbox"/> School |
| <input checked="" type="checkbox"/> Roadway | <input type="checkbox"/> Sidewalk | <input type="checkbox"/> Sign |
| <input type="checkbox"/> Tree | <input type="checkbox"/> Streetlamp | <input type="checkbox"/> Other: _____ |

Repair road going East

Needing Attention:

- | | | |
|-----------------------------------|----------------------------------|---|
| <input type="checkbox"/> Damage | <input type="checkbox"/> Pothole | <input type="checkbox"/> Missing |
| <input type="checkbox"/> Painting | <input type="checkbox"/> Grass | <input type="checkbox"/> Needs Trimming |

Submitted by: James Bauhinis



Borough of North Arlington
Quality of Life Report

Date: 12-26-2019

P.S.E.G. Notifiaed Failing trench

Location: Hoover St & Canterbury Ave


- | | | |
|---|-------------------------------------|---------------------------------------|
| <input type="checkbox"/> Curb | <input type="checkbox"/> Lamp | <input type="checkbox"/> Park |
| <input type="checkbox"/> Fence | <input type="checkbox"/> Playground | <input type="checkbox"/> School |
| <input checked="" type="checkbox"/> Roadway | <input type="checkbox"/> Sidewalk | <input type="checkbox"/> Sign |
| <input type="checkbox"/> Tree | <input type="checkbox"/> Streetlamp | <input type="checkbox"/> Other: _____ |

Dip in road on Canterbury

Needing Attention:

- | | | |
|-----------------------------------|----------------------------------|---|
| <input type="checkbox"/> Damage | <input type="checkbox"/> Pothole | <input type="checkbox"/> Missing |
| <input type="checkbox"/> Painting | <input type="checkbox"/> Grass | <input type="checkbox"/> Needs Trimming |

Submitted by: James Bochneris



Borough of North Arlington
Quality of Life Report

Date: 1-29-2020

Repeat Request MKC

Location: Alford Ave & Ridge by Church


- | | | |
|---|-------------------------------------|---------------------------------------|
| <input type="checkbox"/> Curb | <input type="checkbox"/> Lamp | <input type="checkbox"/> Park |
| <input type="checkbox"/> Fence | <input type="checkbox"/> Playground | <input type="checkbox"/> School |
| <input checked="" type="checkbox"/> Roadway | <input type="checkbox"/> Sidewalk | <input type="checkbox"/> Sign |
| <input type="checkbox"/> Tree | <input type="checkbox"/> Streetlamp | <input type="checkbox"/> Other: _____ |

Pothole

Needing Attention:

- | | | |
|-----------------------------------|----------------------------------|---|
| <input type="checkbox"/> Damage | <input type="checkbox"/> Pothole | <input type="checkbox"/> Missing |
| <input type="checkbox"/> Painting | <input type="checkbox"/> Grass | <input type="checkbox"/> Needs Trimming |

Submitted by: James Bochner



Borough of North Arlington

Quality of Life Report

Date: 3-9-2020

REPAIRED DPW 3124120

Location: Bridge Road & Seferd


- | | | |
|----------------------------------|-------------------------------------|---------------------------------------|
| <input type="checkbox"/> Curb | <input type="checkbox"/> Lamp | <input type="checkbox"/> Park |
| <input type="checkbox"/> Fence | <input type="checkbox"/> Playground | <input type="checkbox"/> School |
| <input type="checkbox"/> Roadway | <input type="checkbox"/> Sidewalk | <input type="checkbox"/> Sign |
| <input type="checkbox"/> Tree | <input type="checkbox"/> Streetlamp | <input type="checkbox"/> Other: _____ |

Needing Attention:

- | | | |
|-----------------------------------|---|---|
| <input type="checkbox"/> Damage | <input checked="" type="checkbox"/> Pothole | <input type="checkbox"/> Missing |
| <input type="checkbox"/> Painting | <input type="checkbox"/> Grass | <input type="checkbox"/> Needs Trimming |

3 Pot Holes

Submitted by: James Basolino



Borough of North Arlington
Quality of Life Report

Date: 7-12-2020

P.V.W.C. Repair completed 3/24/20

Location: 176 Stover


- | | | |
|----------------------------------|-------------------------------------|---------------------------------------|
| <input type="checkbox"/> Curb | <input type="checkbox"/> Lamp | <input type="checkbox"/> Park |
| <input type="checkbox"/> Fence | <input type="checkbox"/> Playground | <input type="checkbox"/> School |
| <input type="checkbox"/> Roadway | <input type="checkbox"/> Sidewalk | <input type="checkbox"/> Sign |
| <input type="checkbox"/> Tree | <input type="checkbox"/> Streetlamp | <input type="checkbox"/> Other: _____ |

Needing Attention:

- | | | |
|-----------------------------------|---|---|
| <input type="checkbox"/> Damage | <input checked="" type="checkbox"/> Pothole | <input type="checkbox"/> Missing |
| <input type="checkbox"/> Painting | <input type="checkbox"/> Grass | <input type="checkbox"/> Needs Trimming |

Fix Pothole

Submitted by: James Bocchino



Borough of North Arlington

Quality of Life Report

Date: 7-25-2020

With address when street turned into a "one way"

Alvotto, coupe
3117120

Location: Jasen Way & Schuyler


- | | | |
|----------------------------------|-------------------------------------|--|
| <input type="checkbox"/> Curb | <input type="checkbox"/> Lamp | <input type="checkbox"/> Park |
| <input type="checkbox"/> Fence | <input type="checkbox"/> Playground | <input type="checkbox"/> School |
| <input type="checkbox"/> Roadway | <input type="checkbox"/> Sidewalk | <input checked="" type="checkbox"/> Sign |
| <input type="checkbox"/> Tree | <input type="checkbox"/> Streetlamp | <input type="checkbox"/> Other: _____ |

Replace signs faded Stop signs

Needing Attention:

- | | | |
|-----------------------------------|----------------------------------|---|
| <input type="checkbox"/> Damage | <input type="checkbox"/> Pothole | <input type="checkbox"/> Missing |
| <input type="checkbox"/> Painting | <input type="checkbox"/> Grass | <input type="checkbox"/> Needs Trimming |

Submitted by: James Boeckeno



Borough of North Arlington

Quality of Life Report

Date: 3-11-2020

Removero 3/17/20 Aluotto, coupe

Location: 9 Locust


- | | | |
|----------------------------------|-------------------------------------|--|
| <input type="checkbox"/> Curb | <input type="checkbox"/> Lamp | <input type="checkbox"/> Park |
| <input type="checkbox"/> Fence | <input type="checkbox"/> Playground | <input type="checkbox"/> School |
| <input type="checkbox"/> Roadway | <input type="checkbox"/> Sidewalk | <input checked="" type="checkbox"/> Sign |
| <input type="checkbox"/> Tree | <input type="checkbox"/> Streetlamp | <input type="checkbox"/> Other: _____ |

Signs on Pole (Take off)

Needing Attention:

- | | | |
|-----------------------------------|----------------------------------|---|
| <input type="checkbox"/> Damage | <input type="checkbox"/> Pothole | <input type="checkbox"/> Missing |
| <input type="checkbox"/> Painting | <input type="checkbox"/> Grass | <input type="checkbox"/> Needs Trimming |

Submitted by: James Boechino



Borough of North Arlington

Quality of Life Report

Date: 3-10-2020

REMOVED WILL BE REFACED: ALUOTTO COUPE 3117120

Location: Albert St & Sixth


- | | | |
|----------------------------------|-------------------------------------|--|
| <input type="checkbox"/> Curb | <input type="checkbox"/> Lamp | <input type="checkbox"/> Park |
| <input type="checkbox"/> Fence | <input type="checkbox"/> Playground | <input type="checkbox"/> School |
| <input type="checkbox"/> Roadway | <input type="checkbox"/> Sidewalk | <input checked="" type="checkbox"/> Sign |
| <input type="checkbox"/> Tree | <input type="checkbox"/> Streetlamp | <input type="checkbox"/> Other: _____ |

Replace sign (do not enter one way)

Needing Attention:

- | | | |
|-----------------------------------|----------------------------------|---|
| <input type="checkbox"/> Damage | <input type="checkbox"/> Pothole | <input type="checkbox"/> Missing |
| <input type="checkbox"/> Painting | <input type="checkbox"/> Grass | <input type="checkbox"/> Needs Trimming |

Submitted by: James Boecklin



Needs attention before growth

Borough of North Arlington

Quality of Life Report

Date: 3-9-2020

ADDRESSED BEFORE WRITE UP
MKC 3116120

(Total clean up)

Location: Allan Park

Curb

Lamp

Park

Fence

Playground

School

Roadway

Sidewalk

Sign

Tree

Streetlamp

Other: _____

Needs good clean up branches all over

Needing Attention:

Damage

Pothole

Missing

Painting


Grass

Needs Trimming

Tree growing in fence by entrance off Stratford Pl.

Submitted by: James Boechino

Cut Pine tree by entrance on Stratford Place.



Borough of North Arlington

Quality of Life Report

Date: 3-5-2020

completed ALuotto, coupe 3/12/20

Location: Crystal St & River Road

Curb

Lamp

Park

Fence

Playground

School

Roadway

Sidewalk

Sign

Tree

Streetlamp

Other: _____

Replace Sign (no Parking this side)

Needing Attention:

Damage

Pothole


Missing

Painting

Grass

Needs Trimming

Submitted by: James Boeckeno



Borough of North Arlington

Quality of Life Report

Date: 3-4-2020

Removed completed Aluotto, coupe 3/12/20

Location: Aster Ave & Ridge Rd


- | | | |
|----------------------------------|-------------------------------------|--|
| <input type="checkbox"/> Curb | <input type="checkbox"/> Lamp | <input type="checkbox"/> Park |
| <input type="checkbox"/> Fence | <input type="checkbox"/> Playground | <input type="checkbox"/> School |
| <input type="checkbox"/> Roadway | <input type="checkbox"/> Sidewalk | <input checked="" type="checkbox"/> Sign |
| <input type="checkbox"/> Tree | <input type="checkbox"/> Streetlamp | <input type="checkbox"/> Other: _____ |

Chart Read Sign Wed 1 to 3 PM

Needing Attention:

- | | | |
|-----------------------------------|----------------------------------|---|
| <input type="checkbox"/> Damage | <input type="checkbox"/> Pothole | <input type="checkbox"/> Missing |
| <input type="checkbox"/> Painting | <input type="checkbox"/> Grass | <input type="checkbox"/> Needs Trimming |

Submitted by: James Baschino



Borough of North Arlington

Quality of Life Report

Date: 3-4-2020

completed Aluotto, coupe 3/12/20


Location: H Astor Ave

- Curb
- Fence
- Roadway
- Tree
- Lamp
- Playground
- Sidewalk
- Streetlamp
- Park
- School
- Sign
- Other: _____

No Parking 1 PM to 3 PM Wed - replace
Needing Attention:

- Damage
- Painting
- Pothole
- Grass
- Missing
- Needs Trimming

Submitted by: James Boeckeno



Borough of North Arlington

Quality of Life Report

Date: 3-2-2020

Sign put onto a U-channel Post coupe, Hoyt, Reilly

Location: 325 Page St


- | | | |
|----------------------------------|-------------------------------------|--|
| <input type="checkbox"/> Curb | <input type="checkbox"/> Lamp | <input type="checkbox"/> Park |
| <input type="checkbox"/> Fence | <input type="checkbox"/> Playground | <input type="checkbox"/> School |
| <input type="checkbox"/> Roadway | <input type="checkbox"/> Sidewalk | <input checked="" type="checkbox"/> Sign |
| <input type="checkbox"/> Tree | <input type="checkbox"/> Streetlamp | <input type="checkbox"/> Other: _____ |

Sign on Pole

Needing Attention:

- | | | |
|-----------------------------------|----------------------------------|---|
| <input type="checkbox"/> Damage | <input type="checkbox"/> Pothole | <input type="checkbox"/> Missing |
| <input type="checkbox"/> Painting | <input type="checkbox"/> Grass | <input type="checkbox"/> Needs Trimming |

Submitted by: James Bochenko



Borough of North Arlington

Quality of Life Report

coups, Re:lh7, Hoyt 3/10/20

Date: 3-3-2020

SIGN STAYS BECAUSE ALL CONCRETE IN AREA

Location: R 71 Crystal St


- | | | |
|----------------------------------|-------------------------------------|--|
| <input type="checkbox"/> Curb | <input type="checkbox"/> Lamp | <input type="checkbox"/> Park |
| <input type="checkbox"/> Fence | <input type="checkbox"/> Playground | <input type="checkbox"/> School |
| <input type="checkbox"/> Roadway | <input type="checkbox"/> Sidewalk | <input checked="" type="checkbox"/> Sign |
| <input type="checkbox"/> Tree | <input type="checkbox"/> Streetlamp | <input type="checkbox"/> Other: _____ |

Sign on Pole

Needing Attention:

- | | | |
|-----------------------------------|----------------------------------|---|
| <input type="checkbox"/> Damage | <input type="checkbox"/> Pothole | <input type="checkbox"/> Missing |
| <input type="checkbox"/> Painting | <input type="checkbox"/> Grass | <input type="checkbox"/> Needs Trimming |

Submitted by: James Bocchino



Borough of North Arlington

Quality of Life Report

Date: 3-2-2020

Sign put on a u. channel coupe, Reilly, Hort

3/10/20

Location: 176 Canterbury Ave


- | | | |
|----------------------------------|-------------------------------------|--|
| <input type="checkbox"/> Curb | <input type="checkbox"/> Lamp | <input type="checkbox"/> Park |
| <input type="checkbox"/> Fence | <input type="checkbox"/> Playground | <input type="checkbox"/> School |
| <input type="checkbox"/> Roadway | <input type="checkbox"/> Sidewalk | <input checked="" type="checkbox"/> Sign |
| <input type="checkbox"/> Tree | <input type="checkbox"/> Streetlamp | <input type="checkbox"/> Other: _____ |

Sign on Pole

Needing Attention:

- | | | |
|-----------------------------------|----------------------------------|---|
| <input type="checkbox"/> Damage | <input type="checkbox"/> Pothole | <input type="checkbox"/> Missing |
| <input type="checkbox"/> Painting | <input type="checkbox"/> Grass | <input type="checkbox"/> Needs Trimming |

Submitted by: James Bocchino



Borough of North Arlington

Quality of Life Report

Date: 2-24-2020

Completed 31420 Keogh

Location: 88 Arlington Blvd


- | | | |
|----------------------------------|-------------------------------------|--|
| <input type="checkbox"/> Curb | <input type="checkbox"/> Lamp | <input type="checkbox"/> Park |
| <input type="checkbox"/> Fence | <input type="checkbox"/> Playground | <input type="checkbox"/> School |
| <input type="checkbox"/> Roadway | <input type="checkbox"/> Sidewalk | <input checked="" type="checkbox"/> Sign |
| <input type="checkbox"/> Tree | <input type="checkbox"/> Streetlamp | <input type="checkbox"/> Other: _____ |

Sign is embedded in tree (dog waste)

Needing Attention:

- | | | |
|-----------------------------------|----------------------------------|---|
| <input type="checkbox"/> Damage | <input type="checkbox"/> Pothole | <input type="checkbox"/> Missing |
| <input type="checkbox"/> Painting | <input type="checkbox"/> Grass | <input type="checkbox"/> Needs Trimming |

Submitted by: James Bochenko



Borough of North Arlington

Quality of Life Report

Date: 2-24-2020

WAS completed in the Past ALwotto coupe 313120

Location: 55 Belmont Ave


- | | | |
|----------------------------------|-------------------------------------|--|
| <input type="checkbox"/> Curb | <input type="checkbox"/> Lamp | <input type="checkbox"/> Park |
| <input type="checkbox"/> Fence | <input type="checkbox"/> Playground | <input type="checkbox"/> School |
| <input type="checkbox"/> Roadway | <input type="checkbox"/> Sidewalk | <input checked="" type="checkbox"/> Sign |
| <input type="checkbox"/> Tree | <input type="checkbox"/> Streetlamp | <input type="checkbox"/> Other: _____ |

Sign on Pole (take off)

Needing Attention:

- | | | |
|-----------------------------------|----------------------------------|---|
| <input type="checkbox"/> Damage | <input type="checkbox"/> Pothole | <input type="checkbox"/> Missing |
| <input type="checkbox"/> Painting | <input type="checkbox"/> Grass | <input type="checkbox"/> Needs Trimming |

Submitted by: James Bocchino



Borough of North Arlington

Quality of Life Report

Date: 2-26-2020

Completed Aluotto, coupe 2/3/20

Location: 4 Vandershelt Pl


- | | | |
|----------------------------------|-------------------------------------|--|
| <input type="checkbox"/> Curb | <input type="checkbox"/> Lamp | <input type="checkbox"/> Park |
| <input type="checkbox"/> Fence | <input type="checkbox"/> Playground | <input type="checkbox"/> School |
| <input type="checkbox"/> Roadway | <input type="checkbox"/> Sidewalk | <input checked="" type="checkbox"/> Sign |
| <input type="checkbox"/> Tree | <input type="checkbox"/> Streetlamp | <input type="checkbox"/> Other: _____ |

Replace sign no Parking 1-3 PM New

Needing Attention:

- | | | |
|-----------------------------------|----------------------------------|---|
| <input type="checkbox"/> Damage | <input type="checkbox"/> Pothole | <input type="checkbox"/> Missing |
| <input type="checkbox"/> Painting | <input type="checkbox"/> Grass | <input type="checkbox"/> Needs Trimming |

Submitted by: James Baschiro



Borough of North Arlington

Quality of Life Report

Date: 2-26-2020

Removed not needed Aluotto coupe 3/31/20

Location: Crystal St @ Rome Parking lot


- Curb
- Fence
- Roadway
- Tree
- Lamp
- Playground
- Sidewalk
- Streetlamp
- Park
- School
- Sign
- Other: _____

Stop ahead sign faded

Needing Attention:

- Damage
- Painting
- Pothole
- Grass
- Missing
- Needs Trimming

Submitted by: James Boeckeno



Borough of North Arlington

Quality of Life Report

Date: 2-27-2020

Removed 313130 ALUOTTO COUPE

Location: Albert St. on top by Ridge Rd


- | | | |
|----------------------------------|-------------------------------------|--|
| <input type="checkbox"/> Curb | <input type="checkbox"/> Lamp | <input type="checkbox"/> Park |
| <input type="checkbox"/> Fence | <input type="checkbox"/> Playground | <input type="checkbox"/> School |
| <input type="checkbox"/> Roadway | <input type="checkbox"/> Sidewalk | <input checked="" type="checkbox"/> Sign |
| <input type="checkbox"/> Tree | <input type="checkbox"/> Streetlamp | <input type="checkbox"/> Other: _____ |

Wrong Way sign Totally fixed

Needing Attention:

- | | | |
|-----------------------------------|----------------------------------|---|
| <input type="checkbox"/> Damage | <input type="checkbox"/> Pothole | <input type="checkbox"/> Missing |
| <input type="checkbox"/> Painting | <input type="checkbox"/> Grass | <input type="checkbox"/> Needs Trimming |

Submitted by: James Boecklin



Borough of North Arlington

Quality of Life Report

Date: 2-20-20

Completed 2/27/20 Aluotto, Hort

Location: 26 Arlingtons Blvd


- | | | |
|----------------------------------|-------------------------------------|--|
| <input type="checkbox"/> Curb | <input type="checkbox"/> Lamp | <input type="checkbox"/> Park |
| <input type="checkbox"/> Fence | <input type="checkbox"/> Playground | <input type="checkbox"/> School |
| <input type="checkbox"/> Roadway | <input type="checkbox"/> Sidewalk | <input checked="" type="checkbox"/> Sign |
| <input type="checkbox"/> Tree | <input type="checkbox"/> Streetlamp | <input type="checkbox"/> Other: _____ |

Sign to be turned, its facing towards house

Needing Attention:

- | | | |
|-----------------------------------|----------------------------------|---|
| <input type="checkbox"/> Damage | <input type="checkbox"/> Pothole | <input type="checkbox"/> Missing |
| <input type="checkbox"/> Painting | <input type="checkbox"/> Grass | <input type="checkbox"/> Needs Trimming |

Submitted by: James Baschiro



Borough of North Arlington

Quality of Life Report

Date: 2-19-20

Completed Hoyt Aluotto 2/25/20

Location: 59 Belmont ave


- | | | |
|----------------------------------|-------------------------------------|--|
| <input type="checkbox"/> Curb | <input type="checkbox"/> Lamp | <input type="checkbox"/> Park |
| <input type="checkbox"/> Fence | <input type="checkbox"/> Playground | <input type="checkbox"/> School |
| <input type="checkbox"/> Roadway | <input type="checkbox"/> Sidewalk | <input checked="" type="checkbox"/> Sign |
| <input type="checkbox"/> Tree | <input type="checkbox"/> Streetlamp | <input type="checkbox"/> Other: _____ |

Sign on Pole - remove

Needing Attention:

- | | | |
|-----------------------------------|----------------------------------|---|
| <input type="checkbox"/> Damage | <input type="checkbox"/> Pothole | <input type="checkbox"/> Missing |
| <input type="checkbox"/> Painting | <input type="checkbox"/> Grass | <input type="checkbox"/> Needs Trimming |

Submitted by: James Baschino



Borough of North Arlington

Quality of Life Report

Date: 2-19-20

Completed Hort, Alutto also/20

Location: 164 Eagle St


- Curb
- Fence
- Roadway
- Tree
- Lamp
- Playground
- Sidewalk
- Streetlamp
- Park
- School
- Sign
- Other: _____

Replace Sign - No Parking this side

Needing Attention:

- Damage
- Painting
- Pothole
- Grass
- Missing
- Needs Trimming

Submitted by: James Basolino



Borough of North Arlington

Quality of Life Report

Date: 2-18-20

ARROW →

Not needed 2/25/20

Location: 105 Park Ave


- | | | |
|----------------------------------|-------------------------------------|--|
| <input type="checkbox"/> Curb | <input type="checkbox"/> Lamp | <input type="checkbox"/> Park |
| <input type="checkbox"/> Fence | <input type="checkbox"/> Playground | <input type="checkbox"/> School |
| <input type="checkbox"/> Roadway | <input type="checkbox"/> Sidewalk | <input checked="" type="checkbox"/> Sign |
| <input type="checkbox"/> Tree | <input type="checkbox"/> Streetlamp | <input type="checkbox"/> Other: _____ |

Sign needs to face west, its facing across st.

Needing Attention:

- | | | |
|-----------------------------------|----------------------------------|---|
| <input type="checkbox"/> Damage | <input type="checkbox"/> Pothole | <input type="checkbox"/> Missing |
| <input type="checkbox"/> Painting | <input type="checkbox"/> Grass | <input type="checkbox"/> Needs Trimming |

Submitted by: James Bocchino



Borough of North Arlington

Quality of Life Report

Date: 2-18-20

Completed Hoyt, Alutto 2/18/20

Location: 90 Forest St


- Curb
- Fence
- Roadway
- Tree
- Lamp
- Playground
- Sidewalk
- Streetlamp
- Park
- School
- Sign
- Other: _____

Replace sign Tues 10-AM - 12 noon (no Park)

Needing Attention:

- Damage
- Painting
- Pothole
- Grass
- Missing
- Needs Trimming

Submitted by: James Baschimo



Borough of North Arlington
Quality of Life Report

Date: 2-10-2020

Added 2 u-channels/signs completed 2/19/20 Alutto, coupe, Hort

Location: 36 Birchwood Dr. US sign for
Sweeper - but no other sign all the
way down to River Road


- | | | |
|----------------------------------|-------------------------------------|--|
| <input type="checkbox"/> Curb | <input type="checkbox"/> Lamp | <input type="checkbox"/> Park |
| <input type="checkbox"/> Fence | <input type="checkbox"/> Playground | <input type="checkbox"/> School |
| <input type="checkbox"/> Roadway | <input type="checkbox"/> Sidewalk | <input checked="" type="checkbox"/> Sign |
| <input type="checkbox"/> Tree | <input type="checkbox"/> Streetlamp | <input type="checkbox"/> Other: _____ |

No Parking Thurs 8-10 AM

Needing Attention:

- | | | |
|-----------------------------------|----------------------------------|---|
| <input type="checkbox"/> Damage | <input type="checkbox"/> Pothole | <input type="checkbox"/> Missing |
| <input type="checkbox"/> Painting | <input type="checkbox"/> Grass | <input type="checkbox"/> Needs Trimming |

Submitted by: James Baschimo



Borough of North Arlington

Quality of Life Report

Date: 2-18-2020

UNFOUNDED ALUOTTO, COUPE

Location: Zadroga Field


- Curb
- Fence
- Roadway
- Tree
- Lamp
- Playground
- Sidewalk
- Streetlamp
- Park
- School
- Sign
- Other: _____

No right turn coming out of field

Needing Attention:

- Damage
- Painting
- Pothole
- Grass
- Missing
- Needs Trimming

Submitted by: James Basolino



Borough of North Arlington

Quality of Life Report

Date: 2-11 - 2-12 - 2-13

Out pick

Location: _____

Curb

Lamp

Park

Fence

Playground

School

Roadway

Sidewalk

Sign

Tree

Streetlamp

Other: _____

Needing Attention:

Damage

Pothole


Missing

Painting

Grass

Needs Trimming

Submitted by: James Boecklin



Borough of North Arlington
Quality of Life Report

Date: 2-4-2020

Completed 2/13/20 Chavati, Keogh

Location: 44 1/2 Sept St


- | | | |
|----------------------------------|-------------------------------------|--|
| <input type="checkbox"/> Curb | <input type="checkbox"/> Lamp | <input type="checkbox"/> Park |
| <input type="checkbox"/> Fence | <input type="checkbox"/> Playground | <input type="checkbox"/> School |
| <input type="checkbox"/> Roadway | <input type="checkbox"/> Sidewalk | <input checked="" type="checkbox"/> Sign |
| <input type="checkbox"/> Tree | <input type="checkbox"/> Streetlamp | <input type="checkbox"/> Other: _____ |

Sign on Pole

Needing Attention:

- | | | |
|-----------------------------------|----------------------------------|---|
| <input type="checkbox"/> Damage | <input type="checkbox"/> Pothole | <input type="checkbox"/> Missing |
| <input type="checkbox"/> Painting | <input type="checkbox"/> Grass | <input type="checkbox"/> Needs Trimming |

Submitted by: James Bochner's



Borough of North Arlington

Quality of Life Report

Date: 2-4-2020

Completed 2/13/20 Churuti, Keogh

Location: 37 Larrigan Pl


- | | | |
|----------------------------------|-------------------------------------|--|
| <input type="checkbox"/> Curb | <input type="checkbox"/> Lamp | <input type="checkbox"/> Park |
| <input type="checkbox"/> Fence | <input type="checkbox"/> Playground | <input type="checkbox"/> School |
| <input type="checkbox"/> Roadway | <input type="checkbox"/> Sidewalk | <input checked="" type="checkbox"/> Sign |
| <input type="checkbox"/> Tree | <input type="checkbox"/> Streetlamp | <input type="checkbox"/> Other: _____ |

Cannot read sign of an Pole

Needing Attention:

- | | | |
|-----------------------------------|----------------------------------|---|
| <input type="checkbox"/> Damage | <input type="checkbox"/> Pothole | <input type="checkbox"/> Missing |
| <input type="checkbox"/> Painting | <input type="checkbox"/> Grass | <input type="checkbox"/> Needs Trimming |

Submitted by: James Bocchenis



Borough of North Arlington
Quality of Life Report

Date: 2-5-2020

UNFOUNDED 2/13/20

coupe, Alotto

Location: Prospect & Alford


- | | | |
|----------------------------------|-------------------------------------|--|
| <input type="checkbox"/> Curb | <input type="checkbox"/> Lamp | <input type="checkbox"/> Park |
| <input type="checkbox"/> Fence | <input type="checkbox"/> Playground | <input type="checkbox"/> School |
| <input type="checkbox"/> Roadway | <input type="checkbox"/> Sidewalk | <input checked="" type="checkbox"/> Sign |
| <input type="checkbox"/> Tree | <input type="checkbox"/> Streetlamp | <input type="checkbox"/> Other: _____ |

Needs to be replace Sign faded

Needing Attention:

- | | | |
|-----------------------------------|----------------------------------|---|
| <input type="checkbox"/> Damage | <input type="checkbox"/> Pothole | <input type="checkbox"/> Missing |
| <input type="checkbox"/> Painting | <input type="checkbox"/> Grass | <input type="checkbox"/> Needs Trimming |

Submitted by: James Barbone



Borough of North Arlington
Quality of Life Report

Date: 2-5-2020

Completed 213120 coupe, Aluotto

Location: 25 Tipton St.


- | | | |
|----------------------------------|-------------------------------------|--|
| <input type="checkbox"/> Curb | <input type="checkbox"/> Lamp | <input type="checkbox"/> Park |
| <input type="checkbox"/> Fence | <input type="checkbox"/> Playground | <input type="checkbox"/> School |
| <input type="checkbox"/> Roadway | <input type="checkbox"/> Sidewalk | <input checked="" type="checkbox"/> Sign |
| <input type="checkbox"/> Tree | <input type="checkbox"/> Streetlamp | <input type="checkbox"/> Other: _____ |

Must need sign Permit Parking key

Needing Attention:

- | | | |
|-----------------------------------|----------------------------------|---|
| <input type="checkbox"/> Damage | <input type="checkbox"/> Pothole | <input type="checkbox"/> Missing |
| <input type="checkbox"/> Painting | <input type="checkbox"/> Grass | <input type="checkbox"/> Needs Trimming |

Submitted by: James Bocchino



Borough of North Arlington
Quality of Life Report

Date: 2-6-2020

Completed 2/13/20
coupe, Aluotto

Location: Sunset Ave
by Doreen Catano


- | | | |
|----------------------------------|-------------------------------------|--|
| <input type="checkbox"/> Curb | <input type="checkbox"/> Lamp | <input type="checkbox"/> Park |
| <input type="checkbox"/> Fence | <input type="checkbox"/> Playground | <input type="checkbox"/> School |
| <input type="checkbox"/> Roadway | <input type="checkbox"/> Sidewalk | <input checked="" type="checkbox"/> Sign |
| <input type="checkbox"/> Tree | <input type="checkbox"/> Streetlamp | <input type="checkbox"/> Other: _____ |

po pole remove

Needing Attention:

- | | | |
|-----------------------------------|----------------------------------|---|
| <input type="checkbox"/> Damage | <input type="checkbox"/> Pothole | <input type="checkbox"/> Missing |
| <input type="checkbox"/> Painting | <input type="checkbox"/> Grass | <input type="checkbox"/> Needs Trimming |

Submitted by: James Buckino



Borough of North Arlington

Quality of Life Report

Date: 1-27-2020

Completed 214120 coupe, Hoyt

Location: 15 Brandenburg Pl


- | | | |
|----------------------------------|-------------------------------------|--|
| <input type="checkbox"/> Curb | <input type="checkbox"/> Lamp | <input type="checkbox"/> Park |
| <input type="checkbox"/> Fence | <input type="checkbox"/> Playground | <input type="checkbox"/> School |
| <input type="checkbox"/> Roadway | <input type="checkbox"/> Sidewalk | <input checked="" type="checkbox"/> Sign |
| <input type="checkbox"/> Tree | <input type="checkbox"/> Streetlamp | <input type="checkbox"/> Other: _____ |

Replace sign Wed. 1-3 PM

Needing Attention:

- | | | |
|-----------------------------------|----------------------------------|---|
| <input type="checkbox"/> Damage | <input type="checkbox"/> Pothole | <input type="checkbox"/> Missing |
| <input type="checkbox"/> Painting | <input type="checkbox"/> Grass | <input type="checkbox"/> Needs Trimming |

Submitted by: James Bochens



Borough of North Arlington
Quality of Life Report

Date: 1-30-2020

completed 214120 coupe, Hoyt


Location: Padroga field

- | | | |
|----------------------------------|-------------------------------------|--|
| <input type="checkbox"/> Curb | <input type="checkbox"/> Lamp | <input checked="" type="checkbox"/> Park |
| <input type="checkbox"/> Fence | <input type="checkbox"/> Playground | <input type="checkbox"/> School |
| <input type="checkbox"/> Roadway | <input type="checkbox"/> Sidewalk | <input checked="" type="checkbox"/> Sign |
| <input type="checkbox"/> Tree | <input type="checkbox"/> Streetlamp | <input type="checkbox"/> Other: _____ |

Going out of field, sign (no left turn)
Needing Attention: is faded

- | | | |
|-----------------------------------|----------------------------------|---|
| <input type="checkbox"/> Damage | <input type="checkbox"/> Pothole | <input type="checkbox"/> Missing |
| <input type="checkbox"/> Painting | <input type="checkbox"/> Grass | <input type="checkbox"/> Needs Trimming |

Submitted by: James Bocchino



Borough of North Arlington
Quality of Life Report

Date: 1-30-2020

completed 214120 coupe, Hoyt

Location: 175 Sunset Man 10 to Pass


- | | | |
|----------------------------------|-------------------------------------|--|
| <input type="checkbox"/> Curb | <input type="checkbox"/> Lamp | <input type="checkbox"/> Park |
| <input type="checkbox"/> Fence | <input type="checkbox"/> Playground | <input type="checkbox"/> School |
| <input type="checkbox"/> Roadway | <input type="checkbox"/> Sidewalk | <input checked="" type="checkbox"/> Sign |
| <input type="checkbox"/> Tree | <input type="checkbox"/> Streetlamp | <input type="checkbox"/> Other: _____ |

replace

Needing Attention:

- | | | |
|-----------------------------------|----------------------------------|---|
| <input type="checkbox"/> Damage | <input type="checkbox"/> Pothole | <input type="checkbox"/> Missing |
| <input type="checkbox"/> Painting | <input type="checkbox"/> Grass | <input type="checkbox"/> Needs Trimming |

Submitted by: James Boehme



Borough of North Arlington
Quality of Life Report

Date: 10-10-2019


Location: * 88 Canton Ave No Parking 10-noon Mon completes 11/28/20 Aluotto, Chiofetti
18 Pershing Pl (No Parking 8-10 Mon) concrete

- | | | |
|----------------------------------|-------------------------------------|--|
| <input type="checkbox"/> Curb | <input type="checkbox"/> Lamp | <input type="checkbox"/> Park |
| <input type="checkbox"/> Fence | <input type="checkbox"/> Playground | <input type="checkbox"/> School |
| <input type="checkbox"/> Roadway | <input type="checkbox"/> Sidewalk | <input checked="" type="checkbox"/> Sign |
| <input type="checkbox"/> Tree | <input type="checkbox"/> Streetlamp | <input type="checkbox"/> Other: <u>Replace</u> |

Needing Attention:

- | | | |
|-----------------------------------|----------------------------------|---|
| <input type="checkbox"/> Damage | <input type="checkbox"/> Pothole | <input type="checkbox"/> Missing |
| <input type="checkbox"/> Painting | <input type="checkbox"/> Grass | <input type="checkbox"/> Needs Trimming |

Submitted by: James Boeckner



Borough of North Arlington
Quality of Life Report

Date: 10-31-2019

Akotto, Churuti
completed 1/28/20


Location: Sunset & Reverew Speed bump
(can't read)

- | | | |
|----------------------------------|-------------------------------------|--|
| <input type="checkbox"/> Curb | <input type="checkbox"/> Lamp | <input type="checkbox"/> Park |
| <input type="checkbox"/> Fence | <input type="checkbox"/> Playground | <input type="checkbox"/> School |
| <input type="checkbox"/> Roadway | <input type="checkbox"/> Sidewalk | <input checked="" type="checkbox"/> Sign |
| <input type="checkbox"/> Tree | <input type="checkbox"/> Streetlamp | <input type="checkbox"/> Other: _____ |

Needing Attention:

- | | | |
|-----------------------------------|----------------------------------|---|
| <input type="checkbox"/> Damage | <input type="checkbox"/> Pothole | <input type="checkbox"/> Missing |
| <input type="checkbox"/> Painting | <input type="checkbox"/> Grass | <input type="checkbox"/> Needs Trimming |

Submitted by: James V. Becklin



Borough of North Arlington
Quality of Life Report

Date: 11-14-19

Akotto, coupe

Completed 11/28/20

Location: Conterbury Ave going east & west

Curb

Lamp

Park

Fence

Playground

School

Roadway

Sidewalk

Sign

Tree

Streetlamp

Other: _____

Can't read speedbump at night

Needing Attention:

Damage

Pothole


Missing

Painting

Grass

Needs Trimming

Submitted by: James Bacchino



Borough of North Arlington
Quality of Life Report

Date: 1-21-20

P.V.W.C. Notified and notice.

Location: Cyton Ave & Forest ~~St~~ St


- | | | |
|----------------------------------|-------------------------------------|--|
| <input type="checkbox"/> Curb | <input type="checkbox"/> Lamp | <input type="checkbox"/> Park |
| <input type="checkbox"/> Fence | <input type="checkbox"/> Playground | <input type="checkbox"/> School |
| <input type="checkbox"/> Roadway | <input type="checkbox"/> Sidewalk | <input type="checkbox"/> Sign |
| <input type="checkbox"/> Tree | <input type="checkbox"/> Streetlamp | <input type="checkbox"/> Other: <u>Hydrant</u> |

Hydrant leaning

Needing Attention:

- | | | |
|-----------------------------------|----------------------------------|---|
| <input type="checkbox"/> Damage | <input type="checkbox"/> Pothole | <input type="checkbox"/> Missing |
| <input type="checkbox"/> Painting | <input type="checkbox"/> Grass | <input type="checkbox"/> Needs Trimming |

Submitted by: James Beckwith



Borough of North Arlington
Quality of Life Report

Date: 1-28-20

Alvotto, Chavuti
Completed 1/28/20

Location: 25 Chamberburg


- | | | |
|---|-------------------------------------|---------------------------------------|
| <input type="checkbox"/> Curb | <input type="checkbox"/> Lamp | <input type="checkbox"/> Park |
| <input type="checkbox"/> Fence | <input type="checkbox"/> Playground | <input type="checkbox"/> School |
| <input checked="" type="checkbox"/> Roadway | <input type="checkbox"/> Sidewalk | <input type="checkbox"/> Sign |
| <input type="checkbox"/> Tree | <input type="checkbox"/> Streetlamp | <input type="checkbox"/> Other: _____ |

Speedbumps cannot read at night E & W

Needing Attention:

- | | | |
|-----------------------------------|----------------------------------|---|
| <input type="checkbox"/> Damage | <input type="checkbox"/> Pothole | <input type="checkbox"/> Missing |
| <input type="checkbox"/> Painting | <input type="checkbox"/> Grass | <input type="checkbox"/> Needs Trimming |

Submitted by: James Beckins



Borough of North Arlington
Quality of Life Report

Date: 1-23-20

Alvotto, Christi
completed 1/28/20

Location: 29 Willis Road


- | | | |
|----------------------------------|-------------------------------------|--|
| <input type="checkbox"/> Curb | <input type="checkbox"/> Lamp | <input type="checkbox"/> Park |
| <input type="checkbox"/> Fence | <input type="checkbox"/> Playground | <input type="checkbox"/> School |
| <input type="checkbox"/> Roadway | <input type="checkbox"/> Sidewalk | <input checked="" type="checkbox"/> Sign |
| <input type="checkbox"/> Tree | <input type="checkbox"/> Streetlamp | <input type="checkbox"/> Other: _____ |

Can't read sign No Park - Now 1-3

Needing Attention:

- | | | |
|-----------------------------------|----------------------------------|---|
| <input type="checkbox"/> Damage | <input type="checkbox"/> Pothole | <input type="checkbox"/> Missing |
| <input type="checkbox"/> Painting | <input type="checkbox"/> Grass | <input type="checkbox"/> Needs Trimming |

Submitted by: James Bochenko



Borough of North Arlington
Quality of Life Report

Date: 11-27-2019

UNFOUNDED 1/23/20

Location: 60 Boston Ave

- | | | |
|----------------------------------|-------------------------------------|---------------------------------------|
| <input type="checkbox"/> Curb | <input type="checkbox"/> Lamp | <input type="checkbox"/> Park |
| <input type="checkbox"/> Fence | <input type="checkbox"/> Playground | <input type="checkbox"/> School |
| <input type="checkbox"/> Roadway | <input type="checkbox"/> Sidewalk | <input type="checkbox"/> Sign |
| <input type="checkbox"/> Tree | <input type="checkbox"/> Streetlamp | <input type="checkbox"/> Other: _____ |

Needing Attention:

- | | | |
|-----------------------------------|---|---|
| <input type="checkbox"/> Damage | <input checked="" type="checkbox"/> Pothole | <input type="checkbox"/> Missing |
| <input type="checkbox"/> Painting | <input type="checkbox"/> Grass | <input type="checkbox"/> Needs Trimming |

Submitted by: James Bechini