

Borough of North Arlington
Quality of Life Report

Date: 12-10-2019

Completed Blacktop 11/23/20

Location: 9th St & Lincoln Ave


- | | | |
|---|-------------------------------------|---------------------------------------|
| <input type="checkbox"/> Curb | <input type="checkbox"/> Lamp | <input type="checkbox"/> Park |
| <input type="checkbox"/> Fence | <input type="checkbox"/> Playground | <input type="checkbox"/> School |
| <input checked="" type="checkbox"/> Roadway | <input type="checkbox"/> Sidewalk | <input type="checkbox"/> Sign |
| <input type="checkbox"/> Tree | <input type="checkbox"/> Streetlamp | <input type="checkbox"/> Other: _____ |

Small hole in road

Needing Attention:

- | | | |
|-----------------------------------|----------------------------------|---|
| <input type="checkbox"/> Damage | <input type="checkbox"/> Pothole | <input type="checkbox"/> Missing |
| <input type="checkbox"/> Painting | <input type="checkbox"/> Grass | <input type="checkbox"/> Needs Trimming |

Submitted by: James Berchio



Borough of North Arlington
Quality of Life Report

Date: 12-23-2019

completed black top crew 11/23/20

Location: Schuyler & Sherman ave


- | | | |
|---|-------------------------------------|---------------------------------------|
| <input type="checkbox"/> Curb | <input type="checkbox"/> Lamp | <input type="checkbox"/> Park |
| <input type="checkbox"/> Fence | <input type="checkbox"/> Playground | <input type="checkbox"/> School |
| <input checked="" type="checkbox"/> Roadway | <input type="checkbox"/> Sidewalk | <input type="checkbox"/> Sign |
| <input type="checkbox"/> Tree | <input type="checkbox"/> Streetlamp | <input type="checkbox"/> Other: _____ |

Hole in road by curb

Needing Attention:

- | | | |
|-----------------------------------|----------------------------------|---|
| <input type="checkbox"/> Damage | <input type="checkbox"/> Pothole | <input type="checkbox"/> Missing |
| <input type="checkbox"/> Painting | <input type="checkbox"/> Grass | <input type="checkbox"/> Needs Trimming |

Submitted by: James Bochneris



Borough of North Arlington
Quality of Life Report

Date: 1-13-2020

Suez vent P;Pc 1122/20

Location: Schuyler Ave & Park Ave at traffic light

Curb

Lamp

Park

Fence

Playground

School

Roadway

Sidewalk

Sign

Tree

Streetlamp

Other: Vent Pipe

Vent Pipe is leaking

Needing Attention:

Damage

Pothole


Missing

Painting

Grass

Needs Trimming

Submitted by: James Beckens



Borough of North Arlington
Quality of Life Report

Date: 1-13-2020

Suez vent pipe 1122120

Location: Schuylers Ave & Belleville Pike
on Foodtown


- | | | |
|----------------------------------|-------------------------------------|---------------------------------------|
| <input type="checkbox"/> Curb | <input type="checkbox"/> Lamp | <input type="checkbox"/> Park |
| <input type="checkbox"/> Fence | <input type="checkbox"/> Playground | <input type="checkbox"/> School |
| <input type="checkbox"/> Roadway | <input type="checkbox"/> Sidewalk | <input type="checkbox"/> Sign |
| <input type="checkbox"/> Tree | <input type="checkbox"/> Streetlamp | <input type="checkbox"/> Other: _____ |

Vent pipe leaning near parking lot

Needing Attention:

- | | | |
|-----------------------------------|----------------------------------|---|
| <input type="checkbox"/> Damage | <input type="checkbox"/> Pothole | <input type="checkbox"/> Missing |
| <input type="checkbox"/> Painting | <input type="checkbox"/> Grass | <input type="checkbox"/> Needs Trimming |

Submitted by: James Beckeno



Borough of North Arlington
Quality of Life Report

Date: 1-14-2020

P.V.W.C. Valve Box TBD

Location: Inman Pl & Rutledge Pl


- | | | |
|---|-------------------------------------|---------------------------------------|
| <input type="checkbox"/> Curb | <input type="checkbox"/> Lamp | <input type="checkbox"/> Park |
| <input type="checkbox"/> Fence | <input type="checkbox"/> Playground | <input type="checkbox"/> School |
| <input checked="" type="checkbox"/> Roadway | <input type="checkbox"/> Sidewalk | <input type="checkbox"/> Sign |
| <input type="checkbox"/> Tree | <input type="checkbox"/> Streetlamp | <input type="checkbox"/> Other: _____ |

By Catch Basin Pipe parking all Cracked

Needing Attention:

- | | | |
|-----------------------------------|----------------------------------|---|
| <input type="checkbox"/> Damage | <input type="checkbox"/> Pothole | <input type="checkbox"/> Missing |
| <input type="checkbox"/> Painting | <input type="checkbox"/> Grass | <input type="checkbox"/> Needs Trimming |

Submitted by: James Becken



Borough of North Arlington
Quality of Life Report

Date: 1-15-2020

Valve Box / Water main Break

PERMANENT REPAIR T.B.D. 60-90 P.V.W.C

Location: Morgan & James Pl


- | | | |
|---|-------------------------------------|---------------------------------------|
| <input type="checkbox"/> Curb | <input type="checkbox"/> Lamp | <input type="checkbox"/> Park |
| <input type="checkbox"/> Fence | <input type="checkbox"/> Playground | <input type="checkbox"/> School |
| <input checked="" type="checkbox"/> Roadway | <input type="checkbox"/> Sidewalk | <input type="checkbox"/> Sign |
| <input type="checkbox"/> Tree | <input type="checkbox"/> Streetlamp | <input type="checkbox"/> Other: _____ |

Issue in Road - Water pipe sinking below road

Needing Attention: blacktop breaking up

- | | | |
|-----------------------------------|----------------------------------|---|
| <input type="checkbox"/> Damage | <input type="checkbox"/> Pothole | <input type="checkbox"/> Missing |
| <input type="checkbox"/> Painting | <input type="checkbox"/> Grass | <input type="checkbox"/> Needs Trimming |

Submitted by: James Boehm



Borough of North Arlington
Quality of Life Report

Date: 1-15-2028

Valve Box / Water Main Repair T.B.D.
P.V.W.C.

Location: Inman Pl & Rutledge Pl


- | | | |
|---|-------------------------------------|---------------------------------------|
| <input type="checkbox"/> Curb | <input type="checkbox"/> Lamp | <input type="checkbox"/> Park |
| <input type="checkbox"/> Fence | <input type="checkbox"/> Playground | <input type="checkbox"/> School |
| <input checked="" type="checkbox"/> Roadway | <input type="checkbox"/> Sidewalk | <input type="checkbox"/> Sign |
| <input type="checkbox"/> Tree | <input type="checkbox"/> Streetlamp | <input type="checkbox"/> Other: _____ |

Hole in road - water pipe sinking below road

Needing Attention:

- | | | |
|-----------------------------------|----------------------------------|---|
| <input type="checkbox"/> Damage | <input type="checkbox"/> Pothole | <input type="checkbox"/> Missing |
| <input type="checkbox"/> Painting | <input type="checkbox"/> Grass | <input type="checkbox"/> Needs Trimming |

Submitted by: James Beckmo



Borough of North Arlington

Quality of Life Report

Date: 11-16-2020

Valve Box / Water Main Repair TBD
P.V.W.C.

Location: 106 Park Ave.


- | | | |
|---|-------------------------------------|---------------------------------------|
| <input type="checkbox"/> Curb | <input type="checkbox"/> Lamp | <input type="checkbox"/> Park |
| <input type="checkbox"/> Fence | <input type="checkbox"/> Playground | <input type="checkbox"/> School |
| <input checked="" type="checkbox"/> Roadway | <input type="checkbox"/> Sidewalk | <input type="checkbox"/> Sign |
| <input type="checkbox"/> Tree | <input type="checkbox"/> Streetlamp | <input type="checkbox"/> Other: _____ |

Hole in middle of Road Water Pipe sticking about 4"

Needing Attention:

- | | | |
|-----------------------------------|----------------------------------|---|
| <input type="checkbox"/> Damage | <input type="checkbox"/> Pothole | <input type="checkbox"/> Missing |
| <input type="checkbox"/> Painting | <input type="checkbox"/> Grass | <input type="checkbox"/> Needs Trimming |

Submitted by: James Beckano



Borough of North Arlington
Quality of Life Report

Date: 1-9-2020

1115120

Been advised Unit-8/county advised

Location: Bevis Road & Crystal - Jusk York


- | | | |
|----------------------------------|-------------------------------------|---------------------------------------|
| <input type="checkbox"/> Curb | <input type="checkbox"/> Lamp | <input type="checkbox"/> Park |
| <input type="checkbox"/> Fence | <input type="checkbox"/> Playground | <input type="checkbox"/> School |
| <input type="checkbox"/> Roadway | <input type="checkbox"/> Sidewalk | <input type="checkbox"/> Sign |
| <input type="checkbox"/> Tree | <input type="checkbox"/> Streetlamp | <input type="checkbox"/> Other: _____ |

Needing Attention:

- | | | |
|--|----------------------------------|---|
| <input checked="" type="checkbox"/> Damage | <input type="checkbox"/> Pothole | <input type="checkbox"/> Missing |
| <input type="checkbox"/> Painting | <input type="checkbox"/> Grass | <input type="checkbox"/> Needs Trimming |

Guardrail to be repaired

Submitted by: James Becken



Borough of North Arlington
Quality of Life Report

Date: 1-8-2020

Completed 1/15/20 coupe

Location: 66 Herdell Ave


- | | | |
|----------------------------------|-------------------------------------|--|
| <input type="checkbox"/> Curb | <input type="checkbox"/> Lamp | <input type="checkbox"/> Park |
| <input type="checkbox"/> Fence | <input type="checkbox"/> Playground | <input type="checkbox"/> School |
| <input type="checkbox"/> Roadway | <input type="checkbox"/> Sidewalk | <input checked="" type="checkbox"/> Sign |
| <input type="checkbox"/> Tree | <input type="checkbox"/> Streetlamp | <input type="checkbox"/> Other: _____ |

Sign on Pole

Needing Attention:

- | | | |
|-----------------------------------|----------------------------------|---|
| <input type="checkbox"/> Damage | <input type="checkbox"/> Pothole | <input type="checkbox"/> Missing |
| <input type="checkbox"/> Painting | <input type="checkbox"/> Grass | <input type="checkbox"/> Needs Trimming |

Submitted by: James Buchanan



Borough of North Arlington
Quality of Life Report

Date: 1-7-2020

Trench cut ^{*} Investigate
coupe

Location: 66 Melrose Ave


- Curb
- Fence
- Roadway
- Tree
- Lamp
- Playground
- Sidewalk
- Streetlamp
- Park
- School
- Sign
- Other: _____

Dip in Road

Needing Attention:

- Damage
- Painting
- Pothole
- Grass
- Missing
- Needs Trimming

Submitted by: James Beckenö



Borough of North Arlington
Quality of Life Report

Date: 1-7-2020

Repeat completed previous
coupe

Location: L. Herluff Rd.


- | | | |
|----------------------------------|-------------------------------------|--|
| <input type="checkbox"/> Curb | <input type="checkbox"/> Lamp | <input type="checkbox"/> Park |
| <input type="checkbox"/> Fence | <input type="checkbox"/> Playground | <input type="checkbox"/> School |
| <input type="checkbox"/> Roadway | <input type="checkbox"/> Sidewalk | <input checked="" type="checkbox"/> Sign |
| <input type="checkbox"/> Tree | <input type="checkbox"/> Streetlamp | <input type="checkbox"/> Other: _____ |

Sign on Pole

Needing Attention:

- | | | |
|-----------------------------------|----------------------------------|---|
| <input type="checkbox"/> Damage | <input type="checkbox"/> Pothole | <input type="checkbox"/> Missing |
| <input type="checkbox"/> Painting | <input type="checkbox"/> Grass | <input type="checkbox"/> Needs Trimming |

Submitted by: James Beckeno



Borough of North Arlington
Quality of Life Report

Date: 1-6-2020

Repeat completed coupe

Location: Verhoff Pl


- | | | |
|----------------------------------|-------------------------------------|--|
| <input type="checkbox"/> Curb | <input type="checkbox"/> Lamp | <input type="checkbox"/> Park |
| <input type="checkbox"/> Fence | <input type="checkbox"/> Playground | <input type="checkbox"/> School |
| <input type="checkbox"/> Roadway | <input type="checkbox"/> Sidewalk | <input checked="" type="checkbox"/> Sign |
| <input type="checkbox"/> Tree | <input type="checkbox"/> Streetlamp | <input type="checkbox"/> Other: _____ |

Replace sign (no parking) res 'T road

Needing Attention:

- | | | |
|-----------------------------------|----------------------------------|---|
| <input type="checkbox"/> Damage | <input type="checkbox"/> Pothole | <input type="checkbox"/> Missing |
| <input type="checkbox"/> Painting | <input type="checkbox"/> Grass | <input type="checkbox"/> Needs Trimming |

Submitted by: James Bouchard



Borough of North Arlington
Quality of Life Report

Date: 1-6-2020

Pole in concrete 1/14/20

Location: Pencil Ave & 6th St


- | | | |
|----------------------------------|-------------------------------------|--|
| <input type="checkbox"/> Curb | <input type="checkbox"/> Lamp | <input type="checkbox"/> Park |
| <input type="checkbox"/> Fence | <input type="checkbox"/> Playground | <input type="checkbox"/> School |
| <input type="checkbox"/> Roadway | <input type="checkbox"/> Sidewalk | <input checked="" type="checkbox"/> Sign |
| <input type="checkbox"/> Tree | <input type="checkbox"/> Streetlamp | <input type="checkbox"/> Other: _____ |

Pole is leaning

Needing Attention:

- | | | |
|-----------------------------------|----------------------------------|---|
| <input type="checkbox"/> Damage | <input type="checkbox"/> Pothole | <input type="checkbox"/> Missing |
| <input type="checkbox"/> Painting | <input type="checkbox"/> Grass | <input type="checkbox"/> Needs Trimming |

Submitted by: James Becken



Borough of North Arlington
Quality of Life Report

Date: 12-31-19

completed 11/8/20 coupe, Alutto

Location: 153 Riverside ave


- | | | |
|----------------------------------|-------------------------------------|--|
| <input type="checkbox"/> Curb | <input type="checkbox"/> Lamp | <input type="checkbox"/> Park |
| <input type="checkbox"/> Fence | <input type="checkbox"/> Playground | <input type="checkbox"/> School |
| <input type="checkbox"/> Roadway | <input type="checkbox"/> Sidewalk | <input checked="" type="checkbox"/> Sign |
| <input type="checkbox"/> Tree | <input type="checkbox"/> Streetlamp | <input type="checkbox"/> Other: _____ |

Replace sign No Park 10 AM TO NOON Tues

Needing Attention:

- | | | |
|-----------------------------------|----------------------------------|---|
| <input type="checkbox"/> Damage | <input type="checkbox"/> Pothole | <input type="checkbox"/> Missing |
| <input type="checkbox"/> Painting | <input type="checkbox"/> Grass | <input type="checkbox"/> Needs Trimming |

Submitted by: James Bocchino



Borough of North Arlington

Quality of Life Report

Date: 12-30-19

N/A coupe / Aluotto 118120

Location: 190 Rittleyrd Pl


- Curb
- Fence
- Roadway
- Tree
- Lamp
- Playground
- Sidewalk
- Streetlamp
- Park
- School
- Sign
- Other: _____

Sign on Pole

Needing Attention:

- Damage
- Painting
- Pothole
- Grass
- Missing
- Needs Trimming

Submitted by: James Beckwith



Borough of North Arlington
Quality of Life Report

Date: 12-30-19

Completed coupe, Aluotto 118120

Location: 50 Rutledge Pl


- | | | |
|----------------------------------|-------------------------------------|--|
| <input type="checkbox"/> Curb | <input type="checkbox"/> Lamp | <input type="checkbox"/> Park |
| <input type="checkbox"/> Fence | <input type="checkbox"/> Playground | <input type="checkbox"/> School |
| <input type="checkbox"/> Roadway | <input type="checkbox"/> Sidewalk | <input checked="" type="checkbox"/> Sign |
| <input type="checkbox"/> Tree | <input type="checkbox"/> Streetlamp | <input type="checkbox"/> Other: _____ |

Signs leaning

Needing Attention:

- | | | |
|-----------------------------------|----------------------------------|---|
| <input type="checkbox"/> Damage | <input type="checkbox"/> Pothole | <input type="checkbox"/> Missing |
| <input type="checkbox"/> Painting | <input type="checkbox"/> Grass | <input type="checkbox"/> Needs Trimming |

Submitted by: James Beckeno



Borough of North Arlington

Quality of Life Report

Date: 12-9-2019

Completed 118100 coupe, Alotto

Location: 189 Ridge Rd


- | | | |
|----------------------------------|-------------------------------------|--|
| <input type="checkbox"/> Curb | <input type="checkbox"/> Lamp | <input type="checkbox"/> Park |
| <input type="checkbox"/> Fence | <input type="checkbox"/> Playground | <input type="checkbox"/> School |
| <input type="checkbox"/> Roadway | <input type="checkbox"/> Sidewalk | <input checked="" type="checkbox"/> Sign |
| <input type="checkbox"/> Tree | <input type="checkbox"/> Streetlamp | <input type="checkbox"/> Other: _____ |

Replace sign no Parking when snow covered

Needing Attention:

- | | | |
|-----------------------------------|----------------------------------|---|
| <input type="checkbox"/> Damage | <input type="checkbox"/> Pothole | <input type="checkbox"/> Missing |
| <input type="checkbox"/> Painting | <input type="checkbox"/> Grass | <input type="checkbox"/> Needs Trimming |

Submitted by: James Bochenko



Borough of North Arlington

Quality of Life Report

Date: 12-16-19

Hort, Aluotto
Completed 1/3/20

Location: 64 Melrose Ave

Curb

Lamp

Park

Fence

Playground

School

Roadway

Sidewalk

Sign

Tree

Streetlamp

Other: _____

Replace sign no park 10 AM to noon Thurs

Needing Attention:

Damage

Pothole


Missing

Painting

Grass

Needs Trimming

Submitted by: James Bochner



Borough of North Arlington
Quality of Life Report

Date: 12-16-19

Hoyt, Aluotto
Completed 1/3/20

Location: 46 Wallis St.


- | | | |
|----------------------------------|-------------------------------------|--|
| <input type="checkbox"/> Curb | <input type="checkbox"/> Lamp | <input type="checkbox"/> Park |
| <input type="checkbox"/> Fence | <input type="checkbox"/> Playground | <input type="checkbox"/> School |
| <input type="checkbox"/> Roadway | <input type="checkbox"/> Sidewalk | <input checked="" type="checkbox"/> Sign |
| <input type="checkbox"/> Tree | <input type="checkbox"/> Streetlamp | <input type="checkbox"/> Other: _____ |

Sign is twisted facing hedges

Needing Attention:

- | | | |
|-----------------------------------|----------------------------------|---|
| <input type="checkbox"/> Damage | <input type="checkbox"/> Pothole | <input type="checkbox"/> Missing |
| <input type="checkbox"/> Painting | <input type="checkbox"/> Grass | <input type="checkbox"/> Needs Trimming |

Submitted by: James Bouchino



Borough of North Arlington

Quality of Life Report

Date: 12-17-19

Hort, Aluotto 113120

SIGN CANNOT BE REMOVED (PLACEMENT)

Location: 194 Canterbury Ave


- | | | |
|----------------------------------|-------------------------------------|--|
| <input type="checkbox"/> Curb | <input type="checkbox"/> Lamp | <input type="checkbox"/> Park |
| <input type="checkbox"/> Fence | <input type="checkbox"/> Playground | <input type="checkbox"/> School |
| <input type="checkbox"/> Roadway | <input type="checkbox"/> Sidewalk | <input checked="" type="checkbox"/> Sign |
| <input type="checkbox"/> Tree | <input type="checkbox"/> Streetlamp | <input type="checkbox"/> Other: _____ |

Sign on Pole

Needing Attention:

- | | | |
|-----------------------------------|----------------------------------|---|
| <input type="checkbox"/> Damage | <input type="checkbox"/> Pothole | <input type="checkbox"/> Missing |
| <input type="checkbox"/> Painting | <input type="checkbox"/> Grass | <input type="checkbox"/> Needs Trimming |

Submitted by: James Baccaro



Borough of North Arlington
Quality of Life Report

Date: 12-23-2019

Hort, Alto 113120

SAME AS 194 CANTERBURY (Placement)

Location: 187 Canterbury ave


- | | | |
|----------------------------------|-------------------------------------|--|
| <input type="checkbox"/> Curb | <input type="checkbox"/> Lamp | <input type="checkbox"/> Park |
| <input type="checkbox"/> Fence | <input type="checkbox"/> Playground | <input type="checkbox"/> School |
| <input type="checkbox"/> Roadway | <input type="checkbox"/> Sidewalk | <input checked="" type="checkbox"/> Sign |
| <input type="checkbox"/> Tree | <input type="checkbox"/> Streetlamp | <input type="checkbox"/> Other: _____ |

Sign on Pole

Needing Attention:

- | | | |
|-----------------------------------|----------------------------------|---|
| <input type="checkbox"/> Damage | <input type="checkbox"/> Pothole | <input type="checkbox"/> Missing |
| <input type="checkbox"/> Painting | <input type="checkbox"/> Grass | <input type="checkbox"/> Needs Trimming |

Submitted by: James Bochenko



Borough of North Arlington
Quality of Life Report

Date: 12-26-2019

Hoyt, Aluotto
Completed 1/3/20

Location: 306 Rutledge Pl


- | | | |
|----------------------------------|-------------------------------------|--|
| <input type="checkbox"/> Curb | <input type="checkbox"/> Lamp | <input type="checkbox"/> Park |
| <input type="checkbox"/> Fence | <input type="checkbox"/> Playground | <input type="checkbox"/> School |
| <input type="checkbox"/> Roadway | <input type="checkbox"/> Sidewalk | <input checked="" type="checkbox"/> Sign |
| <input type="checkbox"/> Tree | <input type="checkbox"/> Streetlamp | <input type="checkbox"/> Other: _____ |

Sign on Pole

Needing Attention:

- | | | |
|-----------------------------------|----------------------------------|---|
| <input type="checkbox"/> Damage | <input type="checkbox"/> Pothole | <input type="checkbox"/> Missing |
| <input type="checkbox"/> Painting | <input type="checkbox"/> Grass | <input type="checkbox"/> Needs Trimming |

Submitted by: James Bochner



Borough of North Arlington

Quality of Life Report

Date: 12-12-19
~~12-9-2019~~

Completed w/ Request From
Previous Form MKC

Location: 9 Aslington Ave


- | | | |
|----------------------------------|-------------------------------------|--|
| <input type="checkbox"/> Curb | <input type="checkbox"/> Lamp | <input type="checkbox"/> Park |
| <input type="checkbox"/> Fence | <input type="checkbox"/> Playground | <input type="checkbox"/> School |
| <input type="checkbox"/> Roadway | <input type="checkbox"/> Sidewalk | <input checked="" type="checkbox"/> Sign |
| <input type="checkbox"/> Tree | <input type="checkbox"/> Streetlamp | <input type="checkbox"/> Other: _____ |

Sign on Pole Take off

Needing Attention:

- | | | |
|-----------------------------------|----------------------------------|---|
| <input type="checkbox"/> Damage | <input type="checkbox"/> Pothole | <input type="checkbox"/> Missing |
| <input type="checkbox"/> Painting | <input type="checkbox"/> Grass | <input type="checkbox"/> Needs Trimming |

Submitted by: James Bouchard



Borough of North Arlington

Quality of Life Report

Date: 12-11-19

171 Rutledge Pl (middle of Rd Hole)

Location: 146 Rutledge Pl. } completed
12/18/19
MKC


- | | | |
|---|-------------------------------------|---------------------------------------|
| <input type="checkbox"/> Curb | <input type="checkbox"/> Lamp | <input type="checkbox"/> Park |
| <input type="checkbox"/> Fence | <input type="checkbox"/> Playground | <input type="checkbox"/> School |
| <input checked="" type="checkbox"/> Roadway | <input type="checkbox"/> Sidewalk | <input type="checkbox"/> Sign |
| <input type="checkbox"/> Tree | <input type="checkbox"/> Streetlamp | <input type="checkbox"/> Other: _____ |

Place new curb 2' off curb

Needing Attention:

- | | | |
|-----------------------------------|----------------------------------|---|
| <input type="checkbox"/> Damage | <input type="checkbox"/> Pothole | <input type="checkbox"/> Missing |
| <input type="checkbox"/> Painting | <input type="checkbox"/> Grass | <input type="checkbox"/> Needs Trimming |

Submitted by: James Bochimo



Borough of North Arlington
Quality of Life Report

Date: 9/12-10-19

Scott's LANDSCAPING NOTIFIED.
PART OF SEASON ENDING CONTRACT
MKC


Location: Allen Park

- | | | |
|----------------------------------|-------------------------------------|--|
| <input type="checkbox"/> Curb | <input type="checkbox"/> Lamp | <input checked="" type="checkbox"/> Park |
| <input type="checkbox"/> Fence | <input type="checkbox"/> Playground | <input type="checkbox"/> School |
| <input type="checkbox"/> Roadway | <input type="checkbox"/> Sidewalk | <input type="checkbox"/> Sign |
| <input type="checkbox"/> Tree | <input type="checkbox"/> Streetlamp | <input type="checkbox"/> Other: _____ |

Needs good cleaning Piles of leaves
Needing Attention:

- | | | |
|-----------------------------------|----------------------------------|---|
| <input type="checkbox"/> Damage | <input type="checkbox"/> Pothole | <input type="checkbox"/> Missing |
| <input type="checkbox"/> Painting | <input type="checkbox"/> Grass | <input type="checkbox"/> Needs Trimming |

Submitted by: James Bacchero



Borough of North Arlington
Quality of Life Report

Date: 11-27-2019

PART OF 2019 ROADWAY IMPROVEMENT

Curb all broken up MKC

Location: 115-117 Riverview Ave

Curb

Fence

Roadway

Tree

Lamp

Playground

Sidewalk

Streetlamp

Park

School

Sign

Other: _____

Needing Attention:

Damage

Painting


Pothole

Grass

Missing

Needs Trimming

Submitted by: James Beckino



Borough of North Arlington
Quality of Life Report

Date: 9-19-2019

Not needed (Visible)

MKC 12/18/19

Location: Prospect ave & Ilford ave


- | | | |
|----------------------------------|-------------------------------------|--|
| <input type="checkbox"/> Curb | <input type="checkbox"/> Lamp | <input type="checkbox"/> Park |
| <input type="checkbox"/> Fence | <input type="checkbox"/> Playground | <input type="checkbox"/> School |
| <input type="checkbox"/> Roadway | <input type="checkbox"/> Sidewalk | <input checked="" type="checkbox"/> Sign |
| <input type="checkbox"/> Tree | <input type="checkbox"/> Streetlamp | <input type="checkbox"/> Other: _____ |

Can't read sign

Needing Attention:

- | | | |
|-----------------------------------|----------------------------------|---|
| <input type="checkbox"/> Damage | <input type="checkbox"/> Pothole | <input type="checkbox"/> Missing |
| <input type="checkbox"/> Painting | <input type="checkbox"/> Grass | <input type="checkbox"/> Needs Trimming |

Submitted by: James Bochenko



Borough of North Arlington
Quality of Life Report

Date: 10-8-2019

NOT A PRIORITY MKC

N/A


Location: NFW 222 River Road replace sign
(members parking only)

- | | | |
|----------------------------------|-------------------------------------|--|
| <input type="checkbox"/> Curb | <input type="checkbox"/> Lamp | <input type="checkbox"/> Park |
| <input type="checkbox"/> Fence | <input type="checkbox"/> Playground | <input type="checkbox"/> School |
| <input type="checkbox"/> Roadway | <input type="checkbox"/> Sidewalk | <input checked="" type="checkbox"/> Sign |
| <input type="checkbox"/> Tree | <input type="checkbox"/> Streetlamp | <input type="checkbox"/> Other: _____ |

Needing Attention:

- | | | |
|-----------------------------------|----------------------------------|---|
| <input type="checkbox"/> Damage | <input type="checkbox"/> Pothole | <input type="checkbox"/> Missing |
| <input type="checkbox"/> Painting | <input type="checkbox"/> Grass | <input type="checkbox"/> Needs Trimming |

Submitted by: James V B...



BLACK TOP CREW
Keogh, Alvarado, Hoyt, Chiruti
12/18/19

Borough of North Arlington
Quality of Life Report

Date: 12-2-2019

Completed

Location: 20 Chestnut St (Pot Hole)

Curb

Lamp

Park

Fence

Playground

School

Roadway

Sidewalk

Sign

Tree

Streetlamp

Other: _____

Needing Attention:

Damage

Pothole


Missing

Painting

Grass

Needs Trimming

Submitted by: James Bacchini



Black top crew
Keosh, Hoyt, Aluotto,
Chavati
12/18/19

Borough of North Arlington
Quality of Life Report

Date: 11-4-2019

18 Forest Ave Pot Hole in Middle of Road
47 Forest Ave Pot Holes Completed, c 10

Location: 41 Argyle Pl. CAR ON TOP UNABLE TO MOVE.


Black top to be patched by crew

- | | | |
|--|-------------------------------------|---------------------------------------|
| <input checked="" type="checkbox"/> Curb | <input type="checkbox"/> Lamp | <input type="checkbox"/> Park |
| <input type="checkbox"/> Fence | <input type="checkbox"/> Playground | <input type="checkbox"/> School |
| <input type="checkbox"/> Roadway | <input type="checkbox"/> Sidewalk | <input type="checkbox"/> Sign |
| <input type="checkbox"/> Tree | <input type="checkbox"/> Streetlamp | <input type="checkbox"/> Other: _____ |

Needing Attention:

- | | | |
|-----------------------------------|---|---|
| <input type="checkbox"/> Damage | <input checked="" type="checkbox"/> Pothole | <input type="checkbox"/> Missing |
| <input type="checkbox"/> Painting | <input type="checkbox"/> Grass | <input type="checkbox"/> Needs Trimming |

Submitted by: James Becken's



Black top crew
Keash, Churati, Hart,
Ahuotto

12/18/19

Borough of North Arlington
Quality of Life Report

Date: 12-2-2019

Completed

Location: Schuyler Ave & Carrie Rd.

(Pot Hole)

Curb

Lamp

Park

Fence

Playground

School

Roadway

Sidewalk

Sign

Tree

Streetlamp

Other: _____

Needing Attention:

Damage

Pothole


Missing

Painting

Grass

Needs Trimming

Submitted by: James Boecklin



Borough of North Arlington
Quality of Life Report

Date: 11-26-2019


Location: 67 Elm St completed 12/18/19
BLACK TOP crew
Kash, Chaviti, Hoyt, Aluotto

- | | | |
|----------------------------------|-------------------------------------|---------------------------------------|
| <input type="checkbox"/> Curb | <input type="checkbox"/> Lamp | <input type="checkbox"/> Park |
| <input type="checkbox"/> Fence | <input type="checkbox"/> Playground | <input type="checkbox"/> School |
| <input type="checkbox"/> Roadway | <input type="checkbox"/> Sidewalk | <input type="checkbox"/> Sign |
| <input type="checkbox"/> Tree | <input type="checkbox"/> Streetlamp | <input type="checkbox"/> Other: _____ |

Needing Attention:

- | | | |
|-----------------------------------|---|---|
| <input type="checkbox"/> Damage | <input checked="" type="checkbox"/> Pothole | <input type="checkbox"/> Missing |
| <input type="checkbox"/> Painting | <input type="checkbox"/> Grass | <input type="checkbox"/> Needs Trimming |

Submitted by: James Berardino



Black top crew
Krosh, Churuti, Aluotto,
Hort

Borough of North Arlington

Quality of Life Report

Date: 10-29-2019

3rd
notice

Completed 12/18/19

Cleaton Pl. off Schuyler & 15 Cleaton Pl

Big Hole

Location: 95 Chestnut St

Completed 12/18/19

Curb

Lamp

Park

Fence

Playground

School

Roadway

Sidewalk

Sign

Tree

Streetlamp

Other: _____

Black top all cracks at Chestnut

Needing Attention:

Damage

Pothole


Missing

Painting

Grass

Needs Trimming

Submitted by: James Bechini



Keogh / Hoyt

12/17/19

Borough of North Arlington
Quality of Life Report

Date: 12-5-2019


Location: Forest St near Roswell School ^{REPLACED}
Sign to be replaced (curb dogs)

- | | | |
|----------------------------------|-------------------------------------|--|
| <input type="checkbox"/> Curb | <input type="checkbox"/> Lamp | <input type="checkbox"/> Park |
| <input type="checkbox"/> Fence | <input type="checkbox"/> Playground | <input type="checkbox"/> School |
| <input type="checkbox"/> Roadway | <input type="checkbox"/> Sidewalk | <input checked="" type="checkbox"/> Sign |
| <input type="checkbox"/> Tree | <input type="checkbox"/> Streetlamp | <input type="checkbox"/> Other: _____ |

Needing Attention:

- | | | |
|-----------------------------------|----------------------------------|---|
| <input type="checkbox"/> Damage | <input type="checkbox"/> Pothole | <input type="checkbox"/> Missing |
| <input type="checkbox"/> Painting | <input type="checkbox"/> Grass | <input type="checkbox"/> Needs Trimming |

Submitted by: James Boeckhno



Keogh / Hoyt

12/17/19

Borough of North Arlington
Quality of Life Report

Date: 12-5-2019

Location: Morton Place needs new stop sign
REPLACED

- | | | |
|----------------------------------|-------------------------------------|--|
| <input type="checkbox"/> Curb | <input type="checkbox"/> Lamp | <input type="checkbox"/> Park |
| <input type="checkbox"/> Fence | <input type="checkbox"/> Playground | <input type="checkbox"/> School |
| <input type="checkbox"/> Roadway | <input type="checkbox"/> Sidewalk | <input checked="" type="checkbox"/> Sign |
| <input type="checkbox"/> Tree | <input type="checkbox"/> Streetlamp | <input type="checkbox"/> Other: _____ |

Needing Attention:

- | | | |
|-----------------------------------|----------------------------------|---|
| <input type="checkbox"/> Damage | <input type="checkbox"/> Pothole | <input type="checkbox"/> Missing |
| <input type="checkbox"/> Painting | <input type="checkbox"/> Grass | <input type="checkbox"/> Needs Trimming |

Submitted by: James Becheto



Keash / Hoyt
12/17/19

Borough of North Arlington
Quality of Life Report

Date: 12-3-2019

9 Arlington Pl (sign on pole) ^{REMOVED}

Location: 10 Union Pl. (sign on pole) ^{REMOVED}

Curb

Lamp

Park

Fence

Playground

School

Roadway

Sidewalk

Sign

Tree

Streetlamp

Other: _____

Needing Attention:

Damage

Pothole


Missing

Painting

Grass

Needs Trimming

Submitted by: James Bochini



Borough of North Arlington
Quality of Life Report

Date: 12-6-2019

2ND write up P.S.E.G. VALVE SHUT-OFF
P.S.E.G. notified

Location: Crystal St & Galed St
(dip in Road)

- | | | |
|---|-------------------------------------|---------------------------------------|
| <input type="checkbox"/> Curb | <input type="checkbox"/> Lamp | <input type="checkbox"/> Park |
| <input type="checkbox"/> Fence | <input type="checkbox"/> Playground | <input type="checkbox"/> School |
| <input checked="" type="checkbox"/> Roadway | <input type="checkbox"/> Sidewalk | <input type="checkbox"/> Sign |
| <input type="checkbox"/> Tree | <input type="checkbox"/> Streetlamp | <input type="checkbox"/> Other: _____ |

Cunningham 12/10/19

Needing Attention:

- | | | |
|-----------------------------------|----------------------------------|---|
| <input type="checkbox"/> Damage | <input type="checkbox"/> Pothole | <input type="checkbox"/> Missing |
| <input type="checkbox"/> Painting | <input type="checkbox"/> Grass | <input type="checkbox"/> Needs Trimming |

Submitted by: James Boekeno



Keogh / churuti

12/9/19

Borough of North Arlington


Quality of Life Report

Date: 9/9/19



Location: 180 6th St. replace signs to Park.
6 & Albert No Park June 10-12 10 to 12
UNFOUNDED.
REPLACED

- | | | |
|----------------------------------|-------------------------------------|--|
| <input type="checkbox"/> Curb | <input type="checkbox"/> Lamp | <input type="checkbox"/> Park |
| <input type="checkbox"/> Fence | <input type="checkbox"/> Playground | <input type="checkbox"/> School |
| <input type="checkbox"/> Roadway | <input type="checkbox"/> Sidewalk | <input checked="" type="checkbox"/> Sign |
| <input type="checkbox"/> Tree | <input type="checkbox"/> Streetlamp | <input type="checkbox"/> Other: _____ |




Needing Attention:

- | | | |
|-----------------------------------|----------------------------------|---|
| <input type="checkbox"/> Damage | <input type="checkbox"/> Pothole | <input type="checkbox"/> Missing |
| <input type="checkbox"/> Painting | <input type="checkbox"/> Grass | <input type="checkbox"/> Needs Trimming |



Submitted by: James Baccarino



Borough of North Arlington

Quality of Life Report

Kesh / Churuti

12/9/19

Date:

9/10/19

Location:

64 Melrose Ave.

Curb

Lamp

Park

Fence

Playground

School

Roadway

Sidewalk

Sign

Tree

Streetlamp

Other: _____

Replace Sign Tues 10-12

NOT NEEDED AS OF NOW.

Needing Attention:

Damage

Pothole

Missing


Painting

Grass

Needs Trimming

Submitted by:

James Barkin



Borough of North Arlington

Quality of Life Report

Keash / choruti

Date: 9/10/19

Location: 10 Pulaski Dr

- Curb
- Fence
- Roadway
- Tree
- Lamp
- Playground
- Sidewalk
- Streetlamp
- Park
- School
- Sign
- Other: _____


Replace Sign No Parking Wed 1-3:30 PM

Needing Attention:

READABLE not needed at the time.

- Damage
- Painting
- Pothole
- Grass
- Missing
- Needs Trimming

Submitted by: James Boeckeris



Keogh / churuti

12/9/19

Borough of North Arlington

Quality of Life Report

Date: 9/10/19

Location: 136 Eagle Ave


- Curb
- Fence
- Roadway
- Tree
- Lamp
- Playground
- Sidewalk
- Streetlamp
- Park
- School
- Sign
- Other: _____

Replace sign Handicap RePLAcEO

Needing Attention:

- Damage
- Painting
- Pothole
- Grass
- Missing
- Needs Trimming

Submitted by: James Bacchini



Ginol coupe
12/10/19

Borough of North Arlington
Quality of Life Report

Date: 9/11/19



Location: 27 Mount St Replace sign No Parking ^{completed}
79 Locust replace sign Wed 1 to 3:30
no Parking Thurs 8 to 10 ^{completed}

- | | | |
|----------------------------------|-------------------------------------|--|
| <input type="checkbox"/> Curb | <input type="checkbox"/> Lamp | <input type="checkbox"/> Park |
| <input type="checkbox"/> Fence | <input type="checkbox"/> Playground | <input type="checkbox"/> School |
| <input type="checkbox"/> Roadway | <input type="checkbox"/> Sidewalk | <input checked="" type="checkbox"/> Sign |
| <input type="checkbox"/> Tree | <input type="checkbox"/> Streetlamp | <input type="checkbox"/> Other: _____ |



Needing Attention:

- | | | |
|-----------------------------------|----------------------------------|---|
| <input type="checkbox"/> Damage | <input type="checkbox"/> Pothole | <input type="checkbox"/> Missing |
| <input type="checkbox"/> Painting | <input type="checkbox"/> Grass | <input type="checkbox"/> Needs Trimming |

Submitted by: James Beckers



Girol coupe
12/10/19

Borough of North Arlington
Quality of Life Report

Date: 10-2-2019

Wickoff Pl & Canterbury (Replace sign ^{completes} no parking _{this side})

Location: Rivermire & Vertess Pl - (Replace sign _{Removal} hidden driveway)


- | | | |
|----------------------------------|-------------------------------------|--|
| <input type="checkbox"/> Curb | <input type="checkbox"/> Lamp | <input type="checkbox"/> Park |
| <input type="checkbox"/> Fence | <input type="checkbox"/> Playground | <input type="checkbox"/> School |
| <input type="checkbox"/> Roadway | <input type="checkbox"/> Sidewalk | <input checked="" type="checkbox"/> Sign |
| <input type="checkbox"/> Tree | <input type="checkbox"/> Streetlamp | <input type="checkbox"/> Other: _____ |

Can't Read Signs

Needing Attention:

- | | | |
|-----------------------------------|----------------------------------|---|
| <input type="checkbox"/> Damage | <input type="checkbox"/> Pothole | <input type="checkbox"/> Missing |
| <input type="checkbox"/> Painting | <input type="checkbox"/> Grass | <input type="checkbox"/> Needs Trimming |

Submitted by: James Bacchero



Keogh / Churuti
12/9/19

Borough of North Arlington
Quality of Life Report

Date: 10-9-2019

Replace Signs

Location:	<u>7 High St</u>	<u>No Park</u>	<u>Issues 1-3</u>	<u>REPLACCO</u>
	<u>96 Park ave</u>	<u>"</u>	<u>10-month</u>	<u>MAN N/A</u>
	<u>37 Elm St</u>	<u>"</u>	<u>10-month</u>	<u>MAN N/A</u>


- | | | |
|----------------------------------|-------------------------------------|--|
| <input type="checkbox"/> Curb | <input type="checkbox"/> Lamp | <input type="checkbox"/> Park |
| <input type="checkbox"/> Fence | <input type="checkbox"/> Playground | <input type="checkbox"/> School |
| <input type="checkbox"/> Roadway | <input type="checkbox"/> Sidewalk | <input checked="" type="checkbox"/> Sign |
| <input type="checkbox"/> Tree | <input type="checkbox"/> Streetlamp | <input type="checkbox"/> Other: <u>Replace</u> |

Needing Attention:

- | | | |
|-----------------------------------|----------------------------------|---|
| <input type="checkbox"/> Damage | <input type="checkbox"/> Pothole | <input type="checkbox"/> Missing |
| <input type="checkbox"/> Painting | <input type="checkbox"/> Grass | <input type="checkbox"/> Needs Trimming |

Submitted by:

James Bachino



Keogh / Churuti
12/9/19

Borough of North Arlington
Quality of Life Report

Date: 10-23-2019

OK / NA

Prospect & Sunset (cannot read Sunset)


Location: 13 Wendell Ave (Reserve Park) Sign OK
Handicap cannot read

- | | | |
|----------------------------------|-------------------------------------|--|
| <input type="checkbox"/> Curb | <input type="checkbox"/> Lamp | <input type="checkbox"/> Park |
| <input type="checkbox"/> Fence | <input type="checkbox"/> Playground | <input type="checkbox"/> School |
| <input type="checkbox"/> Roadway | <input type="checkbox"/> Sidewalk | <input checked="" type="checkbox"/> Sign |
| <input type="checkbox"/> Tree | <input type="checkbox"/> Streetlamp | <input type="checkbox"/> Other: _____ |

Needing Attention:

- | | | |
|-----------------------------------|----------------------------------|---|
| <input type="checkbox"/> Damage | <input type="checkbox"/> Pothole | <input type="checkbox"/> Missing |
| <input type="checkbox"/> Painting | <input type="checkbox"/> Grass | <input type="checkbox"/> Needs Trimming |

Submitted by: James Bocchino



Gino / coupe
12/10/19

Borough of North Arlington
Quality of Life Report

Date: 11-12-19

N/A UNFOUNDED

Location: Argyle Pl by Middle School


- | | | |
|----------------------------------|-------------------------------------|--|
| <input type="checkbox"/> Curb | <input type="checkbox"/> Lamp | <input type="checkbox"/> Park |
| <input type="checkbox"/> Fence | <input type="checkbox"/> Playground | <input type="checkbox"/> School |
| <input type="checkbox"/> Roadway | <input type="checkbox"/> Sidewalk | <input checked="" type="checkbox"/> Sign |
| <input type="checkbox"/> Tree | <input type="checkbox"/> Streetlamp | <input type="checkbox"/> Other: _____ |

replace sign 'No Parking anytime by fence

Needing Attention:

- | | | |
|-----------------------------------|----------------------------------|---|
| <input type="checkbox"/> Damage | <input type="checkbox"/> Pothole | <input type="checkbox"/> Missing |
| <input type="checkbox"/> Painting | <input type="checkbox"/> Grass | <input type="checkbox"/> Needs Trimming |

Submitted by: James Bocchino



Gina Coupe
12/10/19

Borough of North Arlington
Quality of Life Report

*Bed
Notice*

Date: 11-14-19

New sign Installed

Location: Ridge Rd & Church Pl. by bus
stop

- | | | |
|----------------------------------|-------------------------------------|--|
| <input type="checkbox"/> Curb | <input type="checkbox"/> Lamp | <input type="checkbox"/> Park |
| <input type="checkbox"/> Fence | <input type="checkbox"/> Playground | <input type="checkbox"/> School |
| <input type="checkbox"/> Roadway | <input type="checkbox"/> Sidewalk | <input checked="" type="checkbox"/> Sign |
| <input type="checkbox"/> Tree | <input type="checkbox"/> Streetlamp | <input type="checkbox"/> Other: _____ |

Can't Read sign

Needing Attention:

- | | | |
|-----------------------------------|----------------------------------|---|
| <input type="checkbox"/> Damage | <input type="checkbox"/> Pothole | <input type="checkbox"/> Missing |
| <input type="checkbox"/> Painting | <input type="checkbox"/> Grass | <input type="checkbox"/> Needs Trimming |

Submitted by: James Beckins



Borough of North Arlington
Quality of Life Report

Date: 11-21-2019

Keesh / coupe 11/26/19

Location: 22 Albert St N/A

- | | | |
|----------------------------------|-------------------------------------|--|
| <input type="checkbox"/> Curb | <input type="checkbox"/> Lamp | <input type="checkbox"/> Park |
| <input type="checkbox"/> Fence | <input type="checkbox"/> Playground | <input type="checkbox"/> School |
| <input type="checkbox"/> Roadway | <input type="checkbox"/> Sidewalk | <input checked="" type="checkbox"/> Sign |
| <input type="checkbox"/> Tree | <input type="checkbox"/> Streetlamp | <input type="checkbox"/> Other: _____ |

Sign on Pole

Needing Attention:

- | | | |
|-----------------------------------|----------------------------------|---|
| <input type="checkbox"/> Damage | <input type="checkbox"/> Pothole | <input type="checkbox"/> Missing |
| <input type="checkbox"/> Painting | <input type="checkbox"/> Grass | <input type="checkbox"/> Needs Trimming |

Submitted by: James Bocchino



Borough of North Arlington
Quality of Life Report

Date: 11-22-2019

Location: 28 Albert St N/A Repeated

- | | | |
|----------------------------------|-------------------------------------|--|
| <input type="checkbox"/> Curb | <input type="checkbox"/> Lamp | <input type="checkbox"/> Park |
| <input type="checkbox"/> Fence | <input type="checkbox"/> Playground | <input type="checkbox"/> School |
| <input type="checkbox"/> Roadway | <input type="checkbox"/> Sidewalk | <input checked="" type="checkbox"/> Sign |
| <input type="checkbox"/> Tree | <input type="checkbox"/> Streetlamp | <input type="checkbox"/> Other: _____ |

Sign on Pole

Needing Attention:

- | | | |
|-----------------------------------|----------------------------------|---|
| <input type="checkbox"/> Damage | <input type="checkbox"/> Pothole | <input type="checkbox"/> Missing |
| <input type="checkbox"/> Painting | <input type="checkbox"/> Grass | <input type="checkbox"/> Needs Trimming |

Submitted by: James Bacchini



Borough of North Arlington
Quality of Life Report

Date: 11-22-2019

Completed 11/26/19 Keosh / Coupe

Location: Keeshy Park Parking area

- | | | |
|----------------------------------|-------------------------------------|--|
| <input type="checkbox"/> Curb | <input type="checkbox"/> Lamp | <input type="checkbox"/> Park |
| <input type="checkbox"/> Fence | <input type="checkbox"/> Playground | <input type="checkbox"/> School |
| <input type="checkbox"/> Roadway | <input type="checkbox"/> Sidewalk | <input checked="" type="checkbox"/> Sign |
| <input type="checkbox"/> Tree | <input type="checkbox"/> Streetlamp | <input type="checkbox"/> Other: _____ |

Sign on Pole

Needing Attention:

- | | | |
|-----------------------------------|----------------------------------|---|
| <input type="checkbox"/> Damage | <input type="checkbox"/> Pothole | <input type="checkbox"/> Missing |
| <input type="checkbox"/> Painting | <input type="checkbox"/> Grass | <input type="checkbox"/> Needs Trimming |

Submitted by: James Beckins



Borough of North Arlington
Quality of Life Report

Date: 11-19-2019

All Basins ARE clear lateral showing = MORGAN
11/26/19

Location: Gold St + Page Clear
catch basin

- | | | |
|----------------------------------|-------------------------------------|--|
| <input type="checkbox"/> Curb | <input type="checkbox"/> Lamp | <input type="checkbox"/> Park |
| <input type="checkbox"/> Fence | <input type="checkbox"/> Playground | <input type="checkbox"/> School |
| <input type="checkbox"/> Roadway | <input type="checkbox"/> Sidewalk | <input type="checkbox"/> Sign |
| <input type="checkbox"/> Tree | <input type="checkbox"/> Streetlamp | <input type="checkbox"/> Other: <u>Catch Basin</u> |

Needing Attention:

- | | | |
|-----------------------------------|----------------------------------|---|
| <input type="checkbox"/> Damage | <input type="checkbox"/> Pothole | <input type="checkbox"/> Missing |
| <input type="checkbox"/> Painting | <input type="checkbox"/> Grass | <input type="checkbox"/> Needs Trimming |

Submitted by: James Beckert



Borough of North Arlington
Quality of Life Report

Date: 11-21-2019

Completed 10/24/19 BY DPW MKC

Location: 15 Ridge Pk. Dr.

- | | | |
|----------------------------------|-------------------------------------|--|
| <input type="checkbox"/> Curb | <input type="checkbox"/> Lamp | <input type="checkbox"/> Park |
| <input type="checkbox"/> Fence | <input type="checkbox"/> Playground | <input type="checkbox"/> School |
| <input type="checkbox"/> Roadway | <input type="checkbox"/> Sidewalk | <input checked="" type="checkbox"/> Sign |
| <input type="checkbox"/> Tree | <input type="checkbox"/> Streetlamp | <input type="checkbox"/> Other: _____ |

Replace sign no parking this side
Needing Attention:

- | | | |
|-----------------------------------|----------------------------------|---|
| <input type="checkbox"/> Damage | <input type="checkbox"/> Pothole | <input type="checkbox"/> Missing |
| <input type="checkbox"/> Painting | <input type="checkbox"/> Grass | <input type="checkbox"/> Needs Trimming |

Submitted by: James Boechino



Borough of North Arlington
Quality of Life Report

Date: 11-18-2019

P.S.E.G notified GAS VALVE BOX Sinking

Location: 78 Gold St


- | | | |
|---|-------------------------------------|---------------------------------------|
| <input type="checkbox"/> Curb | <input type="checkbox"/> Lamp | <input type="checkbox"/> Park |
| <input type="checkbox"/> Fence | <input type="checkbox"/> Playground | <input type="checkbox"/> School |
| <input checked="" type="checkbox"/> Roadway | <input type="checkbox"/> Sidewalk | <input type="checkbox"/> Sign |
| <input type="checkbox"/> Tree | <input type="checkbox"/> Streetlamp | <input type="checkbox"/> Other: _____ |

Pot Hole 2" off curb

Needing Attention:

- | | | |
|-----------------------------------|---|---|
| <input type="checkbox"/> Damage | <input checked="" type="checkbox"/> Pothole | <input type="checkbox"/> Missing |
| <input type="checkbox"/> Painting | <input type="checkbox"/> Grass | <input type="checkbox"/> Needs Trimming |

Submitted by: James Bochini



Borough of North Arlington
Quality of Life Report

Date: 11-18-2019

Location: 301 High St N/A Keosh/Coupe

- | | | |
|----------------------------------|-------------------------------------|--|
| <input type="checkbox"/> Curb | <input type="checkbox"/> Lamp | <input type="checkbox"/> Park |
| <input type="checkbox"/> Fence | <input type="checkbox"/> Playground | <input type="checkbox"/> School |
| <input type="checkbox"/> Roadway | <input type="checkbox"/> Sidewalk | <input checked="" type="checkbox"/> Sign |
| <input type="checkbox"/> Tree | <input type="checkbox"/> Streetlamp | <input type="checkbox"/> Other: _____ |

Replace sign Trees 1-3 trees

Needing Attention:

- | | | |
|-----------------------------------|----------------------------------|---|
| <input type="checkbox"/> Damage | <input type="checkbox"/> Pothole | <input type="checkbox"/> Missing |
| <input type="checkbox"/> Painting | <input type="checkbox"/> Grass | <input type="checkbox"/> Needs Trimming |

Submitted by: James Beckeno



Borough of North Arlington
Quality of Life Report

Date: 11-18-2019

Location: 2 Vespy Pl Completed 11/26/19
Keosh / coupe


- | | | |
|----------------------------------|-------------------------------------|--|
| <input type="checkbox"/> Curb | <input type="checkbox"/> Lamp | <input type="checkbox"/> Park |
| <input type="checkbox"/> Fence | <input type="checkbox"/> Playground | <input type="checkbox"/> School |
| <input type="checkbox"/> Roadway | <input type="checkbox"/> Sidewalk | <input checked="" type="checkbox"/> Sign |
| <input type="checkbox"/> Tree | <input type="checkbox"/> Streetlamp | <input type="checkbox"/> Other: _____ |

Sign off Pole

Needing Attention:

- | | | |
|-----------------------------------|----------------------------------|---|
| <input type="checkbox"/> Damage | <input type="checkbox"/> Pothole | <input type="checkbox"/> Missing |
| <input type="checkbox"/> Painting | <input type="checkbox"/> Grass | <input type="checkbox"/> Needs Trimming |

Submitted by: James B. Carlini



Borough of North Arlington
Quality of Life Report

Date: 11-13-19

P.V.W.C. Notified Sinking ROADWAY FROM Fire Hydrant

Location: Ridge Rd & Canterbury by fire
Hydrant


- | | | |
|---|-------------------------------------|---------------------------------------|
| <input type="checkbox"/> Curb | <input type="checkbox"/> Lamp | <input type="checkbox"/> Park |
| <input type="checkbox"/> Fence | <input type="checkbox"/> Playground | <input type="checkbox"/> School |
| <input checked="" type="checkbox"/> Roadway | <input type="checkbox"/> Sidewalk | <input type="checkbox"/> Sign |
| <input type="checkbox"/> Tree | <input type="checkbox"/> Streetlamp | <input type="checkbox"/> Other: _____ |

Needing Attention:

- | | | |
|-----------------------------------|---|---|
| <input type="checkbox"/> Damage | <input checked="" type="checkbox"/> Pothole | <input type="checkbox"/> Missing |
| <input type="checkbox"/> Painting | <input type="checkbox"/> Grass | <input type="checkbox"/> Needs Trimming |

Pothole

Submitted by: James Bocchiusi



2nd notice

Borough of North Arlington
Quality of Life Report

Date: 11-7-2019

52 Hedden Terr - Big dip in Road
ROADWAY NEEDS PERMANENT REPAIR PSEG. NOTIFIED.

Location: Public Parking lot off of
Belleville Pike Lot needs Repaving


- | | | |
|----------------------------------|-------------------------------------|---------------------------------------|
| <input type="checkbox"/> Curb | <input type="checkbox"/> Lamp | <input type="checkbox"/> Park |
| <input type="checkbox"/> Fence | <input type="checkbox"/> Playground | <input type="checkbox"/> School |
| <input type="checkbox"/> Roadway | <input type="checkbox"/> Sidewalk | <input type="checkbox"/> Sign |
| <input type="checkbox"/> Tree | <input type="checkbox"/> Streetlamp | <input type="checkbox"/> Other: _____ |

Needing Attention:

- | | | |
|-----------------------------------|---|---|
| <input type="checkbox"/> Damage | <input checked="" type="checkbox"/> Pothole | <input type="checkbox"/> Missing |
| <input type="checkbox"/> Painting | <input type="checkbox"/> Grass | <input type="checkbox"/> Needs Trimming |

Lots of Pot Holes

Submitted by: James Bocchino



Borough of North Arlington

Quality of Life Report

3rd notice

Date: 11-14-19

N/A MKC

Location: Cleaton Ave & Cleaton Place

Curb

Lamp

Park

Fence

Playground

School

Roadway

Sidewalk

Sign

Tree

Streetlamp

Other: _____

Needing Attention:

Damage

Pothole

Missing


Painting

Grass

Needs Trimming

Big Potholes

Submitted by: James Bacchero



Borough of North Arlington

Quality of Life Report

Date: 11-13-19

HAVE to ADDRESS w/ GABC
PROPERTY MAINT. MKC

Location: Crystal St & River Road
near junkyard


- | | | |
|----------------------------------|-------------------------------------|---------------------------------------|
| <input type="checkbox"/> Curb | <input type="checkbox"/> Lamp | <input type="checkbox"/> Park |
| <input type="checkbox"/> Fence | <input type="checkbox"/> Playground | <input type="checkbox"/> School |
| <input type="checkbox"/> Roadway | <input type="checkbox"/> Sidewalk | <input type="checkbox"/> Sign |
| <input type="checkbox"/> Tree | <input type="checkbox"/> Streetlamp | <input type="checkbox"/> Other: _____ |

Needing Attention:

- | | | |
|--|----------------------------------|---|
| <input checked="" type="checkbox"/> Damage | <input type="checkbox"/> Pothole | <input type="checkbox"/> Missing |
| <input type="checkbox"/> Painting | <input type="checkbox"/> Grass | <input type="checkbox"/> Needs Trimming |

Hundreds more repairs

Submitted by: James Bechini



Borough of North Arlington
Quality of Life Report

Date: 11-13-19

COUNTY GUARD RAIL MKC

Location: Bel Dr & Schuyler Ave


- | | | |
|----------------------------------|-------------------------------------|---------------------------------------|
| <input type="checkbox"/> Curb | <input type="checkbox"/> Lamp | <input type="checkbox"/> Park |
| <input type="checkbox"/> Fence | <input type="checkbox"/> Playground | <input type="checkbox"/> School |
| <input type="checkbox"/> Roadway | <input type="checkbox"/> Sidewalk | <input type="checkbox"/> Sign |
| <input type="checkbox"/> Tree | <input type="checkbox"/> Streetlamp | <input type="checkbox"/> Other: _____ |

Needing Attention:

- | | | |
|--|----------------------------------|---|
| <input checked="" type="checkbox"/> Damage | <input type="checkbox"/> Pothole | <input type="checkbox"/> Missing |
| <input type="checkbox"/> Painting | <input type="checkbox"/> Grass | <input type="checkbox"/> Needs Trimming |

Guard Rail

Submitted by: James Bocchino



Borough of North Arlington

Quality of Life Report

Date: 11-18-19

Done 11/14/19 Turned in last week
MKC

Location: 167 Cagle St

- | | | |
|----------------------------------|-------------------------------------|--|
| <input type="checkbox"/> Curb | <input type="checkbox"/> Lamp | <input type="checkbox"/> Park |
| <input type="checkbox"/> Fence | <input type="checkbox"/> Playground | <input type="checkbox"/> School |
| <input type="checkbox"/> Roadway | <input type="checkbox"/> Sidewalk | <input checked="" type="checkbox"/> Sign |
| <input type="checkbox"/> Tree | <input type="checkbox"/> Streetlamp | <input type="checkbox"/> Other: _____ |


Sign on Pole

Needing Attention:

- | | | |
|-----------------------------------|----------------------------------|---|
| <input type="checkbox"/> Damage | <input type="checkbox"/> Pothole | <input type="checkbox"/> Missing |
| <input type="checkbox"/> Painting | <input type="checkbox"/> Grass | <input type="checkbox"/> Needs Trimming |

Submitted by: James Bocchini

11/18/19
coupe



Borough of North Arlington
Quality of Life Report

Date: 11-7-2019

144 Eagle St (new sign) No Parking (Zone) completed

Location: 30 Susan Pl WRONG ADDRESS # 50 Sign to be completed
replaced No Parking this side Removal not needed


- | | | |
|----------------------------------|-------------------------------------|--|
| <input type="checkbox"/> Curb | <input type="checkbox"/> Lamp | <input type="checkbox"/> Park |
| <input type="checkbox"/> Fence | <input type="checkbox"/> Playground | <input type="checkbox"/> School |
| <input type="checkbox"/> Roadway | <input type="checkbox"/> Sidewalk | <input checked="" type="checkbox"/> Sign |
| <input type="checkbox"/> Tree | <input type="checkbox"/> Streetlamp | <input type="checkbox"/> Other: _____ |

Needing Attention:

- | | | |
|-----------------------------------|----------------------------------|---|
| <input type="checkbox"/> Damage | <input type="checkbox"/> Pothole | <input type="checkbox"/> Missing |
| <input type="checkbox"/> Painting | <input type="checkbox"/> Grass | <input type="checkbox"/> Needs Trimming |

Submitted by: James Becken

11/18/19 coupe



Borough of North Arlington
Quality of Life Report

Date: 11-6-2019

Near Parked Person

Need to order sign MKC

No Parking

Tues 10-noon

Location: Shields Pl.

new sign N/A

No Parking. 8-10 Tues

Curb

Lamp

Park

Fence

Playground

School

Roadway

Sidewalk

Sign

Tree

Streetlamp

Other: _____

Needing Attention:

Damage

Pothole

Missing


Painting

Grass

Needs Trimming

Submitted by: James Beckwith

COUPC 11/18/19



Borough of North Arlington
Quality of Life Report

Date: 10-1-2019

157 Ridge Rd (no parking, when snow) completed

Location: 9 Arlington Blvd (no parking anytime) completed
59 Front St (no parking anytime) can't read

- | | | |
|----------------------------------|-------------------------------------|---------------------------------------|
| <input type="checkbox"/> Curb | <input type="checkbox"/> Lamp | <input type="checkbox"/> Park |
| <input type="checkbox"/> Fence | <input type="checkbox"/> Playground | <input type="checkbox"/> School |
| <input type="checkbox"/> Roadway | <input type="checkbox"/> Sidewalk | <input type="checkbox"/> Sign |
| <input type="checkbox"/> Tree | <input type="checkbox"/> Streetlamp | <input type="checkbox"/> Other: _____ |

Replace signs can't read

Needing Attention:

- | | | |
|-----------------------------------|----------------------------------|---|
| <input type="checkbox"/> Damage | <input type="checkbox"/> Pothole | <input type="checkbox"/> Missing |
| <input type="checkbox"/> Painting | <input type="checkbox"/> Grass | <input type="checkbox"/> Needs Trimming |

Submitted by: James Beecher