

DONE.
11-14-19.
Bill Crisp

Borough of North Arlington
Quality of Life Report

Date: 11-6-2019

167 Cage St ⊗ Sign on Pole


Location: 41 Crystal St ⊗ Sign on Pole

- | | | |
|----------------------------------|-------------------------------------|--|
| <input type="checkbox"/> Curb | <input type="checkbox"/> Lamp | <input type="checkbox"/> Park |
| <input type="checkbox"/> Fence | <input type="checkbox"/> Playground | <input type="checkbox"/> School |
| <input type="checkbox"/> Roadway | <input type="checkbox"/> Sidewalk | <input checked="" type="checkbox"/> Sign |
| <input type="checkbox"/> Tree | <input type="checkbox"/> Streetlamp | <input type="checkbox"/> Other: _____ |

Needing Attention:

- | | | |
|-----------------------------------|---|---|
| <input type="checkbox"/> Damage | <input checked="" type="checkbox"/> Pothole | <input type="checkbox"/> Missing |
| <input type="checkbox"/> Painting | <input type="checkbox"/> Grass | <input type="checkbox"/> Needs Trimming |

Submitted by: James Beukens



Borough of North Arlington
Quality of Life Report

Date: 11-4-2019

157 Belmont ave AKL completed 11/13/19 coupe
139 Belmont ave


Location: 20 High Street
Signs on Pole

- | | | |
|----------------------------------|-------------------------------------|--|
| <input type="checkbox"/> Curb | <input type="checkbox"/> Lamp | <input type="checkbox"/> Park |
| <input type="checkbox"/> Fence | <input type="checkbox"/> Playground | <input type="checkbox"/> School |
| <input type="checkbox"/> Roadway | <input type="checkbox"/> Sidewalk | <input checked="" type="checkbox"/> Sign |
| <input type="checkbox"/> Tree | <input type="checkbox"/> Streetlamp | <input type="checkbox"/> Other: _____ |

Needing Attention:

- | | | |
|-----------------------------------|----------------------------------|---|
| <input type="checkbox"/> Damage | <input type="checkbox"/> Pothole | <input type="checkbox"/> Missing |
| <input type="checkbox"/> Painting | <input type="checkbox"/> Grass | <input type="checkbox"/> Needs Trimming |

Submitted by: James Buccino



Done.
11-14-19
Bill Cooper.

Borough of North Arlington
Quality of Life Report

Date: 10-22-19

172 Eagle St (sign on pole)

Location: Park Ave & Argyle (sign on pole)


18 Pershing Pl. sign on pole concrete only MKC

- | | | |
|----------------------------------|-------------------------------------|--|
| <input type="checkbox"/> Curb | <input type="checkbox"/> Lamp | <input type="checkbox"/> Park |
| <input type="checkbox"/> Fence | <input type="checkbox"/> Playground | <input type="checkbox"/> School |
| <input type="checkbox"/> Roadway | <input type="checkbox"/> Sidewalk | <input checked="" type="checkbox"/> Sign |
| <input type="checkbox"/> Tree | <input type="checkbox"/> Streetlamp | <input type="checkbox"/> Other: _____ |

Needing Attention:

- | | | |
|-----------------------------------|----------------------------------|---|
| <input type="checkbox"/> Damage | <input type="checkbox"/> Pothole | <input type="checkbox"/> Missing |
| <input type="checkbox"/> Painting | <input type="checkbox"/> Grass | <input type="checkbox"/> Needs Trimming |

Submitted by: James Boeckhins



Borough of North Arlington
Quality of Life Report

Date: 10-16-2019

P.V.W.C
Trench

62 Morgan Pl. Big dip in road


Location: Inman & Morgan Pl N/A
Pot Hole by Cattel Boxes

- | | | |
|----------------------------------|-------------------------------------|---------------------------------------|
| <input type="checkbox"/> Curb | <input type="checkbox"/> Lamp | <input type="checkbox"/> Park |
| <input type="checkbox"/> Fence | <input type="checkbox"/> Playground | <input type="checkbox"/> School |
| <input type="checkbox"/> Roadway | <input type="checkbox"/> Sidewalk | <input type="checkbox"/> Sign |
| <input type="checkbox"/> Tree | <input type="checkbox"/> Streetlamp | <input type="checkbox"/> Other: _____ |

Needing Attention:

- | | | |
|--|---|---|
| <input checked="" type="checkbox"/> Damage | <input checked="" type="checkbox"/> Pothole | <input type="checkbox"/> Missing |
| <input type="checkbox"/> Painting | <input type="checkbox"/> Grass | <input type="checkbox"/> Needs Trimming |

Submitted by: James Baschins



Borough of North Arlington
Quality of Life Report

Date:

9/25/19

ALL completed 11/13/19
COOPC

Baylen & West St

Location:

Boston & Riverside - 7 Newwood Ter
40 5th St.

Curb

Lamp

Park

Fence

Playground

School

Roadway

Sidewalk

Sign

Tree

Streetlamp

Other: _____

Signs as Paved

Needing Attention:

Damage

Pothole

Missing


Painting

Grass

Needs Trimming

Submitted by:

James Bocchini



Borough of North Arlington
Quality of Life Report

Date: 9/24/19

All completed 11/13/19 coupe

Location: 137 Belmont 143 Stover

61 Bayless 41 Bayless 37 Bayless

Curb

Lamp

Park

Fence

Playground

School

Roadway

Sidewalk

Sign

Tree

Streetlamp

Other: _____

Sign on Pole

Needing Attention:

Damage

Pothole


Missing

Painting

Grass

Needs Trimming

Submitted by: James Bocchino



Borough of North Arlington

Quality of Life Report

Date: 9/23

Ahh concrete AREA N/A MKC
CANNOT CORE DRILL / UTILITIES

Location: Union Place 10-3238

Morgan Pl & Belleville Pl - 17 Rutherford Pl


- | | | |
|----------------------------------|-------------------------------------|--|
| <input type="checkbox"/> Curb | <input type="checkbox"/> Lamp | <input type="checkbox"/> Park |
| <input type="checkbox"/> Fence | <input type="checkbox"/> Playground | <input type="checkbox"/> School |
| <input type="checkbox"/> Roadway | <input type="checkbox"/> Sidewalk | <input checked="" type="checkbox"/> Sign |
| <input type="checkbox"/> Tree | <input type="checkbox"/> Streetlamp | <input type="checkbox"/> Other: _____ |

Sign on Pole

Needing Attention:

- | | | |
|-----------------------------------|----------------------------------|---|
| <input type="checkbox"/> Damage | <input type="checkbox"/> Pothole | <input type="checkbox"/> Missing |
| <input type="checkbox"/> Painting | <input type="checkbox"/> Grass | <input type="checkbox"/> Needs Trimming |

Submitted by: JAMES BOCCINO



Borough of North Arlington
Quality of Life Report

Date: 9-19-2019

ROADWAYS ON LIST
FOR REPAIRS 2020, 2021

Location: 66-74 depin road Heddare
90 & 103 Belmont Ave


- | | | |
|---|-------------------------------------|---------------------------------------|
| <input type="checkbox"/> Curb | <input type="checkbox"/> Lamp | <input type="checkbox"/> Park |
| <input type="checkbox"/> Fence | <input type="checkbox"/> Playground | <input type="checkbox"/> School |
| <input checked="" type="checkbox"/> Roadway | <input type="checkbox"/> Sidewalk | <input type="checkbox"/> Sign |
| <input type="checkbox"/> Tree | <input type="checkbox"/> Streetlamp | <input type="checkbox"/> Other: _____ |

Heddare - depin Road Belmont Pot holes

Needing Attention:

- | | | |
|-----------------------------------|---|---|
| <input type="checkbox"/> Damage | <input checked="" type="checkbox"/> Pothole | <input type="checkbox"/> Missing |
| <input type="checkbox"/> Painting | <input type="checkbox"/> Grass | <input type="checkbox"/> Needs Trimming |

Submitted by: James Boehm



Borough of North Arlington
Quality of Life Report

*3rd
Notice*

Date: 9/10/19


Location: 268P Parking lot @ Ridge Rd replace sign
by traffic light Can't Read (no parking rules
seen)

- | | | |
|----------------------------------|-------------------------------------|--|
| <input type="checkbox"/> Curb | <input type="checkbox"/> Lamp | <input type="checkbox"/> Park |
| <input type="checkbox"/> Fence | <input type="checkbox"/> Playground | <input type="checkbox"/> School |
| <input type="checkbox"/> Roadway | <input type="checkbox"/> Sidewalk | <input checked="" type="checkbox"/> Sign |
| <input type="checkbox"/> Tree | <input type="checkbox"/> Streetlamp | <input type="checkbox"/> Other: _____ |

Needing Attention:

- | | | |
|-----------------------------------|----------------------------------|---|
| <input type="checkbox"/> Damage | <input type="checkbox"/> Pothole | <input type="checkbox"/> Missing |
| <input type="checkbox"/> Painting | <input type="checkbox"/> Grass | <input type="checkbox"/> Needs Trimming |

Submitted by: James Bochner



Borough of North Arlington
Quality of Life Report

Date: 7/17/19

NO CURB work
Scheduled

Location: Elm St dead-end

- | | | |
|--|-------------------------------------|---------------------------------------|
| <input checked="" type="checkbox"/> Curb | <input type="checkbox"/> Lamp | <input type="checkbox"/> Park |
| <input type="checkbox"/> Fence | <input type="checkbox"/> Playground | <input type="checkbox"/> School |
| <input type="checkbox"/> Roadway | <input type="checkbox"/> Sidewalk | <input type="checkbox"/> Sign |
| <input type="checkbox"/> Tree | <input type="checkbox"/> Streetlamp | <input type="checkbox"/> Other: _____ |


Curb needs to be patched

Needing Attention:

- | | | |
|-----------------------------------|----------------------------------|--|
| <input type="checkbox"/> Damage | <input type="checkbox"/> Pothole | <input type="checkbox"/> Missing |
| <input type="checkbox"/> Painting | <input type="checkbox"/> Grass | <input checked="" type="checkbox"/> Needs Trimming |

Answer

Submitted by: James Becheris



Borough of North Arlington
Quality of Life Report

Date: 10-29-2019

62 Melissa ave. Pit Hole in middle of Road


Location: 81 Third St Big Pit Hole completed in Oct. 2019

- | | | |
|----------------------------------|-------------------------------------|---------------------------------------|
| <input type="checkbox"/> Curb | <input type="checkbox"/> Lamp | <input type="checkbox"/> Park |
| <input type="checkbox"/> Fence | <input type="checkbox"/> Playground | <input type="checkbox"/> School |
| <input type="checkbox"/> Roadway | <input type="checkbox"/> Sidewalk | <input type="checkbox"/> Sign |
| <input type="checkbox"/> Tree | <input type="checkbox"/> Streetlamp | <input type="checkbox"/> Other: _____ |

Needing Attention:

- | | | |
|-----------------------------------|---|---|
| <input type="checkbox"/> Damage | <input checked="" type="checkbox"/> Pothole | <input type="checkbox"/> Missing |
| <input type="checkbox"/> Painting | <input type="checkbox"/> Grass | <input type="checkbox"/> Needs Trimming |

Submitted by: James Bocchino



Borough of North Arlington
Quality of Life Report

Date: 10-30-2019

Median at 47 + 48 - 74-75 bottom of sign
can't read (Speed Bump)

Location: 61 Boston Post Hall completed in oct
2019

- | | | |
|----------------------------------|-------------------------------------|--|
| <input type="checkbox"/> Curb | <input type="checkbox"/> Lamp | <input type="checkbox"/> Park |
| <input type="checkbox"/> Fence | <input type="checkbox"/> Playground | <input type="checkbox"/> School |
| <input type="checkbox"/> Roadway | <input type="checkbox"/> Sidewalk | <input checked="" type="checkbox"/> Sign |
| <input type="checkbox"/> Tree | <input type="checkbox"/> Streetlamp | <input type="checkbox"/> Other: _____ |

Needing Attention:

- | | | |
|-----------------------------------|---|---|
| <input type="checkbox"/> Damage | <input checked="" type="checkbox"/> Pothole | <input type="checkbox"/> Missing |
| <input type="checkbox"/> Painting | <input type="checkbox"/> Grass | <input type="checkbox"/> Needs Trimming |

Submitted by: James Beckwith



STEVE
BOROUGH ADMIN

Borough of North Arlington

Quality of Life Report

DONE EVERY 2-3
WEEKS DURING
GROWING SEASON

Date: 10-28-2019

Prescott St at end by Belleville pipe
clean up

Location: West End of Mercedes Rd

- | | | |
|---|-------------------------------------|---------------------------------------|
| <input type="checkbox"/> Curb | <input type="checkbox"/> Lamp | <input type="checkbox"/> Park |
| <input type="checkbox"/> Fence | <input type="checkbox"/> Playground | <input type="checkbox"/> School |
| <input checked="" type="checkbox"/> Roadway | <input type="checkbox"/> Sidewalk | <input type="checkbox"/> Sign |
| <input type="checkbox"/> Tree | <input type="checkbox"/> Streetlamp | <input type="checkbox"/> Other: _____ |

Needing Attention:

- | | | |
|-----------------------------------|----------------------------------|--|
| <input type="checkbox"/> Damage | <input type="checkbox"/> Pothole | <input type="checkbox"/> Missing |
| <input type="checkbox"/> Painting | <input type="checkbox"/> Grass | <input checked="" type="checkbox"/> Needs Trimming |

Clean up

Submitted by: James Burchins

579
600



Borough of North Arlington
Quality of Life Report

Date: 9/9/19

Location: 44 & 10 Street NO LOCATION GIVEN
MKC


- | | | |
|----------------------------------|-------------------------------------|--|
| <input type="checkbox"/> Curb | <input type="checkbox"/> Lamp | <input type="checkbox"/> Park |
| <input type="checkbox"/> Fence | <input type="checkbox"/> Playground | <input type="checkbox"/> School |
| <input type="checkbox"/> Roadway | <input type="checkbox"/> Sidewalk | <input checked="" type="checkbox"/> Sign |
| <input type="checkbox"/> Tree | <input type="checkbox"/> Streetlamp | <input type="checkbox"/> Other: _____ |

Replace sign no parking this side

Needing Attention:

- | | | |
|-----------------------------------|----------------------------------|---|
| <input type="checkbox"/> Damage | <input type="checkbox"/> Pothole | <input type="checkbox"/> Missing |
| <input type="checkbox"/> Painting | <input type="checkbox"/> Grass | <input type="checkbox"/> Needs Trimming |

Submitted by: James Boskovic



Borough of North Arlington
Quality of Life Report

Date: 10-24

* 20 Wood repl signs (no Park 10-noon) Trees ^{NCG.}


Location: Mary Resignole PK (replace signs) ^{ORDERED FROM INFINIT.}

- | | | |
|----------------------------------|-------------------------------------|--|
| <input type="checkbox"/> Curb | <input type="checkbox"/> Lamp | <input type="checkbox"/> Park |
| <input type="checkbox"/> Fence | <input type="checkbox"/> Playground | <input type="checkbox"/> School |
| <input type="checkbox"/> Roadway | <input type="checkbox"/> Sidewalk | <input checked="" type="checkbox"/> Sign |
| <input type="checkbox"/> Tree | <input type="checkbox"/> Streetlamp | <input type="checkbox"/> Other: _____ |

Needing Attention:

- | | | |
|-----------------------------------|----------------------------------|---|
| <input type="checkbox"/> Damage | <input type="checkbox"/> Pothole | <input type="checkbox"/> Missing |
| <input type="checkbox"/> Painting | <input type="checkbox"/> Grass | <input type="checkbox"/> Needs Trimming |

Submitted by: James Becking



Completed
B. coupe

Borough of North Arlington
Quality of Life Report

Date: 10-21-2019

253 Crystal St replace sign No Park ✓
8-10

Location: 22 Devon St ✓ replace sign
10-12 noon Tues
Need New Signs

- | | | |
|----------------------------------|-------------------------------------|--|
| <input type="checkbox"/> Curb | <input type="checkbox"/> Lamp | <input type="checkbox"/> Park |
| <input type="checkbox"/> Fence | <input type="checkbox"/> Playground | <input type="checkbox"/> School |
| <input type="checkbox"/> Roadway | <input type="checkbox"/> Sidewalk | <input checked="" type="checkbox"/> Sign |
| <input type="checkbox"/> Tree | <input type="checkbox"/> Streetlamp | <input type="checkbox"/> Other: _____ |

Needing Attention:

- | | | |
|-----------------------------------|----------------------------------|---|
| <input type="checkbox"/> Damage | <input type="checkbox"/> Pothole | <input type="checkbox"/> Missing |
| <input type="checkbox"/> Painting | <input type="checkbox"/> Grass | <input type="checkbox"/> Needs Trimming |

Submitted by: James Bocchino



Completed
B. coupe

Borough of North Arlington
Quality of Life Report

Date: 10-22-2019

165 ad. Blvd Reppign No Park 1-3 Mon ✓

Location: 147 Melrose replace sign ✓
no Park 1072 - Mon


- | | | |
|----------------------------------|-------------------------------------|---------------------------------------|
| <input type="checkbox"/> Curb | <input type="checkbox"/> Lamp | <input type="checkbox"/> Park |
| <input type="checkbox"/> Fence | <input type="checkbox"/> Playground | <input type="checkbox"/> School |
| <input type="checkbox"/> Roadway | <input type="checkbox"/> Sidewalk | <input type="checkbox"/> Sign |
| <input type="checkbox"/> Tree | <input type="checkbox"/> Streetlamp | <input type="checkbox"/> Other: _____ |

Needing Attention:

- | | | |
|-----------------------------------|----------------------------------|---|
| <input type="checkbox"/> Damage | <input type="checkbox"/> Pothole | <input type="checkbox"/> Missing |
| <input type="checkbox"/> Painting | <input type="checkbox"/> Grass | <input type="checkbox"/> Needs Trimming |

Submitted by: James Bocchino

Completed
B. Coupe



Borough of North Arlington
Quality of Life Report

Date: 10-10-219

Foster & Menard Pl (Reference to Park 8 to 10 Tues)


Location: 37 Larrigan Pl (Handicap sign on Pole) N/A

- | | | |
|----------------------------------|-------------------------------------|--|
| <input type="checkbox"/> Curb | <input type="checkbox"/> Lamp | <input type="checkbox"/> Park |
| <input type="checkbox"/> Fence | <input type="checkbox"/> Playground | <input type="checkbox"/> School |
| <input type="checkbox"/> Roadway | <input type="checkbox"/> Sidewalk | <input checked="" type="checkbox"/> Sign |
| <input type="checkbox"/> Tree | <input type="checkbox"/> Streetlamp | <input type="checkbox"/> Other: _____ |

Needing Attention:

- | | | |
|-----------------------------------|----------------------------------|---|
| <input type="checkbox"/> Damage | <input type="checkbox"/> Pothole | <input type="checkbox"/> Missing |
| <input type="checkbox"/> Painting | <input type="checkbox"/> Grass | <input type="checkbox"/> Needs Trimming |

Submitted by: James Beckwith



coupc / churuti

Borough of North Arlington
Quality of Life Report

Date: 10-21-2019

10/29/19

Chestnut & Elox Clear patrol base

Done

Location: 122 Ridge Rd (meadow sidewalk) N/A

- | | | |
|----------------------------------|-------------------------------------|---------------------------------------|
| <input type="checkbox"/> Curb | <input type="checkbox"/> Lamp | <input type="checkbox"/> Park |
| <input type="checkbox"/> Fence | <input type="checkbox"/> Playground | <input type="checkbox"/> School |
| <input type="checkbox"/> Roadway | <input type="checkbox"/> Sidewalk | <input type="checkbox"/> Sign |
| <input type="checkbox"/> Tree | <input type="checkbox"/> Streetlamp | <input type="checkbox"/> Other: _____ |


Needing Attention:

- | | | |
|-----------------------------------|---|--|
| <input type="checkbox"/> Damage | <input type="checkbox"/> Pothole | <input type="checkbox"/> Missing |
| <input type="checkbox"/> Painting | <input checked="" type="checkbox"/> Grass | <input checked="" type="checkbox"/> Needs Trimming |

Clear weeds on sidewalk

Submitted by: James Boschen

couple church



Borough of North Arlington
Quality of Life Report

10/29/19

Date: 10-23-2019

Luster Pl No Park Replace Sign 8-10 Tues

REPLACES
Done

Location: 98 Park ave Replace Sign

REPLACES

No Park Thurs - 10 to noon
TUE


- | | | |
|----------------------------------|-------------------------------------|--|
| <input type="checkbox"/> Curb | <input type="checkbox"/> Lamp | <input type="checkbox"/> Park |
| <input type="checkbox"/> Fence | <input type="checkbox"/> Playground | <input type="checkbox"/> School |
| <input type="checkbox"/> Roadway | <input type="checkbox"/> Sidewalk | <input checked="" type="checkbox"/> Sign |
| <input type="checkbox"/> Tree | <input type="checkbox"/> Streetlamp | <input type="checkbox"/> Other: _____ |

Needing Attention:

- | | | |
|-----------------------------------|----------------------------------|---|
| <input type="checkbox"/> Damage | <input type="checkbox"/> Pothole | <input type="checkbox"/> Missing |
| <input type="checkbox"/> Painting | <input type="checkbox"/> Grass | <input type="checkbox"/> Needs Trimming |

Submitted by: James Bocchini

coupe / churuti



Borough of North Arlington

Quality of Life Report

Date: 10-1-2019

165 Ridge Rd (can't read sign no parking when snow is covered)

RePLAcED

Done

Location: 71 Argyle Pl (can't read sign (no Park 10-12 - Mon))

RePLAcED

Done

- | | | |
|----------------------------------|-------------------------------------|--|
| <input type="checkbox"/> Curb | <input type="checkbox"/> Lamp | <input type="checkbox"/> Park |
| <input type="checkbox"/> Fence | <input type="checkbox"/> Playground | <input type="checkbox"/> School |
| <input type="checkbox"/> Roadway | <input type="checkbox"/> Sidewalk | <input checked="" type="checkbox"/> Sign |
| <input type="checkbox"/> Tree | <input type="checkbox"/> Streetlamp | <input type="checkbox"/> Other: _____ |


Can't read signs

Needing Attention:

- | | | |
|-----------------------------------|----------------------------------|---|
| <input type="checkbox"/> Damage | <input type="checkbox"/> Pothole | <input type="checkbox"/> Missing |
| <input type="checkbox"/> Painting | <input type="checkbox"/> Grass | <input type="checkbox"/> Needs Trimming |

Submitted by: James Boakins

couple churuti



Borough of North Arlington
Quality of Life Report

Date: 9/23

Location: Journey & Merrill St 10/29/19
175 Journey 43 Journey 49 Journey Done

- | | | |
|----------------------------------|-------------------------------------|--|
| <input type="checkbox"/> Curb | <input type="checkbox"/> Lamp | <input type="checkbox"/> Park |
| <input type="checkbox"/> Fence | <input type="checkbox"/> Playground | <input type="checkbox"/> School |
| <input type="checkbox"/> Roadway | <input type="checkbox"/> Sidewalk | <input checked="" type="checkbox"/> Sign |
| <input type="checkbox"/> Tree | <input type="checkbox"/> Streetlamp | <input type="checkbox"/> Other: _____ |

Signs on Poles

Needing Attention:

- | | | |
|-----------------------------------|----------------------------------|---|
| <input type="checkbox"/> Damage | <input type="checkbox"/> Pothole | <input type="checkbox"/> Missing |
| <input type="checkbox"/> Painting | <input type="checkbox"/> Grass | <input type="checkbox"/> Needs Trimming |

Submitted by: James Brecken