

Completed
over the Summer
1st Request

Borough of North Arlington
Quality of Life Report

Date: 10-15-2019

2nd
Notice


Location: Chestnut St dead-end Clean up

- | | | |
|----------------------------------|-------------------------------------|---------------------------------------|
| <input type="checkbox"/> Curb | <input type="checkbox"/> Lamp | <input type="checkbox"/> Park |
| <input type="checkbox"/> Fence | <input type="checkbox"/> Playground | <input type="checkbox"/> School |
| <input type="checkbox"/> Roadway | <input type="checkbox"/> Sidewalk | <input type="checkbox"/> Sign |
| <input type="checkbox"/> Tree | <input type="checkbox"/> Streetlamp | <input type="checkbox"/> Other: _____ |

Needing Attention:

- | | | |
|-----------------------------------|----------------------------------|--|
| <input type="checkbox"/> Damage | <input type="checkbox"/> Pothole | <input type="checkbox"/> Missing |
| <input type="checkbox"/> Painting | <input type="checkbox"/> Grass | <input checked="" type="checkbox"/> Needs Trimming |

Submitted by: James Bacchenis



Borough of North Arlington
Quality of Life Report

Date: 10-17-2019

1st Boston Pat Hole completed 10/21


Location: 18 James Pl Pat Hole (2nd notice middle of road)
PVWC | Repair temporary
DPW 10/21

- | | | |
|----------------------------------|-------------------------------------|---------------------------------------|
| <input type="checkbox"/> Curb | <input type="checkbox"/> Lamp | <input type="checkbox"/> Park |
| <input type="checkbox"/> Fence | <input type="checkbox"/> Playground | <input type="checkbox"/> School |
| <input type="checkbox"/> Roadway | <input type="checkbox"/> Sidewalk | <input type="checkbox"/> Sign |
| <input type="checkbox"/> Tree | <input type="checkbox"/> Streetlamp | <input type="checkbox"/> Other: _____ |

Needing Attention:

- | | | |
|-----------------------------------|---|---|
| <input type="checkbox"/> Damage | <input checked="" type="checkbox"/> Pothole | <input type="checkbox"/> Missing |
| <input type="checkbox"/> Painting | <input type="checkbox"/> Grass | <input type="checkbox"/> Needs Trimming |

Submitted by: James Boccherio



Borough of North Arlington

Quality of Life Report

Date: 9/25/19

Completed over
summer

Location: West End of Chestnut
& Herald Rd (deadend)


- | | | |
|----------------------------------|-------------------------------------|--|
| <input type="checkbox"/> Curb | <input type="checkbox"/> Lamp | <input type="checkbox"/> Park |
| <input type="checkbox"/> Fence | <input type="checkbox"/> Playground | <input type="checkbox"/> School |
| <input type="checkbox"/> Roadway | <input type="checkbox"/> Sidewalk | <input checked="" type="checkbox"/> Sign |
| <input type="checkbox"/> Tree | <input type="checkbox"/> Streetlamp | <input type="checkbox"/> Other: _____ |

Needs yard cleaning up

Needing Attention:

- | | | |
|-----------------------------------|----------------------------------|--|
| <input type="checkbox"/> Damage | <input type="checkbox"/> Pothole | <input type="checkbox"/> Missing |
| <input type="checkbox"/> Painting | <input type="checkbox"/> Grass | <input checked="" type="checkbox"/> Needs Trimming |

Submitted by: James Boccheri



Borough of North Arlington

Quality of Life Report

Date: 9-16-19

Clean Every 2 months DPW
Weed control Bergen county
ROADS

Location: Deluzo Ave - from Soccer field
to Disposal Road


- | | | |
|----------------------------------|-------------------------------------|---|
| <input type="checkbox"/> Curb | <input type="checkbox"/> Lamp | <input type="checkbox"/> Park |
| <input type="checkbox"/> Fence | <input type="checkbox"/> Playground | <input type="checkbox"/> School |
| <input type="checkbox"/> Roadway | <input type="checkbox"/> Sidewalk | <input type="checkbox"/> Sign |
| <input type="checkbox"/> Tree | <input type="checkbox"/> Streetlamp | <input type="checkbox"/> Other: <u>Guard Rail</u> |

Clean all along Guard Rail

Needing Attention:

- | | | |
|-----------------------------------|----------------------------------|--|
| <input type="checkbox"/> Damage | <input type="checkbox"/> Pothole | <input type="checkbox"/> Missing |
| <input type="checkbox"/> Painting | <input type="checkbox"/> Grass | <input checked="" type="checkbox"/> Needs Trimming |

Submitted by: James Bocchino



Borough of North Arlington
Quality of Life Report

*2nd
notice*

Date: 9-16-19

Location: 6 Sylvia Pl. & 81 Third St
by curb & big holes

Completed
10/21


- | | | |
|----------------------------------|-------------------------------------|---------------------------------------|
| <input type="checkbox"/> Curb | <input type="checkbox"/> Lamp | <input type="checkbox"/> Park |
| <input type="checkbox"/> Fence | <input type="checkbox"/> Playground | <input type="checkbox"/> School |
| <input type="checkbox"/> Roadway | <input type="checkbox"/> Sidewalk | <input type="checkbox"/> Sign |
| <input type="checkbox"/> Tree | <input type="checkbox"/> Streetlamp | <input type="checkbox"/> Other: _____ |

Needing Attention:

- | | | |
|-----------------------------------|---|---|
| <input type="checkbox"/> Damage | <input checked="" type="checkbox"/> Pothole | <input type="checkbox"/> Missing |
| <input type="checkbox"/> Painting | <input type="checkbox"/> Grass | <input type="checkbox"/> Needs Trimming |

Big Pot Hole in street

Submitted by: James Bochner



Borough of North Arlington
Quality of Life Report

Date: 9-17-2019

Location: Dead End of 5th Street
Completed Every 2-3 weeks

- | | | |
|----------------------------------|-------------------------------------|---------------------------------------|
| <input type="checkbox"/> Curb | <input type="checkbox"/> Lamp | <input type="checkbox"/> Park |
| <input type="checkbox"/> Fence | <input type="checkbox"/> Playground | <input type="checkbox"/> School |
| <input type="checkbox"/> Roadway | <input type="checkbox"/> Sidewalk | <input type="checkbox"/> Sign |
| <input type="checkbox"/> Tree | <input type="checkbox"/> Streetlamp | <input type="checkbox"/> Other: _____ |

Needing Attention:

- | | | |
|-----------------------------------|----------------------------------|--|
| <input type="checkbox"/> Damage | <input type="checkbox"/> Pothole | <input type="checkbox"/> Missing |
| <input type="checkbox"/> Painting | <input type="checkbox"/> Grass | <input checked="" type="checkbox"/> Needs Trimming |

needs good clean up

Submitted by: James Bochner



Borough of North Arlington
Quality of Life Report

Date: 10-7-2019

No Sign Available

4 astor ave (replace sign) ~~1-3:30~~ No Parking

Location: 15 Ridge ^{Completed} Park Dr. (replace sign) No Parking this side ✓

- | | | |
|----------------------------------|-------------------------------------|--|
| <input type="checkbox"/> Curb | <input type="checkbox"/> Lamp | <input type="checkbox"/> Park |
| <input type="checkbox"/> Fence | <input type="checkbox"/> Playground | <input type="checkbox"/> School |
| <input type="checkbox"/> Roadway | <input type="checkbox"/> Sidewalk | <input checked="" type="checkbox"/> Sign |
| <input type="checkbox"/> Tree | <input type="checkbox"/> Streetlamp | <input type="checkbox"/> Other: <u>Replace</u> |

Needing Attention:

- | | | |
|-----------------------------------|----------------------------------|---|
| <input type="checkbox"/> Damage | <input type="checkbox"/> Pothole | <input type="checkbox"/> Missing |
| <input type="checkbox"/> Painting | <input type="checkbox"/> Grass | <input type="checkbox"/> Needs Trimming |

Submitted by: James Boucherio

T. Churuti
C. Hoyt
10/29/19



Borough of North Arlington
Quality of Life Report

Date: 10-14-2019

193 Ridge Road replace sign (no parking here to cover) ✓

Location: Isxchel Ave & Rivier Road sign too low ✓
completed

- | | | |
|----------------------------------|-------------------------------------|--|
| <input type="checkbox"/> Curb | <input type="checkbox"/> Lamp | <input type="checkbox"/> Park |
| <input type="checkbox"/> Fence | <input type="checkbox"/> Playground | <input type="checkbox"/> School |
| <input type="checkbox"/> Roadway | <input type="checkbox"/> Sidewalk | <input checked="" type="checkbox"/> Sign |
| <input type="checkbox"/> Tree | <input type="checkbox"/> Streetlamp | <input type="checkbox"/> Other: _____ |

Needing Attention:

- | | | |
|-----------------------------------|----------------------------------|---|
| <input type="checkbox"/> Damage | <input type="checkbox"/> Pothole | <input type="checkbox"/> Missing |
| <input type="checkbox"/> Painting | <input type="checkbox"/> Grass | <input type="checkbox"/> Needs Trimming |

Submitted by: James Bacchini

T. Churuti
C. Hoyt
10/24/19



Borough of North Arlington
Quality of Life Report

Date: 10/14/2019

9 orl Blvd near Church sign replaced Done
Arkingston No Parking Anytime
Here to corner

Location: 4 Astor ave new sign
no Park Wed 1 to 3:30 NO SIGN
AVAILABLE

- | | | |
|----------------------------------|-------------------------------------|--|
| <input type="checkbox"/> Curb | <input type="checkbox"/> Lamp | <input type="checkbox"/> Park |
| <input type="checkbox"/> Fence | <input type="checkbox"/> Playground | <input type="checkbox"/> School |
| <input type="checkbox"/> Roadway | <input type="checkbox"/> Sidewalk | <input checked="" type="checkbox"/> Sign |
| <input type="checkbox"/> Tree | <input type="checkbox"/> Streetlamp | <input type="checkbox"/> Other: _____ |

Needing Attention:

- | | | |
|-----------------------------------|----------------------------------|---|
| <input type="checkbox"/> Damage | <input type="checkbox"/> Pothole | <input type="checkbox"/> Missing |
| <input type="checkbox"/> Painting | <input type="checkbox"/> Grass | <input type="checkbox"/> Needs Trimming |

Submitted by: James Bacchinis

T. Churuti
C. Hoyt
10/24/19



Borough of North Arlington
Quality of Life Report

Date: 10-7-19

Location: 143 Atsnee / ^{No Area to Set pole} Secret ave / ^{No Area to Set pole} Dept of Baltimore
Done

- Curb
- Fence
- Roadway
- Tree
- Lamp
- Playground
- Sidewalk
- Streetlamp
- Park
- School
- Sign
- Other: _____

Sign on Pole Take-off

Needing Attention:

- Damage
- Painting
- Pothole
- Grass
- Missing
- Needs Trimming

Submitted by: James Baccino

TChurutz
C Hoyt
10/24/19



Borough of North Arlington
Quality of Life Report

Date: 10-15-2019

Unfounded - 180 Prospect Ave Sign on Pole?
No pole in front of property

Location: 106 Rutherford Pl. Sign on Pole Completed ✓

- | | | |
|----------------------------------|-------------------------------------|--|
| <input type="checkbox"/> Curb | <input type="checkbox"/> Lamp | <input type="checkbox"/> Park |
| <input type="checkbox"/> Fence | <input type="checkbox"/> Playground | <input type="checkbox"/> School |
| <input type="checkbox"/> Roadway | <input type="checkbox"/> Sidewalk | <input checked="" type="checkbox"/> Sign |
| <input type="checkbox"/> Tree | <input type="checkbox"/> Streetlamp | <input type="checkbox"/> Other: _____ |

Needing Attention:

- | | | |
|-----------------------------------|----------------------------------|---|
| <input type="checkbox"/> Damage | <input type="checkbox"/> Pothole | <input type="checkbox"/> Missing |
| <input type="checkbox"/> Painting | <input type="checkbox"/> Grass | <input type="checkbox"/> Needs Trimming |

Submitted by: James Boschini

T. Churuti
C. Hoyt
10/24/19



Borough of North Arlington
Quality of Life Report

Date: 10-8-2019

Location:

202 Baltimore Ave / 101 Boston Ave
202 Prospect Ave No Parking 10 to noon

Curb

Lamp

Park

Fence

Playground

School

Roadway

Sidewalk

Sign

Tree

Streetlamp

Other: Takeoff

Sign on Pole

Needing Attention:

Damage

Pothole

Missing

Painting


Grass

Needs Trimming

Submitted by:

James Boachino

Completed
T. Churuti
C. Hoyt
10/24/19



Borough of North Arlington
Quality of Life Report

completes
couple
or
Alotto
10/24/19

Date: 9/26/20

40 5th St. 104 Rutterford Pl.

Location: Prospect & Hendel

Ridge Road by H & B 2 signs on Pole

could - with do - (D)

N/A


- | | | |
|----------------------------------|-------------------------------------|--|
| <input type="checkbox"/> Curb | <input type="checkbox"/> Lamp | <input type="checkbox"/> Park |
| <input type="checkbox"/> Fence | <input type="checkbox"/> Playground | <input type="checkbox"/> School |
| <input type="checkbox"/> Roadway | <input type="checkbox"/> Sidewalk | <input checked="" type="checkbox"/> Sign |
| <input type="checkbox"/> Tree | <input type="checkbox"/> Streetlamp | <input type="checkbox"/> Other: _____ |

Signs on Poles

Needing Attention:

- | | | |
|-----------------------------------|----------------------------------|---|
| <input type="checkbox"/> Damage | <input type="checkbox"/> Pothole | <input type="checkbox"/> Missing |
| <input type="checkbox"/> Painting | <input type="checkbox"/> Grass | <input type="checkbox"/> Needs Trimming |

Submitted by: James Boachino



Completed
coupe
Aluotto
10/24/19

Borough of North Arlington
Quality of Life Report

Date: 10-3-2019

Location: 15 Tunnell St / 19 Bayle ave / 11 Bayle ave
106 Stevens Pl


- | | | |
|----------------------------------|-------------------------------------|--|
| <input type="checkbox"/> Curb | <input type="checkbox"/> Lamp | <input type="checkbox"/> Park |
| <input type="checkbox"/> Fence | <input type="checkbox"/> Playground | <input type="checkbox"/> School |
| <input type="checkbox"/> Roadway | <input type="checkbox"/> Sidewalk | <input checked="" type="checkbox"/> Sign |
| <input type="checkbox"/> Tree | <input type="checkbox"/> Streetlamp | <input type="checkbox"/> Other: _____ |

Needing Attention:

- | | | |
|-----------------------------------|----------------------------------|---|
| <input type="checkbox"/> Damage | <input type="checkbox"/> Pothole | <input type="checkbox"/> Missing |
| <input type="checkbox"/> Painting | <input type="checkbox"/> Grass | <input type="checkbox"/> Needs Trimming |

Remove sign on Pote Pole

Submitted by: James Bocchini



Donny
10-24-19

COUPE 10/24/19
Ahuotto

Borough of North Arlington
Quality of Life Report

Date: 9/24/19

Location: 127-B & 13A Jason Way
101-B Jason Way


- | | | |
|----------------------------------|-------------------------------------|--|
| <input type="checkbox"/> Curb | <input type="checkbox"/> Lamp | <input type="checkbox"/> Park |
| <input type="checkbox"/> Fence | <input type="checkbox"/> Playground | <input type="checkbox"/> School |
| <input type="checkbox"/> Roadway | <input type="checkbox"/> Sidewalk | <input checked="" type="checkbox"/> Sign |
| <input type="checkbox"/> Tree | <input type="checkbox"/> Streetlamp | <input type="checkbox"/> Other: _____ |

Sign on Pole

Needing Attention:

- | | | |
|-----------------------------------|----------------------------------|---|
| <input type="checkbox"/> Damage | <input type="checkbox"/> Pothole | <input type="checkbox"/> Missing |
| <input type="checkbox"/> Painting | <input type="checkbox"/> Grass | <input type="checkbox"/> Needs Trimming |

Submitted by: James Buckert



DONE
10-24-19

coupe
ALUO HU 10/24/19

Borough of North Arlington
Quality of Life Report

Date: 9-30-2019

Location: 15 Hth St - 20 High St - 6th St 110-120-185


- | | | |
|----------------------------------|-------------------------------------|--|
| <input type="checkbox"/> Curb | <input type="checkbox"/> Lamp | <input type="checkbox"/> Park |
| <input type="checkbox"/> Fence | <input type="checkbox"/> Playground | <input type="checkbox"/> School |
| <input type="checkbox"/> Roadway | <input type="checkbox"/> Sidewalk | <input checked="" type="checkbox"/> Sign |
| <input type="checkbox"/> Tree | <input type="checkbox"/> Streetlamp | <input type="checkbox"/> Other: _____ |

Remove Sign on Pole

Needing Attention:

- | | | |
|-----------------------------------|----------------------------------|---|
| <input type="checkbox"/> Damage | <input type="checkbox"/> Pothole | <input type="checkbox"/> Missing |
| <input type="checkbox"/> Painting | <input type="checkbox"/> Grass | <input type="checkbox"/> Needs Trimming |

Submitted by: James Bocchino



Done 10-24-19

coupe 10/24/19
Alvotto

Borough of North Arlington
Quality of Life Report

Date: 10-2-2019

242 High St Replace Handicap Sign

Location: 144 Eagle St - No Parking this side


- | | | |
|----------------------------------|-------------------------------------|--|
| <input type="checkbox"/> Curb | <input type="checkbox"/> Lamp | <input type="checkbox"/> Park |
| <input type="checkbox"/> Fence | <input type="checkbox"/> Playground | <input type="checkbox"/> School |
| <input type="checkbox"/> Roadway | <input type="checkbox"/> Sidewalk | <input checked="" type="checkbox"/> Sign |
| <input type="checkbox"/> Tree | <input type="checkbox"/> Streetlamp | <input type="checkbox"/> Other: _____ |

Can't read signs

Needing Attention:

- | | | |
|-----------------------------------|----------------------------------|---|
| <input type="checkbox"/> Damage | <input type="checkbox"/> Pothole | <input type="checkbox"/> Missing |
| <input type="checkbox"/> Painting | <input type="checkbox"/> Grass | <input type="checkbox"/> Needs Trimming |

Submitted by: James Baschenis



DONE
10-28-19

COUPE 10/24/19
ALUOTTO

Borough of North Arlington
Quality of Life Report

Date: 9-30-19

Location: 215 Ridg Rd / Ridge Park Dr & Sixth St

- | | | |
|----------------------------------|-------------------------------------|--|
| <input type="checkbox"/> Curb | <input type="checkbox"/> Lamp | <input type="checkbox"/> Park |
| <input type="checkbox"/> Fence | <input type="checkbox"/> Playground | <input type="checkbox"/> School |
| <input type="checkbox"/> Roadway | <input type="checkbox"/> Sidewalk | <input checked="" type="checkbox"/> Sign |
| <input type="checkbox"/> Tree | <input type="checkbox"/> Streetlamp | <input type="checkbox"/> Other: _____ |

Remove sign on Pole

Needing Attention:

- | | | |
|-----------------------------------|----------------------------------|---|
| <input type="checkbox"/> Damage | <input type="checkbox"/> Pothole | <input type="checkbox"/> Missing |
| <input type="checkbox"/> Painting | <input type="checkbox"/> Grass | <input type="checkbox"/> Needs Trimming |

Submitted by: James Boachino