

Borough of North Arlington
Quality of Life Report

Date: 7/16/19

Location: End of Chestnut St. Road end

- | | | |
|----------------------------------|-------------------------------------|---------------------------------------|
| <input type="checkbox"/> Curb | <input type="checkbox"/> Lamp | <input type="checkbox"/> Park |
| <input type="checkbox"/> Fence | <input type="checkbox"/> Playground | <input type="checkbox"/> School |
| <input type="checkbox"/> Roadway | <input type="checkbox"/> Sidewalk | <input type="checkbox"/> Sign |
| <input type="checkbox"/> Tree | <input type="checkbox"/> Streetlamp | <input type="checkbox"/> Other: _____ |


Needing Attention:

- | | | |
|-----------------------------------|----------------------------------|----------------------------------------------------|
| <input type="checkbox"/> Damage | <input type="checkbox"/> Pothole | <input type="checkbox"/> Missing |
| <input type="checkbox"/> Painting | <input type="checkbox"/> Grass | <input checked="" type="checkbox"/> Needs Trimming |

Needs a clean up

Submitted by: James Bocchini

Done



Borough of North Arlington
Quality of Life Report

Date: 7/16/19


Location: 99 Argyle Pl.

- | | | |
|---------------------------------------------|-------------------------------------|---------------------------------------|
| <input type="checkbox"/> Curb | <input type="checkbox"/> Lamp | <input type="checkbox"/> Park |
| <input type="checkbox"/> Fence | <input type="checkbox"/> Playground | <input type="checkbox"/> School |
| <input checked="" type="checkbox"/> Roadway | <input type="checkbox"/> Sidewalk | <input type="checkbox"/> Sign |
| <input type="checkbox"/> Tree | <input type="checkbox"/> Streetlamp | <input type="checkbox"/> Other: _____ |

Pot Hole & middle of Road
by driveway
Needing Attention:

- | | | |
|-----------------------------------|----------------------------------|-----------------------------------------|
| <input type="checkbox"/> Damage | <input type="checkbox"/> Pothole | <input type="checkbox"/> Missing |
| <input type="checkbox"/> Painting | <input type="checkbox"/> Grass | <input type="checkbox"/> Needs Trimming |

Submitted by: James Becken's



Borough of North Arlington
Quality of Life Report

Date: 7/16/19

Location: 105 Argyle Pl. Seed ext

- | | | |
|----------------------------------|-------------------------------------|---------------------------------------|
| <input type="checkbox"/> Curb | <input type="checkbox"/> Lamp | <input type="checkbox"/> Park |
| <input type="checkbox"/> Fence | <input type="checkbox"/> Playground | <input type="checkbox"/> School |
| <input type="checkbox"/> Roadway | <input type="checkbox"/> Sidewalk | <input type="checkbox"/> Sign |
| <input type="checkbox"/> Tree | <input type="checkbox"/> Streetlamp | <input type="checkbox"/> Other: _____ |


Needing Attention:

- | | | |
|-----------------------------------|----------------------------------|----------------------------------------------------|
| <input type="checkbox"/> Damage | <input type="checkbox"/> Pothole | <input type="checkbox"/> Missing |
| <input type="checkbox"/> Painting | <input type="checkbox"/> Grass | <input checked="" type="checkbox"/> Needs Trimming |

needs grass cleanup

Submitted by: James Bacchini

Dave



Borough of North Arlington
Quality of Life Report

Date: 7/15/19

Location: End of Morgan Pl going up by
Parvett, along fence

- | | | |
|----------------------------------|-------------------------------------|---------------------------------------|
| <input type="checkbox"/> Curb | <input type="checkbox"/> Lamp | <input type="checkbox"/> Park |
| <input type="checkbox"/> Fence | <input type="checkbox"/> Playground | <input type="checkbox"/> School |
| <input type="checkbox"/> Roadway | <input type="checkbox"/> Sidewalk | <input type="checkbox"/> Sign |
| <input type="checkbox"/> Tree | <input type="checkbox"/> Streetlamp | <input type="checkbox"/> Other: _____ |


Needing Attention:

- | | | |
|-----------------------------------|----------------------------------|----------------------------------------------------|
| <input type="checkbox"/> Damage | <input type="checkbox"/> Pothole | <input type="checkbox"/> Missing |
| <input type="checkbox"/> Painting | <input type="checkbox"/> Grass | <input checked="" type="checkbox"/> Needs Trimming |

along fence good clean-up

Submitted by: Jamie Berchus

Done



Borough of North Arlington
Quality of Life Report

Date: 7/15

Clinton Pl near Madison



Location: _____


- | | | |
|----------------------------------|-------------------------------------|---------------------------------------|
| <input type="checkbox"/> Curb | <input type="checkbox"/> Lamp | <input type="checkbox"/> Park |
| <input type="checkbox"/> Fence | <input type="checkbox"/> Playground | <input type="checkbox"/> School |
| <input type="checkbox"/> Roadway | <input type="checkbox"/> Sidewalk | <input type="checkbox"/> Sign |
| <input type="checkbox"/> Tree | <input type="checkbox"/> Streetlamp | <input type="checkbox"/> Other: _____ |

Needing Attention:

- | | | |
|--------------------------------------------|----------------------------------|-----------------------------------------|
| <input checked="" type="checkbox"/> Damage | <input type="checkbox"/> Pothole | <input type="checkbox"/> Missing |
| <input type="checkbox"/> Painting | <input type="checkbox"/> Grass | <input type="checkbox"/> Needs Trimming |

Fire Hydrant Leaking

Submitted by: James Pouchino



Borough of North Arlington
Quality of Life Report

Date: 7/15/19

Location: New H & B Plover Meter 0092


- | | | |
|----------------------------------|-------------------------------------|---------------------------------------|
| <input type="checkbox"/> Curb | <input type="checkbox"/> Lamp | <input type="checkbox"/> Park |
| <input type="checkbox"/> Fence | <input type="checkbox"/> Playground | <input type="checkbox"/> School |
| <input type="checkbox"/> Roadway | <input type="checkbox"/> Sidewalk | <input type="checkbox"/> Sign |
| <input type="checkbox"/> Tree | <input type="checkbox"/> Streetlamp | <input type="checkbox"/> Other: _____ |

Needing Attention:

- | | | |
|--------------------------------------------|----------------------------------|-----------------------------------------|
| <input checked="" type="checkbox"/> Damage | <input type="checkbox"/> Pothole | <input type="checkbox"/> Missing |
| <input type="checkbox"/> Painting | <input type="checkbox"/> Grass | <input type="checkbox"/> Needs Trimming |

Meter is damaged

Submitted by: James Benhew



Borough of North Arlington
Quality of Life Report

Date: 7/17/19

Location: 6th St dead-end

- | | | |
|------------------------------------------|-------------------------------------|---------------------------------------|
| <input checked="" type="checkbox"/> Curb | <input type="checkbox"/> Lamp | <input type="checkbox"/> Park |
| <input type="checkbox"/> Fence | <input type="checkbox"/> Playground | <input type="checkbox"/> School |
| <input type="checkbox"/> Roadway | <input type="checkbox"/> Sidewalk | <input type="checkbox"/> Sign |
| <input type="checkbox"/> Tree | <input type="checkbox"/> Streetlamp | <input type="checkbox"/> Other: _____ |


Curb needs to be patched

Needing Attention:

- | | | |
|-----------------------------------|----------------------------------|----------------------------------------------------|
| <input type="checkbox"/> Damage | <input type="checkbox"/> Pothole | <input type="checkbox"/> Missing |
| <input type="checkbox"/> Painting | <input type="checkbox"/> Grass | <input checked="" type="checkbox"/> Needs Trimming |

Cleanup

Submitted by: James Benke's



Borough of North Arlington
Quality of Life Report

Date: 7/19/19

Location: Jefferson School on Hedden Lane


- | | | |
|-------------------------------------------|-------------------------------------|---------------------------------------|
| <input type="checkbox"/> Curb | <input type="checkbox"/> Lamp | <input type="checkbox"/> Park |
| <input checked="" type="checkbox"/> Fence | <input type="checkbox"/> Playground | <input type="checkbox"/> School |
| <input type="checkbox"/> Roadway | <input type="checkbox"/> Sidewalk | <input type="checkbox"/> Sign |
| <input type="checkbox"/> Tree | <input type="checkbox"/> Streetlamp | <input type="checkbox"/> Other: _____ |

Fence needs repair by playground

Needing Attention:

- | | | |
|-----------------------------------|----------------------------------|-----------------------------------------|
| <input type="checkbox"/> Damage | <input type="checkbox"/> Pothole | <input type="checkbox"/> Missing |
| <input type="checkbox"/> Painting | <input type="checkbox"/> Grass | <input type="checkbox"/> Needs Trimming |

Submitted by: James Beckman



Completed
Keesh / churent:
5/21/19

Borough of North Arlington
Quality of Life Report

Date: 5/10/19

Location: NA High School by Parking Lot


- | | | |
|-------------------------------------------|-------------------------------------|--------------------------------------------|
| <input type="checkbox"/> Curb | <input type="checkbox"/> Lamp | <input type="checkbox"/> Park |
| <input checked="" type="checkbox"/> Fence | <input type="checkbox"/> Playground | <input checked="" type="checkbox"/> School |
| <input type="checkbox"/> Roadway | <input type="checkbox"/> Sidewalk | <input type="checkbox"/> Sign |
| <input type="checkbox"/> Tree | <input type="checkbox"/> Streetlamp | <input type="checkbox"/> Other: _____ |

Needing Attention:

- | | | |
|-----------------------------------|-------------------------------------------|----------------------------------------------------|
| <input type="checkbox"/> Damage | <input type="checkbox"/> Pothole | <input type="checkbox"/> Missing |
| <input type="checkbox"/> Painting | <input checked="" type="checkbox"/> Grass | <input checked="" type="checkbox"/> Needs Trimming |

Needs Cleaning in back of Borough Hall

Submitted by: James Bachro




BOROUGH OF NORTH ARLINGTON

214 RIDGE ROAD
NORTH ARLINGTON, N.J. 07031
Phone (201) 991-6060

The following path finder poles have been repaired:

1. Ridge Park & Gold St. 7/9/19
2. Ridge Rd. & Stover Ave. 7/9/19
3. Beaver Ave. 7/9/19
4. Ridge Rd. & Beaver 7/9/19
5. Hedden Terr. & Ridge Rd. 7/9/19
6. Schuyler Ave. & Carrier Rd. 7/9/19
7. Riverview Ave. & Veterans pl. 7/10/19
8. Schuyler Ave. & Ewing Pl. 7/10/19
9. West St. & Locust Ave. 7/10/19
10. River Rd. & Eagle St. 7/10/19
11. Birchwood Dr. & River Rd. 7/10/19
12. Stevens Pl. & Prospect Ave. 7/10/19
13. 6th St. & Wilson Pl. 7/10/19
14. Brandenburg Pl. 7/10/19
15. Ewing Ave. & Schuyler Ave. 7/10/19
16. Sunset Ave. & York Ave. 7/10/19
17. Chestnut St. 7/10/19
18. Beech St. 7/10/19
19. Arlington Ave. & Rutherford Pl 7/10/19
20. Argyle Pl. & Belleville Ave. 7/10/19
21. Exton Ave. & Argyle Pl. 7/10/19
22. Hendel Ave. & Bathurst Ave. 7/10/19
23. Riverview Ave. & Belmont Ave. 7/11/19
24. Riverview Ave. & Bogle Ave. 7/11/19
25. Pine St. & Belmont Ave. 7/11/19
26. Riverview Ave. & Bayliss St. 7/11/19
27. Belmont Ave. & Hillside Ave. 7/11/19
28. Prospect Ave. & Belmont Ave. 7/11/19
29. Bathurst Ave. & Hendel Ave. 7/11/19
30. Inman Pl. & Rutherford Pl. 7/11/19
31. Exton Ave. & Beech St. 7/11/19
32. William St. & Belleville Tpk. 7/15/19
33. Belleville Tpk. & Newell Pl. 7/15/19
34. Hedden Terr. & William St. 7/15/19
35. Melrose Ave. & Prospect Ave. 7/15/19
36. Abbott Pl. & Bond Pl. 7/15/19
37. Belmont Ave. & Bond Pl. 7/15/19

38. Morgan Pl. & Abbott Pl.	7/15/19
39. River Rd. & Sunset Ave.	7/15/19
40. Abbott Pl. & Ridge Rd.	7/15/19
41. Crystal St. & West St.	7/15/19
42. Biltmore St.	7/15/19
43. Gold St.	7/15/19
44. High St.	7/15/19
45. Coupe Pl.	7/15/19
46. Fisher Pl. & Prospect Ave.	7/15/19
47. Eagle St. & West St.	7/16/19
48. River Rd. Sunset Ave.	7/16/19
49. Bogle Ave. & Seventh St.	7/16/19
50. High St. & Locust Ave.	7/16/19
51. Stover Ave. & Gold St.	7/16/19
52. Sixth S. & Bogle Ave.	7/16/19
53. Shields Pl. & Eagle St.	7/16/19
54. Arlington Ave. & York Ave.	7/16/19
55. Stover Ave. & West St.	7/16/19
56. Vanderbilt St. & Truman Ave.	8/8/19
57. Truman Ave. & Moore	8/8/19
58. Truman Ave. & Halsey Pl.	8/8/19
59. Geraldine Rd. & Silvia Pl.	8/8/19
60. Jauncey Ave & 5 th St.	8/8/19
61. Jauncey Ave & Norwood Terr.	8/8/19
62. Boston Ave	8/14/19
63. Noel Dr. & Second St.	8/14/19
64. 4 th St. & Canterbury Ave.	8/14/19
65. Hoover Ave. & Union Pl.	8/14/19
66. Clinton Pl. & Madison St.	8/14/19
67. Webster St. & Canterbury Ave.	8/14/19
68. Bergen Ave. & 6 th St.	8/14/19
69. 6 th St. & Lincoln Ave.	8/14/19
70. Miller Pl. & 4 th St	8/14/19



BOROUGH OF NORTH ARLINGTON


214 RIDGE ROAD
NORTH ARLINGTON, N.J. 07031
Phone (201) 991-6060

The following path finder poles have been repaired:

1. Ridge Park & Gold St. 7/9/19
2. Ridge Rd. & Stover Ave. 7/9/19
3. Beaver Ave. 7/9/19
4. Ridge Rd. & Beaver 7/9/19
5. Hedden Terr. & Ridge Rd. 7/9/19
6. Schuyler Ave. & Carrier Rd. 7/9/19
7. Riverview Ave. & Veterans pl. 7/10/19
8. Schuyler Ave. & Ewing Pl. 7/10/19
9. West St. & Locust Ave. 7/10/19
10. River Rd. & Eagle St. 7/10/19
11. Birchwood Dr. & River Rd. 7/10/19
12. Stevens Pl. & Prospect Ave. 7/10/19
13. 6th St. & Wilson Pl. 7/10/19
14. Brandenburg Pl. 7/10/19
15. Ewing Ave. & Schuyler Ave. 7/10/19
16. Sunset Ave. & York Ave. 7/10/19
17. Chestnut St. 7/10/19
18. Beech St. 7/10/19
19. Arlington Ave. & Rutherford Pl 7/10/19
20. Argyle Pl. & Belleville Ave. 7/10/19
21. Exton Ave. & Argyle Pl. 7/10/19
22. Riverview Ave. & Belmont Ave. 7/11/19
23. Riverview Ave. & Bogle Ave. 7/11/19
24. Riverview Ave. & Bayliss St. 7/11/19
25. Belmont Ave. & Hillside Ave. 7/11/19
26. Prospect Ave. & Belmont Ave. 7/11/19
27. Bathurst Ave. & Hendel Ave. 7/11/19
28. Inman Pl. & Rutherford Pl. 7/11/19
29. Exton Ave. & Beech St. 7/11/19
30. William St. & Belleville Tpk. 7/15/19
31. Belleville Tpk. & Newell Pl. 7/15/19
32. Hedden Terr. & William St. 7/15/19
33. Melrose Ave. & Prospect Ave. 7/15/19
34. Abbott Pl. & Bond Pl. 7/15/19
35. Belmont Ave. & Bond Pl. 7/15/19
36. Morgan Pl. & Abbott Pl. 7/15/19
37. River Rd. & Sunset Ave. 7/15/19

38. Crystal St. & West St.	7/15/19
39. Biltmore St.	7/15/19
40. Gold St.	7/15/19
41. High St.	7/15/19
42. Coupe Pl.	7/15/19
43. Fisher Pl. & Prospect Ave.	7/15/19
44. Eagle St. & West St.	7/16/19
45. River Rd. Sunset Ave.	7/16/19
46. Bogle Ave. & Seventh St.	7/16/19
47. High St. & Locust Ave.	7/16/19
48. Stover Ave. & Gold St.	7/16/19
49. Sixth S. & Bogle Ave.	7/16/19
50. Shields Pl. & Eagle St.	7/16/19
51. Arlington Ave. & York Ave.	7/16/19
52. Stover Ave. & West St.	7/16/19

FORWARD - To
Police.
They-KNOW.
SHAFRIN
=



Borough of North Arlington
Quality of Life Report

Date: 7/15/19

Location: New H&B Pharmacy Meter 0092

- | | | |
|----------------------------------|-------------------------------------|---------------------------------------|
| <input type="checkbox"/> Curb | <input type="checkbox"/> Lamp | <input type="checkbox"/> Park |
| <input type="checkbox"/> Fence | <input type="checkbox"/> Playground | <input type="checkbox"/> School |
| <input type="checkbox"/> Roadway | <input type="checkbox"/> Sidewalk | <input type="checkbox"/> Sign |
| <input type="checkbox"/> Tree | <input type="checkbox"/> Streetlamp | <input type="checkbox"/> Other: _____ |


Needing Attention:

- | | | |
|--------------------------------------------|----------------------------------|-----------------------------------------|
| <input checked="" type="checkbox"/> Damage | <input type="checkbox"/> Pothole | <input type="checkbox"/> Missing |
| <input type="checkbox"/> Painting | <input type="checkbox"/> Grass | <input type="checkbox"/> Needs Trimming |

Meter is damaged

Submitted by: James Benham

Bill Cypse
7-24-19



Borough of North Arlington

Quality of Life Report

Date: 7/16/19

Location: End of Chestnut Str lead end

- | | | |
|----------------------------------|-------------------------------------|---------------------------------------|
| <input type="checkbox"/> Curb | <input type="checkbox"/> Lamp | <input type="checkbox"/> Park |
| <input type="checkbox"/> Fence | <input type="checkbox"/> Playground | <input type="checkbox"/> School |
| <input type="checkbox"/> Roadway | <input type="checkbox"/> Sidewalk | <input type="checkbox"/> Sign |
| <input type="checkbox"/> Tree | <input type="checkbox"/> Streetlamp | <input type="checkbox"/> Other: _____ |


Needing Attention:

- | | | |
|-----------------------------------|----------------------------------|----------------------------------------------------|
| <input type="checkbox"/> Damage | <input type="checkbox"/> Pothole | <input type="checkbox"/> Missing |
| <input type="checkbox"/> Painting | <input type="checkbox"/> Grass | <input checked="" type="checkbox"/> Needs Trimming |

Needs a clean up

Submitted by: James Bocchini

Done.
Bill - Coupe.
7-~~27~~-19
25.



Borough of North Arlington
Quality of Life Report

Date: 7/16/19

Location: 105 Argyle Pl. 2nd est

- | | | |
|----------------------------------|-------------------------------------|---------------------------------------|
| <input type="checkbox"/> Curb | <input type="checkbox"/> Lamp | <input type="checkbox"/> Park |
| <input type="checkbox"/> Fence | <input type="checkbox"/> Playground | <input type="checkbox"/> School |
| <input type="checkbox"/> Roadway | <input type="checkbox"/> Sidewalk | <input type="checkbox"/> Sign |
| <input type="checkbox"/> Tree | <input type="checkbox"/> Streetlamp | <input type="checkbox"/> Other: _____ |


Needing Attention:

- | | | |
|-----------------------------------|----------------------------------|----------------------------------------------------|
| <input type="checkbox"/> Damage | <input type="checkbox"/> Pothole | <input type="checkbox"/> Missing |
| <input type="checkbox"/> Painting | <input type="checkbox"/> Grass | <input checked="" type="checkbox"/> Needs Trimming |

needs grass cleanup

Submitted by: James Bacchini

Done.
7-25-19



Borough of North Arlington
Quality of Life Report

Date: 7/15/19

Location: End of Morgan Pl going up by
Parvert, along fence

- | | | |
|----------------------------------|-------------------------------------|---------------------------------------|
| <input type="checkbox"/> Curb | <input type="checkbox"/> Lamp | <input type="checkbox"/> Park |
| <input type="checkbox"/> Fence | <input type="checkbox"/> Playground | <input type="checkbox"/> School |
| <input type="checkbox"/> Roadway | <input type="checkbox"/> Sidewalk | <input type="checkbox"/> Sign |
| <input type="checkbox"/> Tree | <input type="checkbox"/> Streetlamp | <input type="checkbox"/> Other: _____ |

Needing Attention:

- | | | |
|-----------------------------------|----------------------------------|----------------------------------------------------|
| <input type="checkbox"/> Damage | <input type="checkbox"/> Pothole | <input type="checkbox"/> Missing |
| <input type="checkbox"/> Painting | <input type="checkbox"/> Grass | <input checked="" type="checkbox"/> Needs Trimming |


along fence good clean-up

Submitted by: Jamie Bonifant

Bill Coyne
7-24-19
DONE

NOTIFY - Police.

Called PVWC
MKC



Borough of North Arlington
Quality of Life Report

Date: 7/15

Clinton Pl near Madison

Location: _____

- | | | |
|----------------------------------|-------------------------------------|---------------------------------------|
| <input type="checkbox"/> Curb | <input type="checkbox"/> Lamp | <input type="checkbox"/> Park |
| <input type="checkbox"/> Fence | <input type="checkbox"/> Playground | <input type="checkbox"/> School |
| <input type="checkbox"/> Roadway | <input type="checkbox"/> Sidewalk | <input type="checkbox"/> Sign |
| <input type="checkbox"/> Tree | <input type="checkbox"/> Streetlamp | <input type="checkbox"/> Other: _____ |


Needing Attention:

- | | | |
|--------------------------------------------|----------------------------------|-----------------------------------------|
| <input checked="" type="checkbox"/> Damage | <input type="checkbox"/> Pothole | <input type="checkbox"/> Missing |
| <input type="checkbox"/> Painting | <input type="checkbox"/> Grass | <input type="checkbox"/> Needs Trimming |

Fire Hydrant Leaking

Submitted by: James Boucher's

Bill Cyprian
7-24-19



BOARD OF
ED

Borough of North Arlington
Quality of Life Report

Date: 7/17/19

Location: Jefferson School on Hedden Terr


- | | | |
|-------------------------------------------|-------------------------------------|---------------------------------------|
| <input type="checkbox"/> Curb | <input type="checkbox"/> Lamp | <input type="checkbox"/> Park |
| <input checked="" type="checkbox"/> Fence | <input type="checkbox"/> Playground | <input type="checkbox"/> School |
| <input type="checkbox"/> Roadway | <input type="checkbox"/> Sidewalk | <input type="checkbox"/> Sign |
| <input type="checkbox"/> Tree | <input type="checkbox"/> Streetlamp | <input type="checkbox"/> Other: _____ |

Fence needs repair by playground

Needing Attention:

- | | | |
|-----------------------------------|----------------------------------|-----------------------------------------|
| <input type="checkbox"/> Damage | <input type="checkbox"/> Pothole | <input type="checkbox"/> Missing |
| <input type="checkbox"/> Painting | <input type="checkbox"/> Grass | <input type="checkbox"/> Needs Trimming |

Submitted by: James Berhina



P.V.W.C.
Notified

Water
Leak

Borough of North Arlington
Quality of Life Report

Date: 7/16/19

Location: 99 Argyle Pl.


- Curb
- Fence
- Roadway
- Tree
- Lamp
- Playground
- Sidewalk
- Streetlamp
- Park
- School
- Sign
- Other: _____

Pothole & middle of Road
by driveway
Needing Attention:

- Damage
- Painting
- Pothole
- Grass
- Missing
- Needs Trimming

Submitted by: James Becken's

COMPLETED
BLACK-TOP CREW
M



Borough of North Arlington
Quality of Life Report

Date: 5/2/19


Location: 50 Pulaski Dr.

- | | | |
|----------------------------------|-------------------------------------|---------------------------------------|
| <input type="checkbox"/> Curb | <input type="checkbox"/> Lamp | <input type="checkbox"/> Park |
| <input type="checkbox"/> Fence | <input type="checkbox"/> Playground | <input type="checkbox"/> School |
| <input type="checkbox"/> Roadway | <input type="checkbox"/> Sidewalk | <input type="checkbox"/> Sign |
| <input type="checkbox"/> Tree | <input type="checkbox"/> Streetlamp | <input type="checkbox"/> Other: _____ |

Needing Attention:

- | | | |
|-----------------------------------|---------------------------------------------|-----------------------------------------|
| <input type="checkbox"/> Damage | <input checked="" type="checkbox"/> Pothole | <input type="checkbox"/> Missing |
| <input type="checkbox"/> Painting | <input type="checkbox"/> Grass | <input type="checkbox"/> Needs Trimming |

Submitted by: James Cacchino



Borough of North Arlington
Quality of Life Report

Date: 5/10/19

Location: Soccer Field & Allon Park

- | | | |
|----------------------------------|-------------------------------------|-------------------------------------------------------|
| <input type="checkbox"/> Curb | <input type="checkbox"/> Lamp | <input checked="" type="checkbox"/> Park |
| <input type="checkbox"/> Fence | <input type="checkbox"/> Playground | <input checked="" type="checkbox"/> School |
| <input type="checkbox"/> Roadway | <input type="checkbox"/> Sidewalk | <input type="checkbox"/> Sign |
| <input type="checkbox"/> Tree | <input type="checkbox"/> Streetlamp | <input type="checkbox"/> Other: _____ |

okay

Needing Attention:


- | | | |
|-----------------------------------|----------------------------------|-----------------------------------------|
| <input type="checkbox"/> Damage | <input type="checkbox"/> Pothole | <input type="checkbox"/> Missing |
| <input type="checkbox"/> Painting | <input type="checkbox"/> Grass | <input type="checkbox"/> Needs Trimming |

??

okay

Submitted by: James Bucher

Completed
Blacktop crew
[Signature]



Borough of North Arlington
Quality of Life Report

Date: 5/8/19

Location: 6 Silvia Pl.

- | | | |
|----------------------------------|-------------------------------------|---------------------------------------|
| <input type="checkbox"/> Curb | <input type="checkbox"/> Lamp | <input type="checkbox"/> Park |
| <input type="checkbox"/> Fence | <input type="checkbox"/> Playground | <input type="checkbox"/> School |
| <input type="checkbox"/> Roadway | <input type="checkbox"/> Sidewalk | <input type="checkbox"/> Sign |
| <input type="checkbox"/> Tree | <input type="checkbox"/> Streetlamp | <input type="checkbox"/> Other: _____ |

Needing Attention:


- | | | |
|-----------------------------------|---------------------------------------------|-----------------------------------------|
| <input type="checkbox"/> Damage | <input checked="" type="checkbox"/> Pothole | <input type="checkbox"/> Missing |
| <input type="checkbox"/> Painting | <input type="checkbox"/> Grass | <input type="checkbox"/> Needs Trimming |

2 small Potholes

Submitted by: James Becheria

Done

Coupe/CUNNINGHAM



Borough of North Arlington

Quality of Life Report

Date: 5/6/19

Location: 25 James Pl.

- | | | |
|----------------------------------|-------------------------------------|------------------------------------------|
| <input type="checkbox"/> Curb | <input type="checkbox"/> Lamp | <input type="checkbox"/> Park |
| <input type="checkbox"/> Fence | <input type="checkbox"/> Playground | <input type="checkbox"/> School |
| <input type="checkbox"/> Roadway | <input type="checkbox"/> Sidewalk | <input checked="" type="checkbox"/> Sign |
| <input type="checkbox"/> Tree | <input type="checkbox"/> Streetlamp | <input type="checkbox"/> Other: _____ |


Sign on Pole takeoff

Needing Attention:

- | | | |
|-----------------------------------|----------------------------------|-----------------------------------------|
| <input type="checkbox"/> Damage | <input type="checkbox"/> Pothole | <input type="checkbox"/> Missing |
| <input type="checkbox"/> Painting | <input type="checkbox"/> Grass | <input type="checkbox"/> Needs Trimming |

Submitted by: James Bocchino

Done
Coupe/CUNNINGHAM



Borough of North Arlington

Quality of Life Report

Date: 5/6/19

Location: 77 B. Ridge Road

- | | | |
|----------------------------------|-------------------------------------|------------------------------------------|
| <input type="checkbox"/> Curb | <input type="checkbox"/> Lamp | <input type="checkbox"/> Park |
| <input type="checkbox"/> Fence | <input type="checkbox"/> Playground | <input type="checkbox"/> School |
| <input type="checkbox"/> Roadway | <input type="checkbox"/> Sidewalk | <input checked="" type="checkbox"/> Sign |
| <input type="checkbox"/> Tree | <input type="checkbox"/> Streetlamp | <input type="checkbox"/> Other: _____ |


Sign on Pole take off

Needing Attention:

- | | | |
|-----------------------------------|----------------------------------|-----------------------------------------|
| <input type="checkbox"/> Damage | <input type="checkbox"/> Pothole | <input type="checkbox"/> Missing |
| <input type="checkbox"/> Painting | <input type="checkbox"/> Grass | <input type="checkbox"/> Needs Trimming |

Submitted by: James Bocchino

Done
Coupe/Cunningham



Borough of North Arlington

Quality of Life Report

Date: 5/8/19

Location: 58 Beech St.


- | | | |
|----------------------------------|-------------------------------------|------------------------------------------|
| <input type="checkbox"/> Curb | <input type="checkbox"/> Lamp | <input type="checkbox"/> Park |
| <input type="checkbox"/> Fence | <input type="checkbox"/> Playground | <input type="checkbox"/> School |
| <input type="checkbox"/> Roadway | <input type="checkbox"/> Sidewalk | <input checked="" type="checkbox"/> Sign |
| <input type="checkbox"/> Tree | <input type="checkbox"/> Streetlamp | <input type="checkbox"/> Other: _____ |

Needing Attention: Replace sign (Permit)
Handicapp Can't read bottom

- | | | |
|-----------------------------------|----------------------------------|-----------------------------------------|
| <input type="checkbox"/> Damage | <input type="checkbox"/> Pothole | <input type="checkbox"/> Missing |
| <input type="checkbox"/> Painting | <input type="checkbox"/> Grass | <input type="checkbox"/> Needs Trimming |

Submitted by: James Borchino

W1E-2 ✓



Borough of North Arlington
Quality of Life Report

Date: 5/2/19

Ridge Road

Location: 436 New Fire Hydrant Sign Remove


- | | | |
|----------------------------------|-------------------------------------|------------------------------------------|
| <input type="checkbox"/> Curb | <input type="checkbox"/> Lamp | <input type="checkbox"/> Park |
| <input type="checkbox"/> Fence | <input type="checkbox"/> Playground | <input type="checkbox"/> School |
| <input type="checkbox"/> Roadway | <input type="checkbox"/> Sidewalk | <input checked="" type="checkbox"/> Sign |
| <input type="checkbox"/> Tree | <input type="checkbox"/> Streetlamp | <input type="checkbox"/> Other: _____ |

Needing Attention:

- | | | |
|-----------------------------------|----------------------------------|-----------------------------------------|
| <input type="checkbox"/> Damage | <input type="checkbox"/> Pothole | <input type="checkbox"/> Missing |
| <input type="checkbox"/> Painting | <input type="checkbox"/> Grass | <input type="checkbox"/> Needs Trimming |

Needs to be replaced

Submitted by: James Bacchini



Complete

Borough of North Arlington
Quality of Life Report

Date: 5/1/19

Location: Forest Pl. & Schuyler

- | | | |
|----------------------------------|-------------------------------------|------------------------------------------|
| <input type="checkbox"/> Curb | <input type="checkbox"/> Lamp | <input type="checkbox"/> Park |
| <input type="checkbox"/> Fence | <input type="checkbox"/> Playground | <input type="checkbox"/> School |
| <input type="checkbox"/> Roadway | <input type="checkbox"/> Sidewalk | <input checked="" type="checkbox"/> Sign |
| <input type="checkbox"/> Tree | <input type="checkbox"/> Streetlamp | <input type="checkbox"/> Other: _____ |


Replace sign

Needing Attention:

- | | | |
|----------------------------------------------|----------------------------------|-----------------------------------------|
| <input type="checkbox"/> Damage | <input type="checkbox"/> Pothole | <input type="checkbox"/> Missing |
| <input checked="" type="checkbox"/> Painting | <input type="checkbox"/> Grass | <input type="checkbox"/> Needs Trimming |

Cannot read

Submitted by: James Beckins



Complete
MKC

Borough of North Arlington
Quality of Life Report

Date: 5/1/19


Location: 30 Renner Place

- | | | |
|----------------------------------|-------------------------------------|---------------------------------------|
| <input type="checkbox"/> Curb | <input type="checkbox"/> Lamp | <input type="checkbox"/> Park |
| <input type="checkbox"/> Fence | <input type="checkbox"/> Playground | <input type="checkbox"/> School |
| <input type="checkbox"/> Roadway | <input type="checkbox"/> Sidewalk | <input type="checkbox"/> Sign |
| <input type="checkbox"/> Tree | <input type="checkbox"/> Streetlamp | <input type="checkbox"/> Other: _____ |

Needing Attention:

- | | | |
|-----------------------------------|---------------------------------------------|-----------------------------------------|
| <input type="checkbox"/> Damage | <input checked="" type="checkbox"/> Pothole | <input type="checkbox"/> Missing |
| <input type="checkbox"/> Painting | <input type="checkbox"/> Grass | <input type="checkbox"/> Needs Trimming |

Submitted by: James Bacchin



✓
complete
MKC

Borough of North Arlington
Quality of Life Report

Date: 5/3/19

Location: Macdless Park


- | | | |
|----------------------------------|-------------------------------------|---------------------------------------------------------------|
| <input type="checkbox"/> Curb | <input type="checkbox"/> Lamp | <input checked="" type="checkbox"/> Park |
| <input type="checkbox"/> Fence | <input type="checkbox"/> Playground | <input type="checkbox"/> School |
| <input type="checkbox"/> Roadway | <input type="checkbox"/> Sidewalk | <input type="checkbox"/> Sign |
| <input type="checkbox"/> Tree | <input type="checkbox"/> Streetlamp | <input checked="" type="checkbox"/> Other: <u>Broken Pail</u> |

Broken Garbage Pail laying on grass

Needing Attention:

- | | | |
|-----------------------------------|----------------------------------|-----------------------------------------|
| <input type="checkbox"/> Damage | <input type="checkbox"/> Pothole | <input type="checkbox"/> Missing |
| <input type="checkbox"/> Painting | <input type="checkbox"/> Grass | <input type="checkbox"/> Needs Trimming |

Submitted by: James Brachino



W.C. ✓

RePlace =

Remove =

Borough of North Arlington

Quality of Life Report

Date: 5/1/19

Ridge Road + Near Ridge Pk Dr.

Location: 446-485 Ridge Rd

- | | | |
|----------------------------------|-------------------------------------|------------------------------------------|
| <input type="checkbox"/> Curb | <input type="checkbox"/> Lamp | <input type="checkbox"/> Park |
| <input type="checkbox"/> Fence | <input type="checkbox"/> Playground | <input type="checkbox"/> School |
| <input type="checkbox"/> Roadway | <input type="checkbox"/> Sidewalk | <input checked="" type="checkbox"/> Sign |
| <input type="checkbox"/> Tree | <input type="checkbox"/> Streetlamp | <input type="checkbox"/> Other: _____ |


Replace

Needing Attention:

- | | | |
|-----------------------------------|----------------------------------|-----------------------------------------|
| <input type="checkbox"/> Damage | <input type="checkbox"/> Pothole | <input type="checkbox"/> Missing |
| <input type="checkbox"/> Painting | <input type="checkbox"/> Grass | <input type="checkbox"/> Needs Trimming |

Crack Seal

Submitted by: James Bochinski



WIC

Borough of North Arlington
Quality of Life Report

Date: 5/1/19

Tue 10-12 Change

Location: 37 Park Ave

- | | | |
|----------------------------------|-------------------------------------|------------------------------------------|
| <input type="checkbox"/> Curb | <input type="checkbox"/> Lamp | <input type="checkbox"/> Park |
| <input type="checkbox"/> Fence | <input type="checkbox"/> Playground | <input type="checkbox"/> School |
| <input type="checkbox"/> Roadway | <input type="checkbox"/> Sidewalk | <input checked="" type="checkbox"/> Sign |
| <input type="checkbox"/> Tree | <input type="checkbox"/> Streetlamp | <input type="checkbox"/> Other: _____ |

Replace Concrete Road

Needing Attention:

- | | | |
|-----------------------------------|----------------------------------|-----------------------------------------|
| <input type="checkbox"/> Damage | <input type="checkbox"/> Pothole | <input type="checkbox"/> Missing |
| <input type="checkbox"/> Painting | <input type="checkbox"/> Grass | <input type="checkbox"/> Needs Trimming |

Submitted by: James Beckler

OPEN SPACES MAINTENANCE

Notes:

Date: ___/___/___

Date: ___/___/___

Issue Location: 51 Park ave

- | | |
|-------------------------------------|--------------------------------------------|
| <input type="checkbox"/> Curb | <input checked="" type="checkbox"/> School |
| <input type="checkbox"/> Fence | <input type="checkbox"/> Sewer |
| <input type="checkbox"/> Hydrant | <input type="checkbox"/> Sidewalk |
| <input type="checkbox"/> Light | <input checked="" type="checkbox"/> Sign |
| <input type="checkbox"/> Litter | <input type="checkbox"/> Street |
| <input type="checkbox"/> Park | <input type="checkbox"/> Tree |
| <input type="checkbox"/> Playground | <input type="checkbox"/> Other _____ |

Problem: Covered by tree growth - faded

- | | |
|-------------------------------------|--------------------------------------|
| <input type="checkbox"/> Damaged | <input type="checkbox"/> Pothole |
| <input type="checkbox"/> Missing | <input type="checkbox"/> Replace |
| <input type="checkbox"/> Overgrowth | <input type="checkbox"/> Trimming |
| <input type="checkbox"/> Painting | <input type="checkbox"/> Other _____ |

Initials: _____



27 STRATFORD PL
BACK YARD



27 STRATFORD PL
BACK YARD

Sent from my iPhone




20 STRATFORD PL



27 STRATFORD PL



20 STRATFORD PL



Borough of North Arlington

Quality of Life Report

Date: 4-6-2020

Replaced Keesh, M. Cunningham 4/21/20

Location: Cptax Ave & Forest Ave


- | | | |
|----------------------------------|-------------------------------------|------------------------------------------|
| <input type="checkbox"/> Curb | <input type="checkbox"/> Lamp | <input type="checkbox"/> Park |
| <input type="checkbox"/> Fence | <input type="checkbox"/> Playground | <input type="checkbox"/> School |
| <input type="checkbox"/> Roadway | <input type="checkbox"/> Sidewalk | <input checked="" type="checkbox"/> Sign |
| <input type="checkbox"/> Tree | <input type="checkbox"/> Streetlamp | <input type="checkbox"/> Other: _____ |

Replace sign Trucks over 4 Tons excluded

Needing Attention:

- | | | |
|-----------------------------------|----------------------------------|-----------------------------------------|
| <input type="checkbox"/> Damage | <input type="checkbox"/> Pothole | <input type="checkbox"/> Missing |
| <input type="checkbox"/> Painting | <input type="checkbox"/> Grass | <input type="checkbox"/> Needs Trimming |

Submitted by: James Bocchino



Borough of North Arlington

Quality of Life Report

Date: 4-6-2020

4/21/20

CAP put back in place Keosh, N. Cunningham

Location: 46 Allen Dr by Fire Department


- | | | |
|----------------------------------|-------------------------------------|--------------------------------------------------|
| <input type="checkbox"/> Curb | <input type="checkbox"/> Lamp | <input type="checkbox"/> Park |
| <input type="checkbox"/> Fence | <input type="checkbox"/> Playground | <input type="checkbox"/> School |
| <input type="checkbox"/> Roadway | <input type="checkbox"/> Sidewalk | <input type="checkbox"/> Sign |
| <input type="checkbox"/> Tree | <input type="checkbox"/> Streetlamp | <input checked="" type="checkbox"/> Other: _____ |

Water cap is off

Needing Attention:

- | | | |
|-----------------------------------|----------------------------------|-----------------------------------------|
| <input type="checkbox"/> Damage | <input type="checkbox"/> Pothole | <input type="checkbox"/> Missing |
| <input type="checkbox"/> Painting | <input type="checkbox"/> Grass | <input type="checkbox"/> Needs Trimming |

Submitted by: James Boecklin



Borough of North Arlington

Quality of Life Report

Date: 4-7-2010

Gino, churuti

RePLACED w/ u-channel 4/21/20

Location: Hedden Terr. & Willis St


- | | | |
|----------------------------------|-------------------------------------|------------------------------------------|
| <input type="checkbox"/> Curb | <input type="checkbox"/> Lamp | <input type="checkbox"/> Park |
| <input type="checkbox"/> Fence | <input type="checkbox"/> Playground | <input type="checkbox"/> School |
| <input type="checkbox"/> Roadway | <input type="checkbox"/> Sidewalk | <input checked="" type="checkbox"/> Sign |
| <input type="checkbox"/> Tree | <input type="checkbox"/> Streetlamp | <input type="checkbox"/> Other: _____ |

2 signs in Pole on Willis St

Needing Attention:

- | | | |
|-----------------------------------|----------------------------------|-----------------------------------------|
| <input type="checkbox"/> Damage | <input type="checkbox"/> Pothole | <input type="checkbox"/> Missing |
| <input type="checkbox"/> Painting | <input type="checkbox"/> Grass | <input type="checkbox"/> Needs Trimming |

Submitted by: James Boecklin



Borough of North Arlington

Quality of Life Report

Date: 4-9-2020

UNFOUNDCO 4/16/20 MKC

Location: 20 Biltmore Ave.

- | | | |
|---------------------------------------------|-------------------------------------|---------------------------------------|
| <input type="checkbox"/> Curb | <input type="checkbox"/> Lamp | <input type="checkbox"/> Park |
| <input type="checkbox"/> Fence | <input type="checkbox"/> Playground | <input type="checkbox"/> School |
| <input checked="" type="checkbox"/> Roadway | <input type="checkbox"/> Sidewalk | <input type="checkbox"/> Sign |
| <input type="checkbox"/> Tree | <input type="checkbox"/> Streetlamp | <input type="checkbox"/> Other: _____ |

Pot Hole

Needing Attention:

- | | | |
|-----------------------------------|----------------------------------|-----------------------------------------|
| <input type="checkbox"/> Damage | <input type="checkbox"/> Pothole | <input type="checkbox"/> Missing |
| <input type="checkbox"/> Painting | <input type="checkbox"/> Grass | <input type="checkbox"/> Needs Trimming |

Submitted by: James Boeckeno



Borough of North Arlington

Quality of Life Report

Date: 4-13-2020

ALL concrete in AREA N/A Gino, Churuti

4/21/20

Location: 22 Albert St

Curb

Lamp

Park

Fence

Playground

School

Roadway

Sidewalk

Sign

Tree

Streetlamp

Other: _____

Signs on Pole

Needing Attention:

Damage

Pothole


Missing

Painting

Grass

Needs Trimming

Submitted by: James Boeckeno



Borough of North Arlington
Quality of Life Report

Date: 4-14-2020

UNFOUNDED ALUOTTO COUPE 4121120

Location: 126 Bergen ave


- | | | |
|----------------------------------|-------------------------------------|------------------------------------------|
| <input type="checkbox"/> Curb | <input type="checkbox"/> Lamp | <input type="checkbox"/> Park |
| <input type="checkbox"/> Fence | <input type="checkbox"/> Playground | <input type="checkbox"/> School |
| <input type="checkbox"/> Roadway | <input type="checkbox"/> Sidewalk | <input checked="" type="checkbox"/> Sign |
| <input type="checkbox"/> Tree | <input type="checkbox"/> Streetlamp | <input type="checkbox"/> Other: _____ |

Sign on Pole

Needing Attention:

- | | | |
|-----------------------------------|----------------------------------|-----------------------------------------|
| <input type="checkbox"/> Damage | <input type="checkbox"/> Pothole | <input type="checkbox"/> Missing |
| <input type="checkbox"/> Painting | <input type="checkbox"/> Grass | <input type="checkbox"/> Needs Trimming |

Submitted by: James Boecklin



Borough of North Arlington

Quality of Life Report

Date: 4-20-2020

completed coupe, Aluotto 4130120

Location: 38 Ridge Rd


- | | | |
|----------------------------------|-------------------------------------|------------------------------------------|
| <input type="checkbox"/> Curb | <input type="checkbox"/> Lamp | <input type="checkbox"/> Park |
| <input type="checkbox"/> Fence | <input type="checkbox"/> Playground | <input type="checkbox"/> School |
| <input type="checkbox"/> Roadway | <input type="checkbox"/> Sidewalk | <input checked="" type="checkbox"/> Sign |
| <input type="checkbox"/> Tree | <input type="checkbox"/> Streetlamp | <input type="checkbox"/> Other: _____ |

replace sign Trees 7 AM to 8 AM

Needing Attention:

- | | | |
|-----------------------------------|----------------------------------|-----------------------------------------|
| <input type="checkbox"/> Damage | <input type="checkbox"/> Pothole | <input type="checkbox"/> Missing |
| <input type="checkbox"/> Painting | <input type="checkbox"/> Grass | <input type="checkbox"/> Needs Trimming |

Submitted by: James Basolino



Borough of North Arlington

Quality of Life Report

Date: 4-21-2020

Completed coupe, Alutto 4130/20

Location: 19 Union Place

Curb

Lamp

Park

Fence

Playground

School

Roadway

Sidewalk

Sign

Tree

Streetlamp

Other: _____

Needing Attention:

Replace sign no parking Mon to 8 AM to 10 AM
Can't read

Damage

Pothole


Missing

Painting

Grass

Needs Trimming

Submitted by: James Baschiro



Borough of North Arlington
Quality of Life Report

Date: 4-21-2020

Completed coupe, Aluotto 4/30/20

Location: 32 & 38 Union Place


- | | | |
|----------------------------------|-------------------------------------|------------------------------------------|
| <input type="checkbox"/> Curb | <input type="checkbox"/> Lamp | <input type="checkbox"/> Park |
| <input type="checkbox"/> Fence | <input type="checkbox"/> Playground | <input type="checkbox"/> School |
| <input type="checkbox"/> Roadway | <input type="checkbox"/> Sidewalk | <input checked="" type="checkbox"/> Sign |
| <input type="checkbox"/> Tree | <input type="checkbox"/> Streetlamp | <input type="checkbox"/> Other: _____ |

Sign on Poles

Needing Attention:

- | | | |
|-----------------------------------|----------------------------------|-----------------------------------------|
| <input type="checkbox"/> Damage | <input type="checkbox"/> Pothole | <input type="checkbox"/> Missing |
| <input type="checkbox"/> Painting | <input type="checkbox"/> Grass | <input type="checkbox"/> Needs Trimming |

Submitted by: James Boecklin



Borough of North Arlington

Quality of Life Report

Date: 4-22-2020

completed Keosh, Churuti 4/30/20

Location: 100 Battenue Ave

- | | | |
|----------------------------------|-------------------------------------|------------------------------------------|
| <input type="checkbox"/> Curb | <input type="checkbox"/> Lamp | <input type="checkbox"/> Park |
| <input type="checkbox"/> Fence | <input type="checkbox"/> Playground | <input type="checkbox"/> School |
| <input type="checkbox"/> Roadway | <input type="checkbox"/> Sidewalk | <input checked="" type="checkbox"/> Sign |
| <input type="checkbox"/> Tree | <input type="checkbox"/> Streetlamp | <input type="checkbox"/> Other: _____ |

replace sign Thu 8 to 10 A M
Needing Attention: Chris T Redd

- | | | |
|-----------------------------------|----------------------------------|-----------------------------------------|
| <input type="checkbox"/> Damage | <input type="checkbox"/> Pothole | <input type="checkbox"/> Missing |
| <input type="checkbox"/> Painting | <input type="checkbox"/> Grass | <input type="checkbox"/> Needs Trimming |

Submitted by: James Boecklin



Borough of North Arlington

Quality of Life Report

Date: 4-23-2020

UNFOUNDED Keosh, Churati 4130120

Location: Ridge Rd & Fourth St


- | | | |
|----------------------------------|-------------------------------------|------------------------------------------|
| <input type="checkbox"/> Curb | <input type="checkbox"/> Lamp | <input type="checkbox"/> Park |
| <input type="checkbox"/> Fence | <input type="checkbox"/> Playground | <input type="checkbox"/> School |
| <input type="checkbox"/> Roadway | <input type="checkbox"/> Sidewalk | <input checked="" type="checkbox"/> Sign |
| <input type="checkbox"/> Tree | <input type="checkbox"/> Streetlamp | <input type="checkbox"/> Other: _____ |

Replace sign (permet parking)

Needing Attention:

- | | | |
|-----------------------------------|----------------------------------|-----------------------------------------|
| <input type="checkbox"/> Damage | <input type="checkbox"/> Pothole | <input type="checkbox"/> Missing |
| <input type="checkbox"/> Painting | <input type="checkbox"/> Grass | <input type="checkbox"/> Needs Trimming |

Submitted by: James Baschiro



Borough of North Arlington
Quality of Life Report

Date: 4-23-2020

Removed Not needed Keogh, chventi 4/30/20


Location: Bilmer Ave by Prospect Ave

- | | | |
|----------------------------------|-------------------------------------|------------------------------------------|
| <input type="checkbox"/> Curb | <input type="checkbox"/> Lamp | <input type="checkbox"/> Park |
| <input type="checkbox"/> Fence | <input type="checkbox"/> Playground | <input type="checkbox"/> School |
| <input type="checkbox"/> Roadway | <input type="checkbox"/> Sidewalk | <input checked="" type="checkbox"/> Sign |
| <input type="checkbox"/> Tree | <input type="checkbox"/> Streetlamp | <input type="checkbox"/> Other: _____ |

Needing Attention: Replace sign Med 10 to turn east
road

- | | | |
|-----------------------------------|----------------------------------|-----------------------------------------|
| <input type="checkbox"/> Damage | <input type="checkbox"/> Pothole | <input type="checkbox"/> Missing |
| <input type="checkbox"/> Painting | <input type="checkbox"/> Grass | <input type="checkbox"/> Needs Trimming |

Submitted by: James Boecklin



Borough of North Arlington

Quality of Life Report

Date: Week of May 2nd

Chest St & Bayless 2 signs on Pole

Location: 234 Crystal St Signs on Pole

Concrete at all locations would need to be repaired
coupe, Aluotto

- | | | |
|----------------------------------|-------------------------------------|------------------------------------------|
| <input type="checkbox"/> Curb | <input type="checkbox"/> Lamp | <input type="checkbox"/> Park |
| <input type="checkbox"/> Fence | <input type="checkbox"/> Playground | <input type="checkbox"/> School |
| <input type="checkbox"/> Roadway | <input type="checkbox"/> Sidewalk | <input checked="" type="checkbox"/> Sign |
| <input type="checkbox"/> Tree | <input type="checkbox"/> Streetlamp | <input type="checkbox"/> Other: _____ |

Needing Attention:

- | | | |
|-----------------------------------|----------------------------------|-----------------------------------------|
| <input type="checkbox"/> Damage | <input type="checkbox"/> Pothole | <input type="checkbox"/> Missing |
| <input type="checkbox"/> Painting | <input type="checkbox"/> Grass | <input type="checkbox"/> Needs Trimming |

Submitted by: James Boecklin