

Borough of North Arlington  
Quality of Life Report

Date: 9-17-2019


Location: 129 Bergen Ave. Curb all broken

- |  |                                     |                                       |
|--|-------------------------------------|---------------------------------------|
| <input checked="" type="checkbox"/> Curb | <input type="checkbox"/> Lamp       | <input type="checkbox"/> Park         |
| <input type="checkbox"/> Fence           | <input type="checkbox"/> Playground | <input type="checkbox"/> School       |
| <input type="checkbox"/> Roadway         | <input type="checkbox"/> Sidewalk   | <input type="checkbox"/> Sign         |
| <input type="checkbox"/> Tree            | <input type="checkbox"/> Streetlamp | <input type="checkbox"/> Other: _____ |

Needing Attention:

- |                                   |                                  |   |
|-----------------------------------|----------------------------------|---|
| <input type="checkbox"/> Damage   | <input type="checkbox"/> Pothole | <input type="checkbox"/> Missing        |
| <input type="checkbox"/> Painting | <input type="checkbox"/> Grass   | <input type="checkbox"/> Needs Trimming |

Submitted by: James Bocchino



NO concrete  
work scheduled

Borough of North Arlington  
Quality of Life Report

Date: 9-17-2019


Location: 129 Bergen Ave. Curb all broken NIA

- |  |                                     |                                       |
|--|-------------------------------------|---------------------------------------|
| <input checked="" type="checkbox"/> Curb | <input type="checkbox"/> Lamp       | <input type="checkbox"/> Park         |
| <input type="checkbox"/> Fence           | <input type="checkbox"/> Playground | <input type="checkbox"/> School       |
| <input type="checkbox"/> Roadway         | <input type="checkbox"/> Sidewalk   | <input type="checkbox"/> Sign         |
| <input type="checkbox"/> Tree            | <input type="checkbox"/> Streetlamp | <input type="checkbox"/> Other: _____ |

Needing Attention:

- |                                   |                                  |   |
|-----------------------------------|----------------------------------|---|
| <input type="checkbox"/> Damage   | <input type="checkbox"/> Pothole | <input type="checkbox"/> Missing        |
| <input type="checkbox"/> Painting | <input type="checkbox"/> Grass   | <input type="checkbox"/> Needs Trimming |

Submitted by: James Bocchino



Borough of North Arlington  
Quality of Life Report

Date: 9-18-2019


Location: 67 Morgan Pl.

- |                                  |                                     |                                       |
|----------------------------------|-------------------------------------|---------------------------------------|
| <input type="checkbox"/> Curb    | <input type="checkbox"/> Lamp       | <input type="checkbox"/> Park         |
| <input type="checkbox"/> Fence   | <input type="checkbox"/> Playground | <input type="checkbox"/> School       |
| <input type="checkbox"/> Roadway | <input type="checkbox"/> Sidewalk   | <input type="checkbox"/> Sign         |
| <input type="checkbox"/> Tree    | <input type="checkbox"/> Streetlamp | <input type="checkbox"/> Other: _____ |

Needing Attention:

- |                                   |   |   |
|-----------------------------------|---|---|
| <input type="checkbox"/> Damage   | <input checked="" type="checkbox"/> Pothole | <input type="checkbox"/> Missing        |
| <input type="checkbox"/> Painting | <input type="checkbox"/> Grass              | <input type="checkbox"/> Needs Trimming |

Submitted by: James Bochner



Borough of North Arlington  
Quality of Life Report

Date: 10-15-2019

*2nd  
Notice*


Location: Chestnut St dead-end Clean up

- |                                  |                                     |                                       |
|----------------------------------|-------------------------------------|---------------------------------------|
| <input type="checkbox"/> Curb    | <input type="checkbox"/> Lamp       | <input type="checkbox"/> Park         |
| <input type="checkbox"/> Fence   | <input type="checkbox"/> Playground | <input type="checkbox"/> School       |
| <input type="checkbox"/> Roadway | <input type="checkbox"/> Sidewalk   | <input type="checkbox"/> Sign         |
| <input type="checkbox"/> Tree    | <input type="checkbox"/> Streetlamp | <input type="checkbox"/> Other: _____ |

Needing Attention:

- |                                   |                                  |  |
|-----------------------------------|----------------------------------|--|
| <input type="checkbox"/> Damage   | <input type="checkbox"/> Pothole | <input type="checkbox"/> Missing                   |
| <input type="checkbox"/> Painting | <input type="checkbox"/> Grass   | <input checked="" type="checkbox"/> Needs Trimming |

Submitted by: James Bocchini



Borough of North Arlington  
Quality of Life Report

Date: 10-16-2019

Boyle Ave & Bright St repair curb  
& post needs repair

Location: Supt St 44 curb all broken  
& 63 curb missing

Curb

Fence

Roadway

Tree

Lamp

Playground

Sidewalk

Streetlamp

Park

School

Sign

Other: \_\_\_\_\_

Needing Attention:

Damage

Painting


Pothole

Grass

Missing

Needs Trimming

Submitted by: James Bocchino



NO concrete  
WORK Scheduled

Borough of North Arlington  
Quality of Life Report

Date: 10-16-2019

Boyle Ave & 8th St repair curb N/A  
& road needs repair

Location: Sept St 44 curb all broken N/A  
& 63 curb missing

- |   |                                     |                                       |
|---|-------------------------------------|---------------------------------------|
| <input checked="" type="checkbox"/> Curb    | <input type="checkbox"/> Lamp       | <input type="checkbox"/> Park         |
| <input type="checkbox"/> Fence              | <input type="checkbox"/> Playground | <input type="checkbox"/> School       |
| <input checked="" type="checkbox"/> Roadway | <input type="checkbox"/> Sidewalk   | <input type="checkbox"/> Sign         |
| <input type="checkbox"/> Tree               | <input type="checkbox"/> Streetlamp | <input type="checkbox"/> Other: _____ |

Needing Attention:

- |                                   |                                  |   |
|-----------------------------------|----------------------------------|---|
| <input type="checkbox"/> Damage   | <input type="checkbox"/> Pothole | <input type="checkbox"/> Missing        |
| <input type="checkbox"/> Painting | <input type="checkbox"/> Grass   | <input type="checkbox"/> Needs Trimming |

Submitted by: James Bocchino



Borough of North Arlington  
Quality of Life Report

Date: 10-21-2019

Chestnut & Eglon Clear metal boxes

Location: 122 Ridge Rd (mudsox sidewalk)

- |                                  |                                     |                                       |
|----------------------------------|-------------------------------------|---------------------------------------|
| <input type="checkbox"/> Curb    | <input type="checkbox"/> Lamp       | <input type="checkbox"/> Park         |
| <input type="checkbox"/> Fence   | <input type="checkbox"/> Playground | <input type="checkbox"/> School       |
| <input type="checkbox"/> Roadway | <input type="checkbox"/> Sidewalk   | <input type="checkbox"/> Sign         |
| <input type="checkbox"/> Tree    | <input type="checkbox"/> Streetlamp | <input type="checkbox"/> Other: _____ |

---

Needing Attention:

- |                                   |   |  |
|-----------------------------------|---|--|
| <input type="checkbox"/> Damage   | <input type="checkbox"/> Pothole          | <input type="checkbox"/> Missing                   |
| <input type="checkbox"/> Painting | <input checked="" type="checkbox"/> Grass | <input checked="" type="checkbox"/> Needs Trimming |

Clear mudsox sidewalk

Submitted by: James Boucheno



Borough of North Arlington  
Quality of Life Report

Date: 10-23-2019

Lusk PL No Park Replace Sign  
8-10 Tues

Location: 98 Park ave Replace Sign  
No Park Mon - 10 to noon


- |                                  |                                     |  |
|----------------------------------|-------------------------------------|--|
| <input type="checkbox"/> Curb    | <input type="checkbox"/> Lamp       | <input type="checkbox"/> Park            |
| <input type="checkbox"/> Fence   | <input type="checkbox"/> Playground | <input type="checkbox"/> School          |
| <input type="checkbox"/> Roadway | <input type="checkbox"/> Sidewalk   | <input checked="" type="checkbox"/> Sign |
| <input type="checkbox"/> Tree    | <input type="checkbox"/> Streetlamp | <input type="checkbox"/> Other: _____    |

Needing Attention:

- |                                   |                                  |   |
|-----------------------------------|----------------------------------|---|
| <input type="checkbox"/> Damage   | <input type="checkbox"/> Pothole | <input type="checkbox"/> Missing        |
| <input type="checkbox"/> Painting | <input type="checkbox"/> Grass   | <input type="checkbox"/> Needs Trimming |

Submitted by: James Bozkins





Borough of North Arlington  
Quality of Life Report

Date: 10-28-2019

Fix as soon as possible  
alot of complaints

Location: Beverly + Lincoln  
Big hole against Curb

Curb

Lamp

Park

Fence

Playground

School

Roadway

Sidewalk

Sign

Tree

Streetlamp

Other: \_\_\_\_\_

Needing Attention:

Damage

Pothole

Missing

Painting

Grass

Needs Trimming

Submitted by: James Boeckens



Borough of North Arlington  
Quality of Life Report

Date: 10-30-2019

109 Melrose - along curb black top broken


Location: 159 Abbot & Morgan Corrses curb  
damaged & Pot Hole

- |   |                                     |                                       |
|---|-------------------------------------|---------------------------------------|
| <input checked="" type="checkbox"/> Curb    | <input type="checkbox"/> Lamp       | <input type="checkbox"/> Park         |
| <input type="checkbox"/> Fence              | <input type="checkbox"/> Playground | <input type="checkbox"/> School       |
| <input checked="" type="checkbox"/> Roadway | <input type="checkbox"/> Sidewalk   | <input type="checkbox"/> Sign         |
| <input type="checkbox"/> Tree               | <input type="checkbox"/> Streetlamp | <input type="checkbox"/> Other: _____ |

Needing Attention:

- |                                   |   |   |
|-----------------------------------|---|---|
| <input type="checkbox"/> Damage   | <input checked="" type="checkbox"/> Pothole | <input type="checkbox"/> Missing        |
| <input type="checkbox"/> Painting | <input type="checkbox"/> Grass              | <input type="checkbox"/> Needs Trimming |

Submitted by: James Borchers



Borough of North Arlington  
Quality of Life Report

Date: 11-25-2019

---

Location: Art Ave & Argyle Pl near curb  
blacktop broken near curb

Curb

Lamp

Park

Fence

Playground

School

Roadway

Sidewalk

Sign

Tree

Streetlamp

Other: \_\_\_\_\_

---

Needing Attention:

Damage

Pothole

Missing


Painting

Grass

Needs Trimming

---

Submitted by: James Bacchino



Borough of North Arlington  
Quality of Life Report

Date: 11-25-2019


Location: 6<sup>th</sup> St + Boston Ave big dip rd  
Work on Boston 2 ft of driveway

- |   |                                     |                                       |
|---|-------------------------------------|---------------------------------------|
| <input type="checkbox"/> Curb               | <input type="checkbox"/> Lamp       | <input type="checkbox"/> Park         |
| <input type="checkbox"/> Fence              | <input type="checkbox"/> Playground | <input type="checkbox"/> School       |
| <input checked="" type="checkbox"/> Roadway | <input type="checkbox"/> Sidewalk   | <input type="checkbox"/> Sign         |
| <input type="checkbox"/> Tree               | <input type="checkbox"/> Streetlamp | <input type="checkbox"/> Other: _____ |

Needing Attention:

- |                                   |                                  |   |
|-----------------------------------|----------------------------------|---|
| <input type="checkbox"/> Damage   | <input type="checkbox"/> Pothole | <input type="checkbox"/> Missing        |
| <input type="checkbox"/> Painting | <input type="checkbox"/> Grass   | <input type="checkbox"/> Needs Trimming |

Submitted by: James B. Baker



Borough of North Arlington  
Quality of Life Report

Date: 11-26-2019

Big Creek rd road


Location: Melrose Ave

- |   |                                     |                                       |
|---|-------------------------------------|---------------------------------------|
| <input type="checkbox"/> Curb               | <input type="checkbox"/> Lamp       | <input type="checkbox"/> Park         |
| <input type="checkbox"/> Fence              | <input type="checkbox"/> Playground | <input type="checkbox"/> School       |
| <input checked="" type="checkbox"/> Roadway | <input type="checkbox"/> Sidewalk   | <input type="checkbox"/> Sign         |
| <input type="checkbox"/> Tree               | <input type="checkbox"/> Streetlamp | <input type="checkbox"/> Other: _____ |

Needing Attention:

- |                                   |                                  |   |
|-----------------------------------|----------------------------------|---|
| <input type="checkbox"/> Damage   | <input type="checkbox"/> Pothole | <input type="checkbox"/> Missing        |
| <input type="checkbox"/> Painting | <input type="checkbox"/> Grass   | <input type="checkbox"/> Needs Trimming |

Submitted by: James Beckins



Borough of North Arlington  
Quality of Life Report

Date: 12-11-19

---

Location: 2104175 Rutterford Pl

- |   |                                     |                                       |
|---|-------------------------------------|---------------------------------------|
| <input type="checkbox"/> Curb               | <input type="checkbox"/> Lamp       | <input type="checkbox"/> Park         |
| <input type="checkbox"/> Fence              | <input type="checkbox"/> Playground | <input type="checkbox"/> School       |
| <input checked="" type="checkbox"/> Roadway | <input type="checkbox"/> Sidewalk   | <input type="checkbox"/> Sign         |
| <input type="checkbox"/> Tree               | <input type="checkbox"/> Streetlamp | <input type="checkbox"/> Other: _____ |


Repair Road

Needing Attention:

- |                                   |                                  |   |
|-----------------------------------|----------------------------------|---|
| <input type="checkbox"/> Damage   | <input type="checkbox"/> Pothole | <input type="checkbox"/> Missing        |
| <input type="checkbox"/> Painting | <input type="checkbox"/> Grass   | <input type="checkbox"/> Needs Trimming |

---

Submitted by: James Bocchino



Borough of North Arlington  
Quality of Life Report

Date: 12-17-19

Location: 6 St & Boston Ave


- |   |                                     |                                       |
|---|-------------------------------------|---------------------------------------|
| <input type="checkbox"/> Curb               | <input type="checkbox"/> Lamp       | <input type="checkbox"/> Park         |
| <input type="checkbox"/> Fence              | <input type="checkbox"/> Playground | <input type="checkbox"/> School       |
| <input checked="" type="checkbox"/> Roadway | <input type="checkbox"/> Sidewalk   | <input type="checkbox"/> Sign         |
| <input type="checkbox"/> Tree               | <input type="checkbox"/> Streetlamp | <input type="checkbox"/> Other: _____ |

dip in road 6' off of Both St.

Needing Attention:

- |                                   |                                  |   |
|-----------------------------------|----------------------------------|---|
| <input type="checkbox"/> Damage   | <input type="checkbox"/> Pothole | <input type="checkbox"/> Missing        |
| <input type="checkbox"/> Painting | <input type="checkbox"/> Grass   | <input type="checkbox"/> Needs Trimming |

Submitted by: James Bacchi



Borough of North Arlington  
Quality of Life Report

Date: 12-18-19

---

Location: Entrance road to Borough Hall  
Right side by library, wall that supports  
parking is breaking up

- |   |                                     |   |
|---|-------------------------------------|---|
| <input type="checkbox"/> Curb               | <input type="checkbox"/> Lamp       | <input type="checkbox"/> Park               |
| <input type="checkbox"/> Fence              | <input type="checkbox"/> Playground | <input type="checkbox"/> School             |
| <input checked="" type="checkbox"/> Roadway | <input type="checkbox"/> Sidewalk   | <input type="checkbox"/> Sign               |
| <input type="checkbox"/> Tree               | <input type="checkbox"/> Streetlamp | <input type="checkbox"/> Other: <u>Wall</u> |

---


Needing Attention:

- |  |                                  |   |
|--|----------------------------------|---|
| <input checked="" type="checkbox"/> Damage | <input type="checkbox"/> Pothole | <input type="checkbox"/> Missing        |
| <input type="checkbox"/> Painting          | <input type="checkbox"/> Grass   | <input type="checkbox"/> Needs Trimming |

---

Submitted by: James Bacchin





Borough of North Arlington  
Quality of Life Report

Date: 12-19-19

Location: 60 Melissa ave - 2 James Pl.


- |   |                                     |                                       |
|---|-------------------------------------|---------------------------------------|
| <input type="checkbox"/> Curb               | <input type="checkbox"/> Lamp       | <input type="checkbox"/> Park         |
| <input type="checkbox"/> Fence              | <input type="checkbox"/> Playground | <input type="checkbox"/> School       |
| <input checked="" type="checkbox"/> Roadway | <input type="checkbox"/> Sidewalk   | <input type="checkbox"/> Sign         |
| <input type="checkbox"/> Tree               | <input type="checkbox"/> Streetlamp | <input type="checkbox"/> Other: _____ |

Dep in road

Needing Attention:

- |                                   |                                  |   |
|-----------------------------------|----------------------------------|---|
| <input type="checkbox"/> Damage   | <input type="checkbox"/> Pothole | <input type="checkbox"/> Missing        |
| <input type="checkbox"/> Painting | <input type="checkbox"/> Grass   | <input type="checkbox"/> Needs Trimming |

Submitted by: James Bacalmo



Borough of North Arlington  
Quality of Life Report

Date: 12-31-19

Location: 169 Riverside Ave


- |   |                                     |                                       |
|---|-------------------------------------|---------------------------------------|
| <input type="checkbox"/> Curb               | <input type="checkbox"/> Lamp       | <input type="checkbox"/> Park         |
| <input type="checkbox"/> Fence              | <input type="checkbox"/> Playground | <input type="checkbox"/> School       |
| <input checked="" type="checkbox"/> Roadway | <input type="checkbox"/> Sidewalk   | <input type="checkbox"/> Sign         |
| <input type="checkbox"/> Tree               | <input type="checkbox"/> Streetlamp | <input type="checkbox"/> Other: _____ |

Depot road

Needing Attention:

- |                                   |                                  |   |
|-----------------------------------|----------------------------------|---|
| <input type="checkbox"/> Damage   | <input type="checkbox"/> Pothole | <input type="checkbox"/> Missing        |
| <input type="checkbox"/> Painting | <input type="checkbox"/> Grass   | <input type="checkbox"/> Needs Trimming |

Submitted by: James Bochini



Borough of North Arlington  
Quality of Life Report

Date: 1-21-20

Location: 67 Morgan Pl.


- |                                  |                                     |                                       |
|----------------------------------|-------------------------------------|---------------------------------------|
| <input type="checkbox"/> Curb    | <input type="checkbox"/> Lamp       | <input type="checkbox"/> Park         |
| <input type="checkbox"/> Fence   | <input type="checkbox"/> Playground | <input type="checkbox"/> School       |
| <input type="checkbox"/> Roadway | <input type="checkbox"/> Sidewalk   | <input type="checkbox"/> Sign         |
| <input type="checkbox"/> Tree    | <input type="checkbox"/> Streetlamp | <input type="checkbox"/> Other: _____ |

Needing Attention:

- |                                   |   |   |
|-----------------------------------|---|---|
| <input type="checkbox"/> Damage   | <input checked="" type="checkbox"/> Pothole | <input type="checkbox"/> Missing        |
| <input type="checkbox"/> Painting | <input type="checkbox"/> Grass              | <input type="checkbox"/> Needs Trimming |

Pothole

Submitted by: James Beckins



Borough of North Arlington  
Quality of Life Report

Date: 1-22-20

Location: Eagle & Hoed St

Curb

Lamp

Park

Fence

Playground

School

Roadway

Sidewalk

Sign

Tree

Streetlamp

Other: \_\_\_\_\_

Cannot Read sign (do not enter)

Needing Attention:

Damage

Pothole


Missing

Painting

Grass

Needs Trimming

Submitted by: James Bachini



Borough of North Arlington  
Quality of Life Report

Date: 1-23-20

Location: 95 Jaucy Ave.


- |                                  |                                     |  |
|----------------------------------|-------------------------------------|--|
| <input type="checkbox"/> Curb    | <input type="checkbox"/> Lamp       | <input type="checkbox"/> Park            |
| <input type="checkbox"/> Fence   | <input type="checkbox"/> Playground | <input type="checkbox"/> School          |
| <input type="checkbox"/> Roadway | <input type="checkbox"/> Sidewalk   | <input checked="" type="checkbox"/> Sign |
| <input type="checkbox"/> Tree    | <input type="checkbox"/> Streetlamp | <input type="checkbox"/> Other: _____    |

Replace sign 10AM-12PM - Wed.

Needing Attention:

- |                                   |                                  |   |
|-----------------------------------|----------------------------------|---|
| <input type="checkbox"/> Damage   | <input type="checkbox"/> Pothole | <input type="checkbox"/> Missing        |
| <input type="checkbox"/> Painting | <input type="checkbox"/> Grass   | <input type="checkbox"/> Needs Trimming |

Submitted by: James Bachini



Borough of North Arlington  
Quality of Life Report

Date: 1-27-2020

Location: 101 Melrose Ave


- |   |                                     |                                       |
|---|-------------------------------------|---------------------------------------|
| <input type="checkbox"/> Curb               | <input type="checkbox"/> Lamp       | <input type="checkbox"/> Park         |
| <input type="checkbox"/> Fence              | <input type="checkbox"/> Playground | <input type="checkbox"/> School       |
| <input checked="" type="checkbox"/> Roadway | <input type="checkbox"/> Sidewalk   | <input type="checkbox"/> Sign         |
| <input type="checkbox"/> Tree               | <input type="checkbox"/> Streetlamp | <input type="checkbox"/> Other: _____ |

Dip in Road

Needing Attention:

- |                                   |                                  |   |
|-----------------------------------|----------------------------------|---|
| <input type="checkbox"/> Damage   | <input type="checkbox"/> Pothole | <input type="checkbox"/> Missing        |
| <input type="checkbox"/> Painting | <input type="checkbox"/> Grass   | <input type="checkbox"/> Needs Trimming |

Submitted by: James Bochenski



Borough of North Arlington  
Quality of Life Report

Date: 2-3-2020

---

Location: 153 Butlersford Pl.

- |   |                                     |                                       |
|---|-------------------------------------|---------------------------------------|
| <input type="checkbox"/> Curb               | <input type="checkbox"/> Lamp       | <input type="checkbox"/> Park         |
| <input type="checkbox"/> Fence              | <input type="checkbox"/> Playground | <input type="checkbox"/> School       |
| <input checked="" type="checkbox"/> Roadway | <input type="checkbox"/> Sidewalk   | <input type="checkbox"/> Sign         |
| <input type="checkbox"/> Tree               | <input type="checkbox"/> Streetlamp | <input type="checkbox"/> Other: _____ |


Small holes in road

Needing Attention:

- |                                   |                                  |   |
|-----------------------------------|----------------------------------|---|
| <input type="checkbox"/> Damage   | <input type="checkbox"/> Pothole | <input type="checkbox"/> Missing        |
| <input type="checkbox"/> Painting | <input type="checkbox"/> Grass   | <input type="checkbox"/> Needs Trimming |

---

Submitted by: James Becker



Borough of North Arlington

Quality of Life Report

Date: 3-12-2020

Location: West St & Baylis

- |                                  |                                     |  |
|----------------------------------|-------------------------------------|--|
| <input type="checkbox"/> Curb    | <input type="checkbox"/> Lamp       | <input type="checkbox"/> Park            |
| <input type="checkbox"/> Fence   | <input type="checkbox"/> Playground | <input type="checkbox"/> School          |
| <input type="checkbox"/> Roadway | <input type="checkbox"/> Sidewalk   | <input checked="" type="checkbox"/> Sign |
| <input type="checkbox"/> Tree    | <input type="checkbox"/> Streetlamp | <input type="checkbox"/> Other: _____    |


Signs on Poles

Needing Attention:

- |                                   |                                  |   |
|-----------------------------------|----------------------------------|---|
| <input type="checkbox"/> Damage   | <input type="checkbox"/> Pothole | <input type="checkbox"/> Missing        |
| <input type="checkbox"/> Painting | <input type="checkbox"/> Grass   | <input type="checkbox"/> Needs Trimming |

Submitted by: James Boeckeno





Borough of North Arlington

Quality of Life Report

Date: 3-16-2020


Location: 37 Fairmont Ave 8-10 AM - Tues  
Replace sign

- |                                  |                                     |  |
|----------------------------------|-------------------------------------|--|
| <input type="checkbox"/> Curb    | <input type="checkbox"/> Lamp       | <input type="checkbox"/> Park            |
| <input type="checkbox"/> Fence   | <input type="checkbox"/> Playground | <input type="checkbox"/> School          |
| <input type="checkbox"/> Roadway | <input type="checkbox"/> Sidewalk   | <input checked="" type="checkbox"/> Sign |
| <input type="checkbox"/> Tree    | <input type="checkbox"/> Streetlamp | <input type="checkbox"/> Other: _____    |

Needing Attention:

- |                                   |                                  |   |
|-----------------------------------|----------------------------------|---|
| <input type="checkbox"/> Damage   | <input type="checkbox"/> Pothole | <input type="checkbox"/> Missing        |
| <input type="checkbox"/> Painting | <input type="checkbox"/> Grass   | <input type="checkbox"/> Needs Trimming |

Submitted by: James Boecklin



Borough of North Arlington

Quality of Life Report

Date: 3-16-2020

---

---

Location: Bulmer & Prospect - No Parking Wed 1 to 3  
Replace Sign

- |                                  |                                     |  |
|----------------------------------|-------------------------------------|--|
| <input type="checkbox"/> Curb    | <input type="checkbox"/> Lamp       | <input type="checkbox"/> Park            |
| <input type="checkbox"/> Fence   | <input type="checkbox"/> Playground | <input type="checkbox"/> School          |
| <input type="checkbox"/> Roadway | <input type="checkbox"/> Sidewalk   | <input checked="" type="checkbox"/> Sign |
| <input type="checkbox"/> Tree    | <input type="checkbox"/> Streetlamp | <input type="checkbox"/> Other: _____    |

---

---


Needing Attention:

- |                                   |                                  |   |
|-----------------------------------|----------------------------------|---|
| <input type="checkbox"/> Damage   | <input type="checkbox"/> Pothole | <input type="checkbox"/> Missing        |
| <input type="checkbox"/> Painting | <input type="checkbox"/> Grass   | <input type="checkbox"/> Needs Trimming |

---

---

Submitted by: James Baschiro



Borough of North Arlington  
Quality of Life Report

Date: 3-17-2020


Location: Med Ave & Selwyn Drive

- |                                  |                                     |  |
|----------------------------------|-------------------------------------|--|
| <input type="checkbox"/> Curb    | <input type="checkbox"/> Lamp       | <input type="checkbox"/> Park            |
| <input type="checkbox"/> Fence   | <input type="checkbox"/> Playground | <input type="checkbox"/> School          |
| <input type="checkbox"/> Roadway | <input type="checkbox"/> Sidewalk   | <input checked="" type="checkbox"/> Sign |
| <input type="checkbox"/> Tree    | <input type="checkbox"/> Streetlamp | <input type="checkbox"/> Other: _____    |

Needing Attention:

- |                                   |                                  |   |
|-----------------------------------|----------------------------------|---|
| <input type="checkbox"/> Damage   | <input type="checkbox"/> Pothole | <input type="checkbox"/> Missing        |
| <input type="checkbox"/> Painting | <input type="checkbox"/> Grass   | <input type="checkbox"/> Needs Trimming |

Submitted by: James Bocchino



Borough of North Arlington  
Quality of Life Report

Date: 3-18-2020


Location: Hugh St & Eagle

- |                                  |                                     |  |
|----------------------------------|-------------------------------------|--|
| <input type="checkbox"/> Curb    | <input type="checkbox"/> Lamp       | <input type="checkbox"/> Park            |
| <input type="checkbox"/> Fence   | <input type="checkbox"/> Playground | <input type="checkbox"/> School          |
| <input type="checkbox"/> Roadway | <input type="checkbox"/> Sidewalk   | <input checked="" type="checkbox"/> Sign |
| <input type="checkbox"/> Tree    | <input type="checkbox"/> Streetlamp | <input type="checkbox"/> Other: _____    |

Needing Attention: Stop sign to be replaced

- |                                   |                                  |   |
|-----------------------------------|----------------------------------|---|
| <input type="checkbox"/> Damage   | <input type="checkbox"/> Pothole | <input type="checkbox"/> Missing        |
| <input type="checkbox"/> Painting | <input type="checkbox"/> Grass   | <input type="checkbox"/> Needs Trimming |

Submitted by: James Basolino



Borough of North Arlington  
Quality of Life Report

Date: 3-18-2020

Location: 5<sup>th</sup> St + Jaurcey

Curb

Lamp

Park

Fence

Playground

School

Roadway

Sidewalk

Sign

Tree

Streetlamp

Other: \_\_\_\_\_

Big Pot Hole on 5<sup>th</sup> off of Jaurcey

Needing Attention:

Damage

Pothole


Missing

Painting

Grass

Needs Trimming

Submitted by: James Basolino



Borough of North Arlington  
Quality of Life Report

Date: 3-19-2020

Location: 39 Carterbury Ave  
85 Carterbury Ave


- |                                  |                                     |  |
|----------------------------------|-------------------------------------|--|
| <input type="checkbox"/> Curb    | <input type="checkbox"/> Lamp       | <input type="checkbox"/> Park            |
| <input type="checkbox"/> Fence   | <input type="checkbox"/> Playground | <input type="checkbox"/> School          |
| <input type="checkbox"/> Roadway | <input type="checkbox"/> Sidewalk   | <input checked="" type="checkbox"/> Sign |
| <input type="checkbox"/> Tree    | <input type="checkbox"/> Streetlamp | <input type="checkbox"/> Other: _____    |

No Parking 1-3 Thurs Can't read

Needing Attention:

- |                                   |                                  |   |
|-----------------------------------|----------------------------------|---|
| <input type="checkbox"/> Damage   | <input type="checkbox"/> Pothole | <input type="checkbox"/> Missing        |
| <input type="checkbox"/> Painting | <input type="checkbox"/> Grass   | <input type="checkbox"/> Needs Trimming |

Submitted by: James Bocchino



Borough of North Arlington

Quality of Life Report

Date: 3-19-2020

Attn: Mike

Location: Parking Meter Ridge Rd 0046


- |                                  |                                     |                                       |
|----------------------------------|-------------------------------------|---------------------------------------|
| <input type="checkbox"/> Curb    | <input type="checkbox"/> Lamp       | <input type="checkbox"/> Park         |
| <input type="checkbox"/> Fence   | <input type="checkbox"/> Playground | <input type="checkbox"/> School       |
| <input type="checkbox"/> Roadway | <input type="checkbox"/> Sidewalk   | <input type="checkbox"/> Sign         |
| <input type="checkbox"/> Tree    | <input type="checkbox"/> Streetlamp | <input type="checkbox"/> Other: _____ |

Does not park

Needing Attention:

- |                                   |                                  |   |
|-----------------------------------|----------------------------------|---|
| <input type="checkbox"/> Damage   | <input type="checkbox"/> Pothole | <input type="checkbox"/> Missing        |
| <input type="checkbox"/> Painting | <input type="checkbox"/> Grass   | <input type="checkbox"/> Needs Trimming |

Submitted by: James Bocchino



Borough of North Arlington

Quality of Life Report

Date: 4-6-2020

Location: Captan Ave & Forest Ave

Curb

Lamp

Park

Fence

Playground

School

Roadway

Sidewalk

Sign

Tree

Streetlamp

Other: \_\_\_\_\_

Replace sign Trucks over 4 Tons excluded

Needing Attention:

Damage

Pothole

Missing


Painting

Grass

Needs Trimming

Submitted by: James B. Boehm





Borough of North Arlington

Quality of Life Report

Date: 4-6-2020

Location: 46 Allen Dr by Fire Department


- Curb
- Fence
- Roadway
- Tree
- Lamp
- Playground
- Sidewalk
- Streetlamp
- Park
- School
- Sign
- Other: \_\_\_\_\_

Water cap is off

Needing Attention:

- Damage
- Painting
- Pothole
- Grass
- Missing
- Needs Trimming

Submitted by: James Boschino



Borough of North Arlington  
Quality of Life Report

Date: 4-7-2020

Location:

Hedden Terr. & Willis St

Curb

Lamp

Park

Fence

Playground

School

Roadway

Sidewalk

Sign

Tree

Streetlamp

Other: \_\_\_\_\_

Signs in Pole on Willis St

Needing Attention:

Damage

Pothole

Missing


Painting

Grass

Needs Trimming

Submitted by:

James Boecklin



Borough of North Arlington  
Quality of Life Report

Date: 4-8-2020

Location: 40 Allan Dr.


- |   |                                     |                                       |
|---|-------------------------------------|---------------------------------------|
| <input type="checkbox"/> Curb               | <input type="checkbox"/> Lamp       | <input type="checkbox"/> Park         |
| <input type="checkbox"/> Fence              | <input type="checkbox"/> Playground | <input type="checkbox"/> School       |
| <input checked="" type="checkbox"/> Roadway | <input type="checkbox"/> Sidewalk   | <input type="checkbox"/> Sign         |
| <input type="checkbox"/> Tree               | <input type="checkbox"/> Streetlamp | <input type="checkbox"/> Other: _____ |

Pothole off Reservoir

Needing Attention:

- |                                   |                                  |   |
|-----------------------------------|----------------------------------|---|
| <input type="checkbox"/> Damage   | <input type="checkbox"/> Pothole | <input type="checkbox"/> Missing        |
| <input type="checkbox"/> Painting | <input type="checkbox"/> Grass   | <input type="checkbox"/> Needs Trimming |

Submitted by: James Boecklin



Borough of North Arlington

Quality of Life Report

Date: 4-9-2010

Location: 20 Biltmore Ave.


- |   |                                     |                                       |
|---|-------------------------------------|---------------------------------------|
| <input type="checkbox"/> Curb               | <input type="checkbox"/> Lamp       | <input type="checkbox"/> Park         |
| <input type="checkbox"/> Fence              | <input type="checkbox"/> Playground | <input type="checkbox"/> School       |
| <input checked="" type="checkbox"/> Roadway | <input type="checkbox"/> Sidewalk   | <input type="checkbox"/> Sign         |
| <input type="checkbox"/> Tree               | <input type="checkbox"/> Streetlamp | <input type="checkbox"/> Other: _____ |

Pot Hole

Needing Attention:

- |                                   |                                  |   |
|-----------------------------------|----------------------------------|---|
| <input type="checkbox"/> Damage   | <input type="checkbox"/> Pothole | <input type="checkbox"/> Missing        |
| <input type="checkbox"/> Painting | <input type="checkbox"/> Grass   | <input type="checkbox"/> Needs Trimming |

Submitted by: James Boeckeno



Borough of North Arlington  
Quality of Life Report

Date: 4-9-2010

Location: 55 Allen Dr


- |   |                                     |                                       |
|---|-------------------------------------|---------------------------------------|
| <input type="checkbox"/> Curb               | <input type="checkbox"/> Lamp       | <input type="checkbox"/> Park         |
| <input type="checkbox"/> Fence              | <input type="checkbox"/> Playground | <input type="checkbox"/> School       |
| <input checked="" type="checkbox"/> Roadway | <input type="checkbox"/> Sidewalk   | <input type="checkbox"/> Sign         |
| <input type="checkbox"/> Tree               | <input type="checkbox"/> Streetlamp | <input type="checkbox"/> Other: _____ |

Pothole

Needing Attention:

- |                                   |                                  |   |
|-----------------------------------|----------------------------------|---|
| <input type="checkbox"/> Damage   | <input type="checkbox"/> Pothole | <input type="checkbox"/> Missing        |
| <input type="checkbox"/> Painting | <input type="checkbox"/> Grass   | <input type="checkbox"/> Needs Trimming |

Submitted by: James Baschimo



Borough of North Arlington

Quality of Life Report

Date: 4-13-2020

Location: 22 Albert St


- |                                  |                                     |  |
|----------------------------------|-------------------------------------|--|
| <input type="checkbox"/> Curb    | <input type="checkbox"/> Lamp       | <input type="checkbox"/> Park            |
| <input type="checkbox"/> Fence   | <input type="checkbox"/> Playground | <input type="checkbox"/> School          |
| <input type="checkbox"/> Roadway | <input type="checkbox"/> Sidewalk   | <input checked="" type="checkbox"/> Sign |
| <input type="checkbox"/> Tree    | <input type="checkbox"/> Streetlamp | <input type="checkbox"/> Other: _____    |

Signs on Pole

Needing Attention:

- |                                   |                                  |   |
|-----------------------------------|----------------------------------|---|
| <input type="checkbox"/> Damage   | <input type="checkbox"/> Pothole | <input type="checkbox"/> Missing        |
| <input type="checkbox"/> Painting | <input type="checkbox"/> Grass   | <input type="checkbox"/> Needs Trimming |

Submitted by: James Boecklin



Borough of North Arlington  
Quality of Life Report

Date: 4-14-2020

Location: \_\_\_\_\_

126 Bergen ave

Curb

Lamp

Park

Fence

Playground

School

Roadway

Sidewalk

Sign

Tree

Streetlamp

Other: \_\_\_\_\_

Sign on pole

Needing Attention:

Damage

Pothole

Missing


Painting

Grass

Needs Trimming

Submitted by: \_\_\_\_\_

James Boecklin



Borough of North Arlington

Quality of Life Report

Date: 4-14-2020

Location: 169 & 175 Riverside Ave

- |   |                                     |                                       |
|---|-------------------------------------|---------------------------------------|
| <input type="checkbox"/> Curb               | <input type="checkbox"/> Lamp       | <input type="checkbox"/> Park         |
| <input type="checkbox"/> Fence              | <input type="checkbox"/> Playground | <input type="checkbox"/> School       |
| <input checked="" type="checkbox"/> Roadway | <input type="checkbox"/> Sidewalk   | <input type="checkbox"/> Sign         |
| <input type="checkbox"/> Tree               | <input type="checkbox"/> Streetlamp | <input type="checkbox"/> Other: _____ |


Dep in Road

Needing Attention:

- |                                   |                                  |   |
|-----------------------------------|----------------------------------|---|
| <input type="checkbox"/> Damage   | <input type="checkbox"/> Pothole | <input type="checkbox"/> Missing        |
| <input type="checkbox"/> Painting | <input type="checkbox"/> Grass   | <input type="checkbox"/> Needs Trimming |

Submitted by: James Basolino





Borough of North Arlington

Quality of Life Report

Date: 4-15-2020

Location: High St & Putnam

Curb

Lamp

Park

Fence

Playground

School

Roadway

Sidewalk

Sign

Tree

Streetlamp

Other: \_\_\_\_\_

Hole in Road

Needing Attention:

Damage

Pothole


Missing

Painting

Grass

Needs Trimming

Submitted by: James Baschiro



Borough of North Arlington

Quality of Life Report

Date: 4-29-2020

Location: 176 Arlington Blvd & Shields Pl.

Curb

Lamp

Park

Fence

Playground

School

Roadway

Sidewalk

Sign

Tree

Streetlamp

Other: Catch Basin

Catch Basin 3/4 full (Clear out)

Needing Attention:

Damage

Pothole


Missing

Painting

Grass

Needs Trimming

Submitted by: James Boecklin



Borough of North Arlington

Quality of Life Report

Date: Week of June 1st

Location: Hendel Ave 474 48 going W  
74 & 75 " E


- Curb
- Fence
- Roadway
- Tree
- Lamp
- Playground
- Sidewalk
- Streetlamp
- Park
- School
- Sign
- Other: Speed Bumps

Can't read speed bump at night

Needing Attention:

- Damage
- Painting
- Pothole
- Grass
- Missing
- Needs Trimming

Submitted by: James Boecklin



Borough of North Arlington

Quality of Life Report

Date: Week of June 7<sup>th</sup> 2020

Location: 203 Prospect Ave

Curb

Lamp

Park

Fence

Playground

School

Roadway

Sidewalk

Sign

Tree

Streetlamp

Other: \_\_\_\_\_

Sign on Pole

Needing Attention:

Damage

Pothole

Missing

Painting

Grass

Needs Trimming

Submitted by: James Boecklin



Borough of North Arlington

Quality of Life Report

Date: Week of June 15<sup>th</sup>

Paint Poles

Location: List Attached

Curb

Lamp

Park

Fence

Playground

School

Roadway

Sidewalk

Sign

Tree

Streetlamp

Other: \_\_\_\_\_

Needing Attention:

Damage

Pothole

Missing

Painting

Grass

Needs Trimming

Submitted by: James Baschero

# Paint Poles

Wesson Pl & Sixth

Jaucy ave & Riverview

Jaucy ave & 7<sup>th</sup> St

Lincoln ave & 9<sup>th</sup>

Sixth St & Burwood Dr

Allen Dr & Burwood Dr

Riverview & Allen Dr

River Road & Ferguson Ave

Lincoln ave & Riverview

Seventh St & Boyle

River Road & Boyle

Baltimore & Riverview

Sixth St & Ridge Park Dr

Lincoln ave & Sixth (also Pole setting)

# Paint Poles

9<sup>th</sup> St & Juncney

E 10<sup>th</sup> St & Seale

6<sup>th</sup> St & Bergen

Bergen & 8<sup>th</sup>

Baltimore & Riverside

Francis & 8<sup>th</sup>

Juncney & 9<sup>th</sup>

E 10<sup>th</sup> St & Juncney Ave & 9<sup>th</sup>

Union Ave & 4<sup>th</sup> St

River Rd & Boston

Union Ave & 3<sup>rd</sup>